Remington Arms Co., Inc. Product Service Legal Case #:2990

Case Information

RE# **Date Opened** Date Opened(PS) **Date Closed Incident Date** Pre Lit Obsolete 12/17/2008 12/17/2008 12/16/2008 157234

Customer Information

Business First Name Last Name Street City State Zip Contact Type Age H 608-577-7655 John G. Lazaris 2249 Fox Ave Madison WI Incident E lazaris@charter.net

Incident Information

Claims Codes Repair Est. **Medical Treatment Medical Status**

PI

PD Could Not Duplicate Concern

Unknown Concern: 1007 Fired on Safe Release

Customer says he put the safety in the fire position and it went off.

Firearm Information

S fired on safe release

Model/Ga. SKU Serial Bbl. DOM Mfg. Type 700/270 WIN CF/BA 20000 A6854940 OA 7/21/1980 Remington

Where Purchased Original Owner **Date Purchased** Accessories

OUTDOOR SPT HQ WILLOWBROOK IL TWO PIECE SCOPE BASE U

CONCERN:FSR

Ammunition Information - None Defined Other Products Information - None Defined Settlement

Remington/700/CF/BA Release of Claims

Reimbursement Cash Settlement Reim. Date APV Cash Date APV Settlement Release Date

BLM Program

Repair/Replacement Cost Repair/Replacement Date

45.00 12/18/2008

12/17/2008 returned to AS to install a new TA and clean action. Quoting \$20 under the bolt lock modification program fls.

Examination[Remington/CF/BA]

Part	Sub-Part	Code	Comment
	Examiner		B.TRAVIS
	Exam Date		12/17/2008
Examination	Product Type		RF
	Action Type		A
	Assigned To		F.SUPRY
Cause	4038	Could Not Duplicate Concern	
Barrel	Description		22" 270 WIN
	Date Code		OA
	Bore Plugged	False	
	Bulged	False	
	Fired	False	
	Fired while Obstructed		
	Muzzle/Crown Condition	Slightly Worn; Functioning	
	Firing Pin	Slightly Worn; Functioning	
Bolt	Shroud	Slightly Worn; Functioning	
	Face	Slightly Worn; Functioning	· .

ı .	(<u></u>		-
	Handle	Slightly Wom; Functioning	
	Stop	Slightly Worn; Functioning	
Extractor	Condition	Slightly Worn; Functioning	
	Cut Condition	Slightly Worn; Functioning	
Locking	Ext/Eject Test	False]
	Block Condition	Select	
	Lug Condition	Slightly Worn; Functioning	
Overall	Notch Condition	Select]
	Exterior Condition	Slightly Worn; Functioning]
	Stock Condition	Slightly Worn; Functioning	
	Fore End Condition	Select	
D	Condition	Slightly Worn; Functioning]
Receiver	Bulged	False	
0-64	Description		STANDARD M/700 BOLT LOCK SAFETY
Safety	Function	Like new; Functioning]
	Lift	Select	.008
ear	Notch	Like new; Functioning	
	Tests	Test Fired	False
Feeding Test	li ests	False	
	Condition	Like new; Functioning	
Trigger	Pull	Select	4#
	Altered	False	
	Sub-Assembly	M/700 Bolt Lock	
Non-Remington Components	Description		TWO PIECE SCOPE BASE

Repair Inquiry			System Maintenance S Help S	<u> </u>	
	erial: A5854940: Model 700: Center Fire (70:WIN: LH: Produced: 0772171980	Parallel State Control	Bruce Travis Hald 12/17/2008 6:32:36 AM		
ddress Information Customer: Name: JOHN G. LAZARIS	the first the second se	un To:	C Received From		
ddjess 1 2249 FOX AVENUE	PO Box J	9 FOX AVENUE DISON Zip Codes [53711	PO Box		
Contact/ Condition Problem	FFL: \(\sum_{\text{ens}} \)	History / Status	Shipping // Billing		
Date Code User ID 12/16/2008-807. New sanguine 12/18/2008-811. Expedite sanguine 12/16/2008-12/0 EmailVertied AmmEmai 12/16/2008-12/0 EmailVertied Trevistoe 12/17/2008-630 Expedite Trevistoe 12/17/2008-637 Expedite Trevistoe 12/17/2008-737 Expedite penceri	ggi Repair Added ggi From: Check In To: I Repair Received LAZARIS I Receipt LAZARIS From: Product Services To: Repa	interface Hold CHARTE Estimate Sent CHARTE Paits Received in Bench Passed Inspection pprovalled Return & Research	ed <u>Eurient Location</u>		
Repair <u>S</u> earch		<u>Be</u>	fresh Close	The state of the s	

Returned to AS For boil lock modifications
program
FLS 12/17/08

2990



General Repair Form

Back to Repair Services

NOTE: Please complete and print this form, and then include it with your firearm

2211 4# .008

Model Number: 700BDL LH	Serial Number: A6854940		
Name: John G. Lazaris	Date of Purchase: 1980		
Address (no PO Boxes): 2249 Fox Avenue			
ity: Madison	State: Wi Zip: 53711		
hone (Daytime): (608)577-7655	Fax:		
-mail Address: lazaris@charter.net			
lease describe your problem:	,		
280 characters left			
SERIAL NUMBER OF YOUR FIREARM.	hipping and handling. Preferably, ship in a		
	shipping and handling. Preferably, ship in a smage. mington is not responsible for damage or loss a your carrier.		

could not duplicate concern.

Replace TPA check over, clean

under bolt Lock program

Ron \$ 20.00 + S+H

Quode

http://www.remington.com/support/repair services/general repair form.asp

12/4/2008