

Remington Arms Co., Inc.
Product Service
Legal Case #:2488

Case Information

RE#	Date Opened	Date Opened(PS)	Date Closed	Incident Date	Pre Lit	Lit	Obsolete
146627	6/19/2008	6/20/2008	6/20/2008				

Customer Information

Type	Business	First Name	Last Name	Street	City	State	Zip	Age	Contact
Reporter		William	Perkins Jr.	156 Oak Green Dr.	Ridgeland	MS	39157		H 601-292-3218 E perk007@bellsouth.net

Incident Information

Claims	Codes	Repair Est.	Medical Treatment	Medical Status
PI PD S rifle firing while unloading C	Cause:4006 Altered Adjustments or Components Concern:1020 Fired on Bolt Opening		Unknown	

6/25/08-correspondence from repair-rifle is firing while unloading, when working the bolt action and without finger on trigger. Bolt lock mechanism needs to be removed.lw

Firearm Information

Mfg.	Type	Model/Ga.	SKU	Serial	Bbl.	DOM
Remington	CF/BA	700/8MM REM MA	20000	A6473726	PO	6/22/1977
Date Purchased	Where Purchased	Accessories	Original Owner			
	SPORTS SOUTH SHREVEPORT LA	TWO PIECE SCOPE BASE,BOTTOM HALF RINGS	U			

CONCERN:FBC

Ammunition Information - None Defined

Other Products Information - None Defined

Settlement

Remington/700/CF/BA							
Settlement	Release of Claims	Release Date	Reimbursement	Cash Settlement	Reim. Date APV	Cash Date APV	
Replace TA under SMP							
Repair/Replacement Cost		Repair/Replacement Date					

6/25/08-quote sent to replace ta under smp for \$20.lw

Examination[Remington/CF/BA]

Part	Sub-Part	Code	Comment
Examination	Examiner		B.TRAVIS
	Exam Date		6/20/2008
	Product Type		RF

	Action Type		A
	Assigned To		F.SUPRY
Cause	4006	Altered Adjustments or Components	
Barrel	Description		24" 8MM REM MAG
	Date Code		PO
	Bore Plugged	False	
	Bulged	False	
	Fired	False	
	Fired while Obstructed		
	Muzzle/Crown Condition	Slightly Worn; Functioning	
Bolt	Firing Pin	Slightly Worn; Functioning	
	Shroud	Slightly Worn; Functioning	
	Face	Slightly Worn; Functioning	
	Handle	Slightly Worn; Functioning	
	Stop	Slightly Worn; Functioning	
Extractor	Condition	Slightly Worn; Functioning	
	Cut Condition	Slightly Worn; Functioning	
	Ext/Eject Test	False	
Locking	Block Condition	---Select---	
	Lug Condition	Slightly Worn; Functioning	
	Notch Condition	---Select---	
Overall	Exterior Condition	Slightly Worn; Functioning	
	Stock Condition	Slightly Worn; Functioning	
	Fore End Condition	---Select---	
Receiver	Condition	Slightly Worn; Functioning	
	Bulged	False	
Safety	Description		STANDARD M/700 BOLT LOCK SAFETY
	Function	Like new; Functioning	
Sear	Lift	---Select---	.012
	Notch	Slightly Worn; Functioning	
	Tests	Test Fired	False
Feeding Test		False	
Trigger	Condition	Slightly Worn; Functioning	
	Pull	---Select---	3#
	Altered	True	SET SCREWS ALTERED
	Sub-Assembly	M/700 Bolt Lock	
Non-Remington Components	Description		TWO PIECE SCOPE BASE,BOTTOM HALF OF RINGS

DE00146237

- Address Information -

Name:	WILLIAM PERKINS JR	WILLIAM PERKINS JR
-------	--------------------	--------------------

[illegible]

Contact / Condition	Problems	Estimate	History / Status	Shipping / Billing
---------------------	----------	----------	------------------	--------------------

Date	User ID	Desc1	Desc2	<input type="checkbox"/> Shipping Hold	<input type="checkbox"/> New

6/19/2008 3:16:1	valentis	Repair information charge
6/20/2008 7:49:2	sunroof	Returned to AS for repair Bolt Lock Modification Program

☐ Estimate Sent

<p> <input type="checkbox"/> Passed Inspection <input type="checkbox"/> Repair Location <input type="checkbox"/> UN </p>	<p> <input type="checkbox"/> Repair Location <input type="checkbox"/> UN </p>
---	--

Has been Annulled

Downloaded from ascelibrary.org by New York University on 06/01/15. Copyright ASCE, For All Rights Reserved, No part of this document may be reproduced, stored in a retrieval system, or transmitted, in any form or by any means, electronic, mechanical, photocopying, recording, or by any information storage or retrieval system, without permission in writing from ASCE.

Repair Search Refresh Close

100-443887-100

[The following page contains extremely faint, illegible text.]

[illegible]

6/20/2008	7:49 AM	CAES	NUM	115	SCB
-----------	---------	------	-----	-----	-----

[1/2 Sale!](#)
[Curtains & Blinds South](#)
[4 Airis Services Repair](#)
[1/2 Price! 1/2 Price! 1/2 Price!](#)

2488



PO 6/77
3#
24"
012

General Repair Form

Back to Repair Services

NOTE: Please complete and print this form, and then include it with your firearm

Model Number: 700 BDL		Serial Number: A6473726	
Name: William H. Perkins Jr.		Date of Purchase: Unknown	
Address (no PO Boxes): 156 Green Oak Drive			
City: Ridgeland		State: MS	Zip: 39157
Phone (Daytime): (601) 292-3218		Fax:	
E-mail Address: perk007@bellsouth.net			
Please describe your problem: Rifle is firing while unloading, when working the bolt action and without finger on trigger. Bolt lock mechanism needs to be removed per manufacturer's instructions.			
335 characters left			
NOTE: Prior to shipping your firearm, contact the Repair Center for services provided and estimated repair time.			
Ⓢ WARNING: DO NOT SEND LIVE OR SPENT SHELLS IN YOUR FIREARM OR IN THE SAME BOX WITH THE FIREARM. THIS IS A VIOLATION OF FEDERAL LAW. IF YOU FEEL YOU MUST SEND SPENT SHELLS PLEASE SEND THEM IN A SEPARATE PACKAGE AND INCLUDE NAME, ADDRESS (WITH ZIP CODE), TELEPHONE AND MODEL AND SERIAL NUMBER OF YOUR FIREARM. :: Record the serial number of your firearm before sending it. :: Pack your firearm for safety and to prevent further damage in shipping and handling. Preferably, ship in a firearm box. (Note: Original boxes may not be returned.) :: Remove all accessories from your firearm to prevent loss or damage. :: Ship your ENSURED firearm by either UPS or Parcel Post. Remington is not responsible for damage or loss during shipment, so you may elect to purchase insurance from your carrier.			

©2008 Remington Arms Company, Inc. All Rights Reserved.
Investor Relations | Other Remington Brand Products | Legal Notices | About Us

Visit Our Other Remington Websites

Other Sites

Number: **A6473726**

Model: **700**



RE00146627

Trigger set screws adjusted.
could not duplicate concern.
replace TPA, check down, clean
under bolt lock program
Ron \$20.00 + S&H.

Quote