Remington Arms Co., Inc. **Product Service** Legal Case #:3052

Case Information

RE# **Date Opened** Date Opened(PS) 1/12/2009

Perron

Date Closed 1/12/2009

Incident Date

Pre Lit Lit Obsolete

1/10/2009 158497

Customer Information Business First Name Last Name

Street

State Zip City Age

Contact

Incident

Patrick

140 Guinea Rd

Biddeford ME 04005

W 207-571-4801 F 207-284-8290

E pperron@maine.rr.com

Incident Information

Claims

Codes

Repair Est.

Medical Treatment Medical Status

PΙ

PD

Cause:4038

Could Not Duplicate

Concern

fired after releasing S safety

Concern: 1007 Fired on Safe Release

Unknown

1/13/09 According to letter with rifle, the gun fired when he removed the safety. Only used it in 2001 on one hunting trip prior to this.cm

Firearm Information

Mfg.

Type CF/BA

Model/Ga. 700/300 RUM

SKU 25973 Serial Bbl.

DOM

S6389431 BV 1/23/2001 1:22:38 PM

Remington **Date Purchased**

Where Purchased

Accessories Original Owner

JERRY S SPORT CENTER NORT

U

CONCERN:FSR

Ammunition Information - None Defined Other Products Information - None Defined Settlement

Remington/700/CF/BA

Cash

Reim. Cash

Settlement

Release of Claims

Release Date

Reimbursement

Settlement

Date Date APV APV

replace TPA at no charge as goodwill gesture

Repair/Replacement Repair/Replacement

Cost

Date

65.96


1/13/2009

1/13/09 could not duplicate concern. Trig piece is bent. Replace TPA at n/c as good will gesture.

Examination[Remington/CF/BA]

Sub-Part	Code	Comment
Examiner		B.TRAVIS
Exam Date		1/12/2009
Product Type		RF
	Examiner Exam Date	Examiner Exam Date

	Action Type		Α
·	Assigned To		F.SUPRY
Cause	4038	Could Not Duplicate Concern	
Barrel	Description		26" 300 RUM SS
	Date Code		BV
	Bore Plugged	False	
	Bulged	False	
	Fired	False	
	Fired while Obstructed		
	Muzzle/Crown Condition	Slightly Worn; Functioning	
	Firing Pin	Slightly Worn; Functioning	
	Shroud	Slightly Worn; Functioning	
Bolt	Face	Slightly Worn; Functioning	
	Handle	Slightly Worn; Functioning	
	Stop	Slightly Worn; Functioning	
	Condition	Slightly Worn; Functioning	
Extractor	Cut Condition	Slightly Worn; Functioning	
	Ext/Eject Test	False	
	Block Condition	Select	
Locking	Lug Condition	Slightly Worn; Functioning	
	Notch Condition	Select	
	Exterior Condition	Slightly Worn; Functioning	
Overall	Stock Condition	Slightly Worn; Functioning	
	Fore End Condition	Select	
Receiver	Condition	Slightly Worn; Functioning	
	Bulged	False	
Safety	Description		STANDARD M/700 SAFETY
	Function	Like new; Functioning	
	Sub-Assembly	ISS	
Sear	Lift	Select	.015
	Notch	Like new; Functioning	
	Tests	Test Fired	False
Feeding Test	1 6212	False	
Trigger	Condition	Slightly Worn; Functioning	TRIGGER IS BENT
	Pull	Select	5#
	Altered	False	
	Sub-Assembly	M/700 Non-Bolt Lock	



38.96 15 12 65.96

Factory Repair Instructions

(NOTE: Please print and complete this form, and then include it with your firearm.)				
Model Number: Reminyton 700 LH	Serial Number: \$6389431			
Are you the original owner?:				
Name: Patrick Perron	Date of Purchase: 2001			
Address (no PO Boxes): 140 Guineu	Rcl.			
Biddeford				
City:	State: Me. Zip: 04005			
Phone (Daytime): 267 571-486/	Fax: 267 284-8290			
E-mail Address: PRETTON (a MAINE. TY. COM I would like to receive future e-mail updates from Remington.				
Please describe your problem: The gu	n fired when			
I removed th	e Satety.			
la de la companya de				
Only used gon	in 2001 on 1			
, ,	,			
- hunting trip prior to this.				
Ammunition Information:				
Manufacturer: Lewinston	Type: 300 Ultra Mag			
Other (I.e. bullet weight/type; shot size, powder): 180-6-rain				
Noster-Partition				
Handload Information:				
Powder Used:	Powder Weight:			
Case/Hull Used:	Primer Used:			
Bullet Type/Shat Size:	Reloader Used:			
Firearms Care (Cleaning and Lubrication):				
Brand of cleaning solution used: Outers				
How often do you clean the bore? (Months or Number of rounds) After each use				
How often do you clean the action? (Months or Number of rounds). After each use				
How often do you clean the trigger assembly? (Months or Number of rounds)				
*				
Brand of lubricant used: 04 ters				

A Company of the Comp	The second section of the second seco
How often do you lubricate the bore? (Mont	2 0000000
How often do you lubricate the action? (Mor	
How often do you lubricate the trigger asser	noly? (Months or Number of rounds)
1.00	The Committee of the Co
Have ou reviewed the cleaning and mainte	nance recommendations on our web site or in our owners manual
Comments: I'VE ONLY U	sed this gon twice . Once
in 2001 & on	ce in october 2008
When was the last time that your firearm wa	as serviced by a Remington authorized repairman/gunsmith?
What were the services performed?	one
The state of the second	Control of the Contro
For the Appear to the Appear t	and the second of the second o
Ship your INSURED firearm by either UF	S or Parcel Post to:
ATTN	GTON ARMS CO., INC Arms Service Divison 14 Hoefler Ave
1	lion, NY 13357
FIREARM. THIS IS A VIOLATION OF FEDE SEND THEM IN A SEPARATE PACKAGE AND I MODEL AND SERIAL NUMBER OF YOUR FIRE	pefore sending it. It further damage in shipping and handling. Preferably,
38943	l Post. Remington is not responsible for to purchase insurance from your carrier.
VUU	uldelines:
	turned to you C.O.D. (To avoid C.O.D. Charges, please vith your gun)
00158497	estimate detailing the nature of the repair, applicable to pair estimate. Repairs can be paid by check, money order

could not Euplicate concern.
Trog. piece is sent. Puphace
TPA AT H/C Good will gesture.
#230145

a pre-authorized amount that can be billed to your credit card.

rd, or VISA). If you wish, you can expedite repairs over

Model: