

Remington Arms Co., Inc.
Product Service
Legal Case #:2243

Case Information

RE#	Date Opened	Date Opened(PS)	Date Closed	Incident Date	Pre Lit	Lit	Obsolete
143141	3/14/2008	3/17/2008	3/17/2008				

Customer Information

Type	Business	First Name	Last Name	Street	City	State	Zip	Age	Contact
Reporter		Greg	Stone-employee	870 Remington Dr. PO Box 700	Madison	NC	27025		W 336-548-8642

Incident Information

Claims	Codes	Repair Est.	Medical Treatment	Medical Status
PI				
PD				
S	Cause:4006 fires on safe release	Altered Adjustments or Components Concern:1007 Fired on Safe Release	Unknown	
C				

3/20/08-correspondence from repair-gun fires when moving safety.lw

Firearm Information

Mfg.	Type	Model/Ga.	SKU	Serial Bbl.	DOM
Remington	CF/BA	700/6MM REM	20000	6537136 AW	3/1/1972
Date Purchased	Where Purchased	Accessories	Original Owner		
	MATHEWS&BOUCHER ROCHESTER N Y	TWO PIECE SCOPE BASE	U		

CONCERN:FSR

Ammunition Information - None Defined

Other Products Information - None Defined

Settlement

Remington/700/CF/BA

Settlement	Release of Claims	Release Date	Reimbursement	Cash Settlement	Reim. Date APV	Cash Date APV
Replace TPA						
	Repair/Replacement Cost	Repair/Replacement Date				
	35	3/20/2008				

3/20/08-tpa replaced.lw

Examination[Remington/CF/BA]

Part	Sub-Part	Code	Comment
	Examiner		B.TRAVIS
	Exam Date		3/17/2008

Examination	Product Type		RF
	Action Type		A
	Assigned To		F.SUPRY
Cause	4006	Altered Adjustments or Components	WILL FOLLOW DOWN
Barrel	Description		24" 6MM REM HB
	Date Code		AW
	Bore Plugged	False	
	Bulged	False	
	Fired	False	
	Fired while Obstructed		
	Muzzle/Crown Condition	Slightly Worn; Functioning	
Bolt	Firing Pin	Slightly Worn; Functioning	
	Shroud	Slightly Worn; Functioning	
	Face	Worn; Functioning	DAMAGE FROM LEAKING PRIMERS
	Handle	Slightly Worn; Functioning	
	Stop	Slightly Worn; Functioning	
Extractor	Condition	Slightly Worn; Functioning	
	Cut Condition	Slightly Worn; Functioning	
	Ext/Eject Test	False	
Locking	Block Condition	---Select---	
	Lug Condition	Slightly Worn; Functioning	
	Notch Condition	---Select---	
Overall	Exterior Condition	Slightly Worn; Functioning	
	Stock Condition	Slightly Worn; Functioning	
	Fore End Condition	---Select---	
Receiver	Condition	Slightly Worn; Functioning	
	Bulged	False	
Safety	Description		STANDARD M/700 BOLT LOCK SAFETY
	Function	Like new; Functioning	
Sear	Lift	---Select---	.005
	Notch	Slightly Worn; Functioning	
	Tests	Test Fired	False
Feeding Test		False	
Trigger	Condition	Slightly Worn; Functioning	SEAR CAM STICKY/BINDING
	Pull	---Select---	2#
	Altered	True	SET SCREWS ALTERED NO TRIG RETURN
	Sub-Assembly	M/700 Bolt Lock	
Non-Remington Components	Description		TWO PIECE SCOPE BASE

Arms Services Repair & Estimate System

FileAdd RepairEstimate RepairExpedite RepairInquiryRepair ToolsCSR ToolsReportsTable MaintenanceSystem MaintenanceHelp

Repair Inquiry

Repair Number: RE00143141

Serial: 6537136 Model: 700 Center Fire Caliber: 6mm Rem Produced: 05/04/1973

Repairman: Status: New 3/14/2008 6:05:25 PM

Verify Repair

Address Information

Customer:Received From:Return To:Received From:

Name: GRAG STONE-MADISON EMPLOYEEGRAG STONE-MADISON EMPLOYEE

Address 1: 870 REMINGTON DRIVE870 REMINGTON DRIVE

Address 2: PO Box: PO Box:

City: MADISONMADISON

State: NC Zip Code: 27025 Country: USState: NC Zip Code: 27025 Country: US

FFL:

Contact / ConditionProblemsEstimateHistory / StatusShipping / Billing

Date	Code	User ID	Desc1	Desc2
3/14/2008 6:05:25	New	wainmands	Repair Added	
3/14/2008 6:08:00	Expedite	wainmands	From Check In	To:
3/17/2008 9:34:00	Comment	supryll	Bolt Lock Modification Program	

Repair Search

Shipping Hold

InterFace Hold

Estimate Sent

Parts Received

Passed Inspection

Return As Received

Has been Approved

Internal Repair

Current Status

New

3/14/2008 6:05:25 PM

wainmands

Product Services

Repair Location

ILN

Current Location

ILN

Transfer Number

Refresh

Close

supryll3/17/20089:34 AMCAPSNUMINSISCR

startArms Services Repair & Estimate SystemMicrosoft Excel 2003Arms Services Repair & Estimate System

CP0050 6:05 AM

PS 10074

Remington®

2243

2#
AW 3/7
24"
005

Product Service
Attn: Fred Supry

Ref: Model 700 6mm, Serial number 6537136

Gun fires when moving safety

Please evaluate firearm and install new trigger.

Any questions, please contact John Loschin.

Greg Stone
Madison employee - x8642

Trig. set screws altered, no
trig. return. sear cam sticky
binding. replace TPA, check over
clean under bolt lock safety
low \$ 20.00

Quote.

Serial
Number:

6537136

Model: 700



RE00143141