

Remington Arms Co., Inc.
Product Service
Legal Case #:2623

Case Information

RE#	Date Opened	Date Opened(PS)	Date Closed	Incident Date	Pre Lit	Lit	Obsolete
149341	8/20/2008	8/21/2008	8/21/2008				

Customer Information

Type	Business	First Name	Last Name	Street	City	State	Zip	Age	Contact
Reporter	Tejas Trading Post			2121 W. Hwy 290	Giddings	TX	78942		W 979-542-3885 E tejastrading@verizon.net

Incident Information

Claims	Codes	Repair Est.	Medical Treatment	Medical Status
PI				
PD	Cause:4038	Could Not Duplicate Concern		Unknown
S	Fired on bolt closing	Concern:1008 Fired on Bolt Closing		
C				

Could not get the rifle to malfunction under any of the tests performed. Bolt lock style rifle will be changed to non-bolt lock under the bolt lock modification program fls.

Firearm Information

Mfg.	Type	Model/Ga.	SKU	Serial	Bbl.	DOM
Remington	CF/BA	700/222 REM MA	20000	157644	PM	6/1/1965
Date Purchased	Where Purchased	Accessories	Original Owner			
	PREC TOOL GUN ITHACA NY		U			

CONCERN:FBC

Ammunition Information - None Defined

Other Products Information - None Defined

Settlement

Settlement	Release of Claims	Release Date	Reimbursement	Cash Settlement	Reim. Date APV	Cash Date APV
BLM Program						
	Repair/Replacement Cost	Repair/Replacement Date				
	65.00	8/21/2008				

8/21/2008 returned to AS to repair under the bolt lock modification program fls.

Examination[Remington/CF/BA]

Part	Sub-Part	Code	Comment
Examination	Examiner		B.TRAVIS
	Exam Date		8/21/2008
	Product Type		RF
	Action Type		A
	Assigned To		F.SUPRY

Cause	4038	Could Not Duplicate Concern	
Barrel	Description		24" 222 REM MAG
	Date Code		PM
	Bore Plugged	False	
	Bulged	False	
	Fired	False	
	Fired while Obstructed		
	Muzzle/Crown Condition	---Select---	
Bolt	Firing Pin	Slightly Worn; Functioning	
	Shroud	Slightly Worn; Functioning	
	Face	Slightly Worn; Functioning	
	Handle	Slightly Worn; Functioning	
	Stop	Slightly Worn; Functioning	
Extractor	Condition	Slightly Worn; Functioning	
	Cut Condition	Slightly Worn; Functioning	
	Ext/Eject Test	False	
Locking	Block Condition	---Select---	
	Lug Condition	Slightly Worn; Functioning	
	Notch Condition	---Select---	
Overall	Exterior Condition	Slightly Worn; Functioning	
	Stock Condition	Slightly Worn; Functioning	
	Fore End Condition	---Select---	
Receiver	Condition	Slightly Worn; Functioning	
	Bulged	False	
Safety	Description		STANDARD M/700 BOLT LOCK SAFETY
	Function	Like new; Functioning	
Sear	Lift	---Select---	.006
	Notch	Slightly Worn; Functioning	BLACK GREASE ON SEARCAM
	Tests	Test Fired	False
Feeding Test		False	
Trigger	Condition	Slightly Worn; Functioning	EXCESSIVE BLACK GREASE ON SEARCAM
	Pull	---Select---	3#
	Altered	False	
	Sub-Assembly	M/700 Bolt Lock	

Arms Services Repair & Estimate System

File Add Repair Estimate Repair Expedite Repair Inquiry Repair Tools CSR Tools Reports Table Maintenance System Maintenance Help

Repair Inquiry

Repair Number: **RE00149341** Serial: 157644 Model: 700 Center Fire Caliber: 222 REM. MAG. Produced: 06/17/1970 Repairman: Robert Frink
 Verify Repair Status: ApprovalHold 8/21/2008 5:59:15 AM

Address Information

Customer: **TEJAS TRADING POST** Received From: **TEJAS TRADING POST** Return To: **TEJAS TRADING POST**
 Address 1: 2121 W HWY 290 Address 2: 2121 W HWY 290
 City: GIDDINGS PO Box: PO Box: GIDDINGS
 State: TX Zip Code: 78942 Country: US State: TX Zip Code: 78942 Country: US

FEL 5 74 287 01 11 02016 082011

Contact / Condition	Problems	Estimate	History / Status	Shipping / Billing
Date	Code	User ID	Desc1	Desc2
8/14/2008 6:17:4	New	sanguis	Repair Added	
8/14/2008 12:05	EmailSent	ArmEm	Repair Received	TEJASTRADING@VERIZON.N
8/14/2008 12:05	EmailVerif	ArmEm	Receipt	TEJASTRADING@VERIZON.N
8/20/2008 6:26:3	Expedite	pencer	From: Check In	To: Repair Bench
8/20/2008 1:09:3	Estimate	frinkre	Estimate Update	Status: Estimating
8/21/2008 5:59:1	Estimate	frinkre	Estimate Update	Status: ApprovalHold
8/21/2008 7:50:5	Expedite	pencer	From: Repair Bench	To: ApproveRack

Shipping Hold ☐ InterFace Hold ☐ Estimate Sent ☐ Parts Received ☐ Passed Inspection ☐ ReturnAs Received ☐ Has been Approved ☐ Internal Repair ☐

Current Status: ApprovalHold 8/21/2008 5:59:15 AM
 frinkre
 ApproveRack
 Repair Location: ILN
 Current Location: ILN
 Transfer Number:

Repair Search Refresh Close

supryll 8/21/2008 8:32 AM CAPS NUM INS SCPI

start Inbox - Micros... Microsoft Exce... Arms Services... Search for a S... Current Cases... Part Search by... 8:32 AM

Bolt Lock modification Program

2623
TEJAS TRADING POST

PO BOX 546

LIFE MEMBER

2121 W HWY 290

LIFE MEMBER

NRA

GIDDINGS, TX 78942

TSRA

979-542-3885 TEJASTRADING@VERIZON.NET

PM 6/65
24"
3#
.006

GUN LOCK

DATE 8-11-08

Remington Arms Co., Inc.
Bolt Safety Modification
14 Hoefler Ave
Ilion, NY 13357

QUANTITY	DESCRIPTION	AMOUNT
	Remington 700 BDL	
	222 Rem Mag	
	Sn # 157644	
	Gun may fire and has	
	fired when you close	
	the bolt. Please repair	
	under warranty. Do	
	not keep this gun.	
	Customer says it is	
	a family gun.	
	Thanks	
	Bob Whiteides	
	FFL Attached	

Serial
Number:

157644

Model: 700



RE00149341

COULD NOT DUPLICATE CONCERN.
Replaced TPA, check over, clean
under bolt lock program
for \$20.00 + GST

Quote