

Remington Arms Co., Inc.
Product Service
Legal Case #:2615

Case Information

RE#	Date Opened	Date Opened(PS)	Date Closed	Incident Date	Pre Lit	Lit	Obsolete
149411	8/15/2008	8/18/2008	8/18/2008				

Customer Information

Type	Business	First Name	Last Name	Street	City	State	Zip	Age	Contact
Reporter		Larry	Todd	704 Laurel Ridge Ln	Cataula	GA	31804		H 706 322-0237

Incident Information

Claims	Codes	Repair Est.	Medical Treatment	Medical Status
PI				
PD	Cause:4038 Could Not Duplicate Concern		Unknown	
S	fires on safe release Concern:1007 Fired on Safe Release			
C				

8/19/08-correspondence from repair-gun fires when safety is removed to shoot but not at all times.lw

Firearm Information

Mfg.	Type	Model/Ga.	SKU	Serial	Bbl.	DOM
Remington	CF/BA	700/3006 SPR	20000	B6556734	AE	3/1/1984
Date Purchased	Where Purchased	Accessories	Original Owner			
	MAURICE SPTG CHICAGO IL		U			

CONCERN:FSR

Ammunition Information - None Defined

Other Products Information - None Defined

Settlement

Settlement	Release of Claims	Release Date	Reimbursement	Cash Settlement	Reim. Date APV	Cash Date APV
Repair at discount						
	Repair/Replacement Cost	Repair/Replacement Date				

8/19/08-quote sent to repair at discount. trig assem set screw altered.lw

Examination[Remington/CF/BA]

Part	Sub-Part	Code	Comment
Examination	Examiner		B.TRAVIS
	Exam Date		8/18/2008
	Product Type		RF
	Action Type		A
	Assigned To		F.SUPRY
Cause	4006	Altered Adjustments or Components	TRIG SET SCREWS ALTERED
Barrel	Description		22" 3006 SPR
	Date Code		AE
	Bore Plugged	False	
	Bulged	False	
	Fired	False	
	Fired while Obstructed		

	Muzzle/Crown Condition	Slightly Worn; Functioning	
Bolt	Firing Pin	Slightly Worn; Functioning	
	Shroud	Slightly Worn; Functioning	
	Face	Worn; Functioning	
	Handle	Slightly Worn; Functioning	
	Stop	Slightly Worn; Functioning	
Extractor	Condition	Slightly Worn; Functioning	
	Cut Condition	Slightly Worn; Functioning	
	Ext/Eject Test	False	
Locking	Block Condition	---Select---	
	Lug Condition	Slightly Worn; Functioning	
	Notch Condition	---Select---	
Overall	Exterior Condition	Worn; Functioning	
	Stock Condition	Worn; Functioning	
	Fore End Condition	---Select---	
Receiver	Condition	Slightly Worn; Functioning	
	Bulged	False	
Safety	Description		STANDRAD M/700 SAFETY
	Function	Like new; Functioning	
	Sub-Assembly	Non-ISS	
Sear	Lift	---Select---	.014
	Notch	Like new; Functioning	
	Tests	Test Fired	False
Feeding Test		False	
Trigger	Condition	Slightly Worn; Functioning	
	Pull	---Select---	3#
	Altered	True	SET SCREWS ALTERED
	Sub-Assembly	M/700 Non-Bolt Lock	

Arms Services Repair & Estimate System

File Add Repair Estimate Repair Expedite Repair Inquiry Repair Tools CSR Tools Reports Table Maintenance System Maintenance Help

Repair Inquiry

Repair Number: RE00149411 Serial: 86556734 Model: 700 Center Fire Caliber: 3006 SPRG Produced: 04/19/1994 Repairman: Status: New: 8/15/2008 5:40:13 AM

Verify Repair

Address Information

Customer: Received From Return To Received From

Name: LARRY TODD LARRY TODD

Address 1: 704 LAURELRIDGE LANE 704 LAURELRIDGE LANE

Address 2: PO Box PO Box

City: CATAUALA CATAUALA

State: GA Zip Code: 31804 Country: US State: GA Zip Code: 31804 Country: US

FFL

Contact / Condition Problems Estimate History / Status Shipping / Billing

Date	Code	User ID	Desc1	Desc2
8/15/2008 5:40:13	New	valentids	Repair Added	
8/18/2008 11:07:6	Expedite	percerl	From: Check In	To: Repair Bench
8/18/2008 3:12:4	Comment	supryfl	Returned for special price repair	

Shipping Hold
Interface Hold
Estimate Sent
Parts Received
Passed Inspection
Return As Received
Has been Approved
Internal Repair

Current Status
New
8/15/2008 5:40:13 AM
valentids
Repair Bench
Repair Location
ILN
Current Location
ILN
Transfer Number

Repair Search Refresh Close

start 8/18/2008 3:12 PM CAP6 NUM INS SCRL
Inbox - Microsoft Out... Arms Services Repair PS Hold Guns AS Search for a Serial Nu... 3:12 PM

Serial
Number:

B6556734

Model: 700



RE00149411

2615

AE 3/84
3#
22"
014

VIA



FROM:

LARRY TODD
704 LAUREL RIDGE LN
CAVALA GA 31804

T
O

GUN FIRES WHEN SAFETY
IS REMOVED TO SHOOT
BUT NOT ALL TIMES.

PEEL HERE TO REMOVE BACKING

COULD NOT DUPLICATE CONCERN.
TRIG ASSM. SET SCREWS ADJUSTED.
REPLACE TPA, CHECK OVER, CLEAN
AT 1/2 NORMAL COST.

Quote