Remington Arms Co., Inc.
Product Service
Legal Case #:2411

Case Information

RE# Date Opened Date Opened(PS) Date Closed Incident Date Pre Lit Lit Obsolete

146375 6/13/2008 5/19/2008 6/16/2008

**Customer Information** 

Type Business First Last Name Street City State Zip Age Contact

Street City State Zip Age Contact

April 10 Street City State Zip Age Contact

April 10 Street City State Zip Age Contact

Reporter Wilburn Umstattd Ave Maysville KY 41056 5019

Incident Information

Claims Codes Repair Medical Medical Est. Treatment Status

PI

shot through

Cause: 4079 Other - Unexamined

PD mattress & boxspring

Fired on Bolt

Concern:1008 Fired on Bolt Closing

Unknown

S fired on bolt closing

 $\mathbf{C}$ 

5/19/08-Customer purchased rifle used at a gun show. On two occasions, it fired when the bolt was closed. Once at the gun range and once at home, shooting a hole through his mattress & boxspring. He would like to send it in to be evaluated.lw

Firearm Information

Mfg. Model/Ga. SKU Type Serial Bbl. DOM CF/BA 700/22 250 REM Remington 27488 E6205162 XP 12/18/1995 Date **Original** Where Purchased Accessories Purchased Owner NATIONAL TWO PIECE RECREATIONAL SCOPE BASE, N SHOOTING SUPP RINGS 5/19/08-purchased used at a gun show.lw CONCERN:FBC

Ammunition Information - None Defined

Other Products Information - None Defined

Settlement

Remington/700/CF/BA

Settlement Release of Claims Release Date Reimbursement Cash Settlement Release Date Reimbursement Release Date Settlement Release Date Settlement Release Date Settlement Release Date Reimbursement Release Date Settlement Release Date Reimbursement Release Date Release

Consumer

paid for repairs

### Repair/Replacement Repair/Replacement Cost Date

5/20/08-sending box, ars, ltr.lw 6/19/08 the consumer authorized and paid for repair of this firearm. cm

### Examination[Remington/CF/BA]

Part	Sub-Part	Code	Comment
	Examiner		B.TRAVIS
	Exam Date		6/16/2008
Examination  Cause  Barrel  Bolt  Extractor  Locking	Product Type		RF
	Action Type		A
	Assigned To	B.TRAVIS   6/16/2008   RF   A   F.SUPRY	F.SUPRY
Cause	4006		
	Description		26" 22 250 REM HB
	Date Code		XP
	Bore Plugged	False	
Rarrel	Bulged	False	
Darioi	Fired	False	]
	Fired while Obstructed		
	Muzzle/Crown Condition	Slightly Worn; Functioning	
	Firing Pin	Slightly Worn; Functioning	]
Cause  Barrel  Bolt  Extractor  Locking	Shroud	Slightly Worn; Functioning	
	Face	Slightly Worn; Functioning	
	Handle	Slightly Worn; Functioning	]
	Stop	Slightly Worn; Functioning	
	Condition	Slightly Worn; Functioning	
Extractor	Cut Condition	Slightly Worn; Functioning	
	Ext/Eject Test	False	
Locking	Block Condition	Select	
	Lug Condition	Slightly Worn; Functioning	
	Notch Condition	Select	
Overall	Exterior Condition	Slightly Worn; Functioning	
	Stock Condition	Slightly Worn; Functioning	
	Fore End Condition	Select	
	Condition	Slightly Worn; Functioning	

Receiver	Bulged	False	1
Safety	Description		STANDARD M/700 SAFETY
	Function	Like new; Functioning	
	Sub-Assembly	Non-ISS	
	Lift	Select	.016
Sear	Notch	Like new; Functioning	
		Test Fired	False
Feeding Test	Tests	False	
	Condition	Slightly Worn; Not Functioning	]
Trigger	Pull	Select	2.5#
	Altered	True	SET SCREWS ALTERED
	Sub-Assembly	M/700 Non-Bolt Lock	

### Remington.

May 20, 2008

17 2/95 26"

Wilburn Umstattd 5 Arrington Ave Maysville, KY 41056-1701

Subject: Model 700 RE: Case #2411

Dear Mr. Umstattd,

E6205162

Model: 700



We were sorry to learn about the unfortunate incident you experienced with your Model 700. As I understand it, the rifle fired when you closed the bolt. We are certainly glad that no one was injured, and that you are anxious to get back to enjoying the shooting sports.

As we discussed, I have enclosed a prepaid UPS shipping label for you to ship the firearm back to our factory for examination. I have also included a copy of this letter to put inside the shipping box. (The box will come under separate cover). The letter inside is important as we want to be sure the firearm is logged in correctly. On the factory repair form, please provide additional information about the incident, including the date of the last occurrence, type of weather, type of ammunition being used, etc.

We apologize for the inconvenience that this incident has caused and we hope that our actions will keep you as a loyal Remington customer.

Sincerely,

Laura Watson

Consumer Affairs Administrator

Remington Arms Company

Phone: 800-243-9700 ext 8789

Fax: 336-548-7890

E-mail: laura.watson@remington.com

TRIG. ASSM. Set Screws Altered, will follow down, hephace TAA, cleck over, clean AT 1/2 NON WAL Charges.

Quote

Re Arms Services Repair & Estimate System	Tools GSR/Tools Reports Table Maintenance System Maintenance, Help	
S Repair Inquiry		
Repail Number, RE00146375   Senal : E6205162 Model : 22250 REM. Produced: 1	700 Center Fire Caliber Repairman 2/18/1995 Status Closed 6/13/2008 5:33:30 AM	
Address Information	om Return I C	
Name: WILBURN UMSTATTD  Addiess 1: 5 ARRINGTON AVE. Address 2: RO.Box: City: MAYSVILLE State: KY Zip Code: A1056 Country: US  Contact / Condition Problems  Date: Code: User,ID Desc1 6/13/2008 5:27.2 New sanguined Repair Added 6/13/2008 5:33.3 Closed sanguined Closed at Expedite 6/16/2008 17:27 Comment supryfl Returned to AS for re	MILBURN UMSTATTD    SARRINGTON AVE.   PO:Box     MAYSVILLE   State   KY   Zip Code: [41056   Counity]   US     Estimate   History / Status   Shipping / Billing     Estimate   History / Status   Shipping / Billing     Current Status   Closed:     Shipping Hold   Closed:   S6/13/2008.533.30/AM     Pair   Festimate Sent   Froduct Services     Parts Received   Product Services     Passed Inspection   Epimit Location     Return As Received   Current Location	
Repair Search	Has been Approved  Transfer Number  Finernal Repair  Refresh  Close	
T 27 AW 6/16/2008 (11:27 AW)	CAPS INUM INS. SERE	
Hatari Duba Micorotolia o Amasana	nena. 💹 Patted Guna (Sartara) 🖟 🐧 Port Search by Male 📆 🔭 🤰	Current Cases a Mic (C)   O   C   EU   Int ZYAM .

Repairing at special price

# Remington

Factory Repair Instructions

(NOTE: Please print and complete this form, and then include it with your firearm.)

Model Number: 700 1304	Serial Number: <i>E670</i> 5162			
Are you the original owner?: Are you the original owner?:				
Name: WILBURN UMSTATTO	Date of Purchase: 2600			
Address (no PO Boxes): 5 A 17,21 NG TON				
	,			
City: MAYSVILLE	State: Ky	zip: 4/1056		
Phone (Daytime): 106-564-5019	Fax: NONE	· · · · · · · · · · · · · · · · · · ·		
E-mail Address: NONE	a service and the service and			
would like to receive future e-mail updates from R		<del></del>		
Please describe your problem: FIRES ON	CLOSINY ROLT			
the state of the state of				
		·.		
	The state of the s			
	<u> </u>			
4. 44.		• • •		
and the second of the second o	name to a state thought and a state of	·		
Ammunition Information:				
Manufacturer:	Туре:			
Other (i.e. bullet weight/type, shot size, powder):	<u> </u>	· · · · · · · · · · · · · · · · · · ·		
	ente a la companya de la companya d	,		
Handload Information:	<u> </u>			
Powder Used: JMR 4064  Case/Hull Used: REM — WIN	Primer Used: Cel Han	1 1 35.5q		
Case/Hull Used: REM — WIN;	Primer Used: CC/ Hop	Small PIFLE		
Bullet Type/Shot Size: 55 92 . S.P.	Reloader Used: Lym	9N		
Firearms Care (Cleaning and Lubrication):	77			
Brand of cleaning solution used: REM-OIL	+ HOPPES			
How often do you clean the bore? (Months or Number of	•	SISOOTING		
How often do you clean the action? (Months or Number of		_		
How often do you clean the trigger assembly? (Months or Number of rounds)				
Brand of lubricant used: REm - 012	-Hoppes			

·
How aften do you lubricate the bore? (Months or Number of rounds) AFTFR SHOETING
How often do you lubricate the action? (Months or Number of rounds)
How often do you lubricate the trigger assembly? (Months or Number of rounds) 6 m c
Have you reviewed the cleaning and maintenance recommendations on our web site or in our owners manual?
Comments:
When was the last time that your firearm was serviced by a Remington authorized repairman/gunsmith?
What were the services performed?
Ship your INSURED firearm by either UPS or Parcel Post to:
REMINGTON ARMS CO., INC
Control of the Contro
ATTN: Arms Service Divison  - 14 Hoefler Ave  - Ilion, NY 13357
WARNING: DO NOT SEND LIVE OR SPENT SHELLS IN YOUR FIREARM OR IN THE SAME BOX WITH THE FIREARM. THIS IS A VIOLATION OF FEDERAL-LAW: IF YOU FEEL YOU MUST SEND SPENT SHELLS PLEASE SEND THEM IN A SEPARATE PACKAGE AND INCLUDE NAME, ADDRESS (WITH ZIP CODE), TELEPHONE AND MODEL AND SERIAL NUMBER OF YOUR FIREARM.
<ul> <li>Record the serial number of your firearm before sending it.</li> <li>Pack your firearm for safety and to prevent further damage in shipping and handling. Preferably, ship in a firearm box. (Note: Original boxes may not be returned.)</li> </ul>
:: Remove all accessories from your firearm to prevent loss or damage. :: Provide a return address on both the outside and inside the box. Shipments without a proper
return address will be refused.  Ship your INSURED firearm by either UPS or Parcel Post. Remington is not responsible for damage or loss during shipment, so you may elect to purchase insurance from your carrier.
Charge repairs will be processed using the following guidelines:
:: Repairs \$75.00 and under will be completed and returned to you C.O.D. (To avoid C.O.D. Charges, please include your credit card number and expiration date with your gun)
For Repairs over \$75.00, you will receive a written estimate detailing the nature of the repair, applicable taxes and shipping. You will have 30 days to approve the repair estimate. Repairs can be paid by check, money order, or credit card (American Express, Discover, MasterCard, or VISA). If you wish, you can expedite repairs over \$\frac{1}{3}5.00 by setting a pre-authorized amount that can be billed to your credit card.



May 20, 2008

Wilburn Umstattd 5 Arrington Ave Maysville, KY 41056-1701

Subject: Model 700 RE: Case #2411

Dear Mr. Umstattd,

We were sorry to learn about the unfortunate incident you experienced with your Model 700. As I understand it, the rifle fired when you closed the bolt. We are certainly glad that no one was injured, and that you are anxious to get back to enjoying the shooting sports.

As we discussed, I have enclosed a prepaid UPS shipping label for you to ship the firearm back to our factory for examination. I have also included a copy of this letter to put inside the shipping box. (The box will come under separate cover). The letter inside is important as we want to be sure the firearm is logged in correctly. On the factory repair form, please provide additional information about the incident, including the date of the last occurrence, type of weather, type of ammunition being used, etc.

We apologize for the inconvenience that this incident has caused and we hope that our actions will keep you as a loyal Remington customer.

Sincerely,

Laura Watson

Consumer Affairs Administrator Remington Arms Company

Phone: 800-243-9700 ext 8789

Fax: 336-548-7890

E-mail: laura.watson@remington.com

WILBURN UMSTATTD 5 ARRINGTON AVE MAYSVILLE KY 41056

12 LBS RS


1 OF 1

SHIP TO:

ATTN: PRODUCT SERVICES REMINGTON ARMS CO INC

14 HOEFLER AVE

**ILION NY 13357** 



## 135 0-01



#### UPS GROUND

TRACKING #: 1Z 4XX 596 90 6767 0494



BILLING: 3RD PARTY DESC: FIREARM RETURN SERVICE

REF 1:WILBURN UMSTATTD/LW REF 2:REF# 700

WS 10.0.45

LF2844 72.8A 10/2087



#### Oakley, Anita B.

From:

Watson, Laura M.

Sent:

Monday, May 19, 2008 2:35 PM

To:

Oakley, Anita B.

Subject:

If this doesn't work, I'll bring it over:)

Attachments: image001.jpg



www.remington.com

Remington Arms Company, Inc.

870 Remington Drive

P. O. Box 700

Madison, NC 27025-0700

### ARS LABEL REQUEST

DATE:		5/19/2008	REQUESTED E	3Y:	Laura Watson	
QUANTITY:		1	WEIGHT PER I	PACKAGE	•	12
PLEASE CHECK ONE: MEDIA COORDINATOR TO MAIL			I WILL MAIL		XXXX	
DESCRIPTION:	REF: 700					

### LABEL INFORMATION

MAIL LABEL TO:	Wilburn Umstattd 5 Arrington Ave Maysville, KY 41056	4XX596 MAY 19, 200 SERVICE GNDCOM ACT TRACKING# 1Z4XX5969067676 REF 1:WILBURN UMSTATTD/LU REF 2:REF# 700	WT 12.0 LBS 0494	} SD 1 OF 1
RETURN ITEM	llion, NY Attn: Product Service Factory Only	HANDLING CHARGE 0.00 SINGLE-PIECE PUB RATE CHE DV 0.00 COD DC 0.00 DG AH 0.00 PR TOT PUB CHG 7.73	0.00 R: 0.00 Si	C T/P USD S 0.50 D 0.00 P 0.00 7.73
	(Need a label please)			1

PLEASE COMPLETE ALL PARTS OF THIS FORM AND SEND TO THE MEDIA COORDINATOR