Remington Arms Co., Inc.
Product Service
Legal Case #:3333

Case Information

RE# Date Opened Date Opened(PS) Date Closed Incident Date Pre Lit Lit Obsolete 162971 2/26/2009 3/18/2009 3/18/2009

Customer Information

Type Business First Name Last Name Street City State Zip Age Contact

Reporter Gander Mountain Gander Mountain 19302 Interstate 45 Spring TX 77373

Incident Information

Claims Codes Repair Est. Medical Treatment Medical Status

PΙ

PD Cause:4038 Could Not Duplicate Concern Unknown

S fired with safety on Concern: 1028 Fired With Safe ON

C

3/23/09 per letter with rifle, customer wants factory certification that the gun is safe. Claims the gun fired with the safety switch engaged when the bolt was closed.cm

Firearm Information

 Mfg.
 Type
 Model/Ga.
 SKU
 Serial
 Bbi.
 DOM

 Remington
 CF/BA
 710/7MM REM MA
 27412
 71275968
 BA
 1/25/2006 3:21:44 AM

Date Purchased Where Purchased Accessories Original Owner

ACADEMY CORP SCOPE, RINGS, BASE U

ONORDALEIDED WITH CAFETY ON

CONCERN: FIRED WITH SAFETY ON

Ammunition Information - None Defined Other Products Information - None Defined

Settlement

Remington/710/CF/BA

Settlement Release of Claims Release Date Reimbursement Cash Reim. Date Cash Date

Settlement APV APV

replace TPA at no charge as goodwill gesture

Repair/Replacement Repair/Replacement Cost Date


109.16 3/23/2009

3/23/09 Could not duplicate concern. Check over completely, replace TPA to restore confidence in rifle.cm

Examination[Remington/CF/BA]

Part	Sub-Part	Code	Comment
Examination	Examiner		B.TRAVIS
	Exam Date		3/18/2009
	Product Type		RF
	Action Type		A
	Assigned To		F.SUPRY
Cause	4038	Could Not Duplicate Concern	
	Description		24" 7MM RÉM MAG
	Date Code	 	BA

Barrel	Bore Plugged	False	
	Bulged	False	
	Fired	False	7
	Fired while Obstructed		
	Muzzle/Crown Condition	Slightly Worn; Functioning	
Bolt	Firing Pin	Slightly Worn; Functioning	
	Shroud	Slightly Worn; Functioning	
	Face	Slightly Worn; Functioning	=
	Handle	Slightly Worn; Functioning	
	Stop	Slightly Worn; Functioning	<u> </u>
Extractor	Condition	Slightly Worn; Functioning	
	Cut Condition	Slightly Worn; Functioning	
	Ext/Eject Test	False	
	Block Condition	Select	
Locking	Lug Condition	Slightly Worn; Functioning	
_	Notch Condition	Select	
	Condition	Select	
Magazine	Box Condition	Slightly Worn; Functioning	
Overall	Exterior Condition	Slightly Worn; Functioning	
	Stock Condition	Slightly Worn; Functioning	
	Fore End Condition	Select	
Receiver	Condition	Slightly Worn; Functioning	
	Bulged	False	
Safety	Description		STANDARD M/710 SAFETY
	Function	Like new; Functioning	
	Sub-Assembly	Non-ISS	
Sear	Lift	Select	N/A
	Notch	Like new; Functioning	
	Tests	Test Fired	False
Feeding Test	1 6363	False	
Trigger	Condition	Like new; Functioning	
	Pull	Select	6.5#
	Altered	False	
	Sub-Assembly	Other Remington	



\$14.66 15 35 17.50 12 15 104.16





Service Request

Service Order # 2967

SHIPPED TO VENDOR/STORE:

Remington Repair FFL# 6-16-00726 14 Hoefler Ave

Ilion, NY 13357

Model:

Attn: Warranty Repair

Date Shipped: 02/03/2009

Phone: (000) 000-0000

RETURN SHIP TO:

Gander Mountain, FFL# 5-76-201-01-8B-01220

Attn: Gun Parts Dept. 19302 Interstate 45 Spring, TX 77373

FIREARM INFORMATION:

710

Manufacturer: Remington Arms Co Inc.

Type:

Rifle

Serial Number: 71275968

Cal/Ga.: 7mm. Mag

Cased?:

DESCRIPTION OF ITEM RETURNED:

Complete firearm package w/scope mounted and one mag

REASON FOR RETURN:

Customer wards Factory certification that gun is safe. Claims the gun fired with the safety switch engaged when the bolt was closed.

ATTENTION VENDOR

Please contact me with any questions or concerns.

Jerry Dawkins

BILLING INFORMATION:

Please include the service order number on all invoices and correspondence:

SHIP TO ABOVE ADDRESS

Forward all invoices to:

Gander Mountain

Attn: Cindy Kilbride 180 East Fifth Street

St. Paul, MN 55101

could not duplicate concerna-check over completely replace TPA to pestare confidence

in rifle. x/

230145



Model:

710

