

Remington Arms Co., Inc.
Product Service
Legal Case #:4176

Case Information

RE#	Date Opened	Date Opened(PS)	Date Closed	Incident Date	Pre Lit	Lit	Obsolete
183107	12/14/2009	12/29/2009	12/29/2009				

Customer Information

Type	Business	First Name	Last Name	Street	City	State	Zip	Age	Contact
Reporter	Southern Pride Guns		Southern Pride	4670 Hwy 49	Tennessee Ridge	TN	37178		

Incident Information

Claims	Codes	Repair Est.	Medical Treatment	Medical Status
PI				
PD	Cause:4015	Improper Maintenance		
S	Concern:1070	Unknow Claim	Unknown	
C				

1/4/09 No correspondence with the rifle other than a copy of their FFL.cm

Firearm Information

Mfg.	Type	Model/Ga.	SKU	Serial	Bbl.	DOM
Remington	CF/BA	XP100/221 FB	20000	B7500704	LQ	2/27/1978
Date Purchased	Where Purchased	Accessories	Original Owner			
	SOUTHERN GUN DISTR MIAMI FL		U			

CONCERN:FBC

Ammunition Information - None Defined

Other Products Information - None Defined

Settlement

Remington/XP100/CF/BA

Settlement	Release of Claims	Release Date	Reimbursement	Cash Settlement	Reim. Date APV	Cash Date APV
Per Ilion inspect/decision replace TPA, clean for \$20 BLSM program price						

Repair/Replacement Cost	Repair/Replacement Date
42.78	1/4/2009

1/4/09 Per Ilion, trig assm dirty and sticky. Trig return is sluggish. Replace TPA, check over, clean under BLSM program price of \$20 + S&H.cm

Examination[Remington/CF/BA]

Part	Sub-Part	Code	Comment
Examination	Examiner		B.TRAVIS
	Exam Date		12/29/2009
	Product Type		RF
	Action Type		A
	Assigned To		F.SUPRY

Cause	4015	Improper Maintenance	
Barrel	Description		10.5" 221 FB VT
	Date Code		LQ
	Bore Plugged	False	
	Bulged	False	
	Fired	False	
	Fired while Obstructed		
	Muzzle/Crown Condition	Slightly Worn; Functioning	
Bolt	Firing Pin	Slightly Worn; Functioning	
	Shroud	Slightly Worn; Functioning	
	Face	Slightly Worn; Functioning	
	Handle	Slightly Worn; Functioning	
	Stop	Slightly Worn; Functioning	
Extractor	Condition	Slightly Worn; Functioning	
	Cut Condition	Slightly Worn; Functioning	
	Ext/Eject Test	False	
Locking	Block Condition	---Select---	
	Lug Condition	Slightly Worn; Functioning	
	Notch Condition	---Select---	
Overall	Exterior Condition	Slightly Worn; Functioning	
	Stock Condition	Slightly Worn; Functioning	
	Fore End Condition	---Select---	
Receiver	Condition	Slightly Worn; Functioning	
	Bulged	False	
Safety	Description		STANDARD XP100 BOLT LOCK SAFETY
	Function	Like new; Functioning	
Sear	Lift	---Select---	.012
	Notch	Like new; Functioning	
	Tests	Test Fired	False
Feeding Test		False	
Trigger	Condition	Slightly Worn; Functioning	DIRTY,STICKY TRIG RETURN SLUGGISH
	Pull	---Select---	3.5#
	Altered	False	
	Sub-Assembly	Other Remington	

DIRECT ATF
CORRESPONDENCE
TO

Chief, Federal Firearms Licensing Center (FFLC)
Bureau of Alcohol, Tobacco, Firearms and Explosives
2600 Century Parkway NE Suite 110
Atlanta, Georgia 30345-3104

Telephone: 1-866-662-2750 Fax: 1-866-257-2749
E-mail: NLC@atf.gov ATF website: <http://www.atf.gov>

LICENSE
NUMBER

1-62-083-01-0F-03079

EXPIRATION
DATE

June 1, 2010

NAME

SOUTHERN PRIDE GUNS

Premises Address CHANGES? You must notify the FFLC at le

4670 HWY 49

TENNESSEE RIDGE, TN 37178-

TYPE OF LICENSE

01-DEALER IN FIREARMS OTHER THAN DESTRUCTIVE DEVICES

CHIEF, FEDERAL FIREARMS LICENSING CENTER (FFLC)

Patricia Power

PURCHASING CERTIFICATION

I certify that this is a true copy of a license
issued to me to engage in the business specified.

Michael A. Richardson

Mailing Address CHANGES? Mail is NOT forwarded. Notify th

RICHARDSON, MICHAEL ANTHONY

SOUTHERN PRIDE GUNS

4670 HWY 49

TENNESSEE RIDGE, TN 37178-

Serial
Number:

B7500704

Model: **XP-100**



RE00183107

*FILE
COPY*

*TRIG. Assm dirty & sticky. TRIG.
RETURN IS SLUGGISH. Replace*

*GPA, check over, clear under
BOLT LOCK, program for \$20.00 +*

SH.

Quote