Remington Arms Co., Inc. Product Service Legal Case #:2283

Case Information

RE# Date Opened Date Opened(PS) Date Closed Incident Date Pre Lit Lit Obsolete 3/28/2008 3/28/2008

Customer Information

Contact **Business** Type First Name Last Name Street City State Zip Age Reporter Richard 9600 Lockerbie Ave El Paso 79925 H 915-593-1570 Apodaca TX

Incident Information

Claims Codes Repair Est. Medical Treatment Medical Status

PΙ

PD

Cause:4038 Could Not Duplicate Concern

. . .

S fires on bolt closing

Concern: 1008 Fired on Bolt Closing

Unknown

C

4/2/08-correspondence from repair-safety does not work. goes off when "receiver" is pushed forward.lw

Firearm Information

Mfg.

Type CF/BA Model/Ga.

SKU

Serial Bbl.

DOM

Remington

Date Purchased

Where Purchased

600/308 WIN Accessories

Original Owner U 33184 LM 2/1/1965

CONCERN:FBC

Ammunition Information - None Defined Other Products Information - None Defined Settlement

Remington/600/CF/BA

Settlement Release of Claims

Release Date

Reimbursement

Cash Settlement Reim. Date Ca

Cash Date APV

Replace TA under

recall

Repair/Replacement Cost Repair/Replacement

35

Date 4/2/2008

4/2/08-update TA at n/c under recall.lw

Examination[Remington/CF/BA]

Sub-Part Code Part Comment **B.TRAVIS** Examiner Exam Date 3/28/2008 Product Type RF Examination Action Type F.SUPRY Assigned To Could Not Duplicate Concern 4038 Cause 18.5" 308 WIN VT Description LM Date Code Bore Plugged False Barrel Bulged False Fired False

http://cps03ap13:200/psaapp/PrintDisplay.aspx?ID=2283&Type=Case

4/2/2008

	Fired while Obstructed		
	Muzzle/Crown Condition	Slightly Worn; Functioning	
Bolt	Firing Pin	Slightly Worn; Functioning	
	Shroud	Slightly Worn; Functioning	
	Face	Slightly Worn; Functioning	
	Handle	Slightly Worn; Functioning	
	Stop	Slightly Worn; Functioning	
Extractor	Condition	Slightly Worn; Functioning	
	Cut Condition	Slightly Worn; Functioning	
	Ext/Eject Test	False	
	Block Condition	Select	
Locking	Lug Condition	Slightly Worn; Functioning	
_	Notch Condition	Select	
Overall	Exterior Condition	Like new; Functioning	
	Stock Condition	Slightly Worn; Functioning	
	Fore End Condition	Select	
Receiver	Condition	Slightly Worn; Functioning	
	Bulged	False	
Safety	Description		STANDARD M/600 BOLT LOCK SAFETY
	Function	Like new; Functioning	
Sear	Lift	Select	.007
	Notch	Slightly Worn; Functioning	
	Teata	Test Fired	False
Feeding Test	Tests	False	
Trigger	Condition	Slightly Worn; Functioning	OLD STYLE DOUBLE SEAR
	Pull	Select	5.5#
	Altered	False	
	Sub-Assembly	Other Remington	

Repair Inquiry		gerteration (newspaper)	and the second		X	
Repair Number RE00143669 /eniny Repair	Serial 33184 M WIN	lodel,600: Center Fire: Caliber 30		3/27/2008 6: 34:26 AM	Section 1	
ddress Information Customer Name: RICHARD APODACA	. Ae	cerved From	TO APODAÇA	C Received From		
Address 1: 9600 LOCKERBIE AVE Address 2: City EL PASO	PO Box	9600 LOC EL PASO	CKERBIE AVE	0.8ox		
State TX Zip Code 79925	Coun	iji Jus State TX 2 FFL	Zipi Code: 179925	Country US		
Contact / Condition	Problems User ID	Estimale	History 7 Status	Shipping? Billing Current Status New		
3/27/2008 6:33: New 3/27/2008 6:34: Update 3/27/2008 6:34: Expedite 3/28/2008 8:08:4 Expedite	valentds valentds valentds pencerl	Repair Added Repair information change From: Check In From: Product Services	□ InteiFace Höld □ Estimate Sent □ Parts Received	3/27/2008 6:34:26 AM valentds Repair Bench		
			Passed Inspection Return As Receive Has been Approve	ed Current Location		
			T Internal Repair	Tränsfei Number		
RepairSearch			<u>R</u> e	fresh <u>C</u> lose		

Updating poer current procedures. No

Factory Repair Instructions
(NOTE: Please print and complete this form, and then include it with your firearm.)

Model Number: 600	Serial Number: 3318	34						
Are you the original owner?: YES NO								
Name: RICHARDP. APODACA	Date of Purchase: 09-	2000						
Address (no PO Boxes): 9600 LOCKERBIE AVE								
city: EL PASO	State: TEXAS	zip: 79925-4121						
Phone (Daytime) (915) 593 1570	Fax:							
E-mail Address: I would like to receive future e-mail updates from Remington.								
Please describe your problem: SAFETY								
AMMUNITION GOES OFF WHEN RECEIVER								
15 PUSHED KOWARD.								
the second secon								
		· .						
		··· .						
to the second second	and the second of the second o							
Ammunition Information:								
Manufacturer: WINCHESTER	Type: COR6 LOKT	PTDSOFT						
Other (i.e. bullet weight/type, shot size, powder):								
150 GR								
Handload Information:								
Powder Used:	Powder Weight:							
Case/Hull Used:	Primer Used:							
Bullet Type/Shot Size:	Reloader Used:							
		*						
Firearms Care (Cleaning and Lubrication):								
Brand of cleaning solution used: UYTERS								
How often do you clean the bore? (Months or Number of rounds)								
How often do you clean the bore? (Months or Number of rounds) How often do you clean the action? (Months or Number of rounds) How often do you clean the trigger assembly? (Months or Number of rounds) TRIED SEVERAL								
How often do you clean the trigger assembly? (Months or Number of rounds) TRIED SEVERAL								
TINES STILL WILL NOT WORK								
Brand of lubricant used: REWINGTON	WONDER LUB	5						

How often do you lubricate the bore? (Months or Number of rounds)

How often do you lubricate the action? (Months or Number of rounds)

How often do you lubricate the trigger assembly? (Months of Number of rounds)

Have you reviewed the cleaning and maintenance recommendations on our web site or in our owners manual?

MANUAL WAS GIVEN WHEN

Comments:

When was the last time that your firearm was serviced by a Remington authorized repairman/gunsmith?

What were the services performed?

UPS or Parcel Post to:

Mr. Richard P. Apodaca

To Whom IT MAXONEEN Ilion, NY 13357

NGTON ARMS CO., INC

: Arms Service Divison 14 Hoefler Ave

I WAS INFORMED THAT THERE WOULD

NOT BE ACHARGE FOR THE REPAIR ETC HOWEVER IF THERE 15 ONE PLEASE CONTACT MESOIMAY GIVE YOU INTO ON ACREDIT CARD CHARBE. THANKING

PENT SHELLS IN YOUR FIREARM OR IN THE SAME BOX WITH THE EDERAL LAW. IF YOU FEEL YOU MUST SEND SPENT SHELLS PLEASE ND INCLUDE NAME, ADDRESS (WITH ZIP CODE), TELEPHONE AND IREARM.

rm before sending it. event further damage in shipping and handling. Preferably, oxes may not be returned.) irm to prevent loss or damage. outside and inside the box. Shipments without a proper

UPS or Parcel Post. Remington is not responsible for ou may elect to purchase insurance from your carrier.

he following guidelines:

pleted and returned to you C.O.D. (To avoid C.O.D. Charges, please iration date with your gun)

sive a written estimate detailing the nature of the repair, applicable taxes approve the repair estimate. Repairs can be paid by check, money order, ver, MasterCard, or VISA). If you wish, you can expedite repairs over unt that can be billed to your credit card.

33184

JOW IN ADVANCE.

Model:



rould not duplicate concern replace TPA under Trig. ASSM Nicall, check over, clenn AT N/C

27014