

Remington Arms Co., Inc.  
Product Service  
Legal Case #:2109

## Case Information

| RE#    | Date Opened | Date Opened(PS) | Date Closed | Incident Date | Pre Lit | Lit | Obsolete |
|--------|-------------|-----------------|-------------|---------------|---------|-----|----------|
| 141369 | 2/7/2008    | 2/8/2008        | 2/8/2008    |               |         |     |          |

## Customer Information

| Type     | Business                       | First Name | Last Name | Street         | City        | State | Zip   | Age | Contact        |
|----------|--------------------------------|------------|-----------|----------------|-------------|-------|-------|-----|----------------|
| Reporter | Taylor & Vadney Sporting Goods | Taylor     | Vadney    | 3071 Broadway  | Schenectady | NY    | 12306 |     | W 518-374-3030 |
| Incident |                                | Michael    | hamlin    | 111 Jenkins Rd | Burnt Hilo  | NY    | 12027 |     |                |

## Incident Information

| Claims                  | Codes                              | Repair Est. | Medical Treatment | Medical Status |
|-------------------------|------------------------------------|-------------|-------------------|----------------|
| PI                      |                                    |             |                   |                |
| PD                      | Cause:4015 Improper Maintenance    |             | Unknown           |                |
| S fired on safe release | Concern:1007 Fired on Safe Release |             |                   |                |
| C                       |                                    |             |                   |                |

2/11/08-correspondence from repair-gun fired when safety released. Trigger replaced in 2002.lw

## Firearm Information

| Mfg.           | Type            | Model/Ga.   | SKU            | Serial | Bbl. | DOM       |
|----------------|-----------------|-------------|----------------|--------|------|-----------|
| Remington      | CF/BA           | 600/308 WIN |                | 77044  | EU   | 10/1/1971 |
| Date Purchased | Where Purchased | Accessories | Original Owner |        |      |           |
|                |                 |             | U              |        |      |           |

CONCERN:FSR

Ammunition Information - None Defined

Other Products Information - None Defined

## Settlement

| Settlement        | Release of Claims       | Release Date            | Reimbursement | Cash Settlement | Reim. Date APV | Cash Date APV |
|-------------------|-------------------------|-------------------------|---------------|-----------------|----------------|---------------|
| Replace TA at n/c |                         |                         |               |                 |                |               |
|                   | Repair/Replacement Cost | Repair/Replacement Date |               |                 |                |               |
|                   | 35                      | 2/11/2008               |               |                 |                |               |

2/11/08-replace TA at n/c.lw

## Examination[Remington/CF/BA]

| Part        | Sub-Part     | Code                 | Comment                       |
|-------------|--------------|----------------------|-------------------------------|
| Examination | Examiner     |                      | B.TRAVIS                      |
|             | Exam Date    |                      | 2/8/2008                      |
|             | Product Type |                      | RF                            |
|             | Action Type  |                      | A                             |
|             | Assigned To  |                      | F.SUPRY                       |
| Cause       | 4015         | Improper Maintenance | TRIG ASSM RUSTY,PARTS BINDING |
| Barrel      | Description  |                      | 18.5" 308 WIN                 |
|             | Date Code    |                      | EU                            |
|             | Bore Plugged | False                |                               |
|             | Bulged       | False                |                               |

|              |                        |                                |                           |
|--------------|------------------------|--------------------------------|---------------------------|
|              | Fired                  | False                          |                           |
|              | Fired while Obstructed |                                |                           |
|              | Muzzle/Crown Condition | Slightly Worn; Functioning     |                           |
| Bolt         | Firing Pin             | Slightly Worn; Functioning     |                           |
|              | Shroud                 | Slightly Worn; Functioning     |                           |
|              | Face                   | Slightly Worn; Functioning     |                           |
|              | Handle                 | Worn; Functioning              |                           |
|              | Stop                   | Slightly Worn; Functioning     |                           |
| Extractor    | Condition              | Slightly Worn; Functioning     |                           |
|              | Cut Condition          | Slightly Worn; Functioning     |                           |
|              | Ext/Eject Test         | False                          |                           |
| Locking      | Block Condition        | ---Select---                   |                           |
|              | Lug Condition          | Slightly Worn; Functioning     |                           |
|              | Notch Condition        | ---Select---                   |                           |
| Overall      | Exterior Condition     | Worn; Functioning              |                           |
|              | Stock Condition        | Worn; Functioning              |                           |
|              | Fore End Condition     | ---Select---                   |                           |
| Receiver     | Condition              | Worn; Functioning              |                           |
|              | Bulged                 | False                          |                           |
| Safety       | Description            |                                | STANDARD M/600 SAFETY     |
|              | Function               | Slightly Worn; Functioning     |                           |
|              | Sub-Assembly           | Non-ISS                        |                           |
| Sear         | Lift                   | ---Select---                   | N/A                       |
|              | Notch                  | Like new; Functioning          |                           |
|              | Tests                  | Test Fired                     | False                     |
| Feeding Test |                        | False                          |                           |
| Trigger      | Condition              | Slightly Worn; Not Functioning | RUSTY,PARTS TRIG. BINDING |
|              | Pull                   | ---Select---                   | N/A                       |
|              | Altered                | False                          |                           |
|              | Sub-Assembly           | Other Remington                |                           |



Installing new Trigger  
Assembly at NLC.

RECEIVED  
FEB 11 2008  
BY: *[Signature]*




Mick Ham  
111 Jenkins  
Burnsville,  
1206

578-879-1

REMINGTON ARMS CO. INC  
870 REMINGTON DR  
PO BOX 700  
MADISON, NC 27025

TO WHOM IT MAY CONCERN,

MY MODEL 600 .308 HAS HAD  
A HISTORY OF FIRING w/o NOTICE. IT WAS REPAIRED  
PER REPAIR # RE 00050835 FOR A TRIGGER MECHANISM  
IN 2002. I HAVE SHOT THE GUN APPROXIMATELY  
10-20 TIMES SINCE. IN 2007, THE GUN  
FIRED WHILE REMOVING THE SAFETY. THANK  
GOODNESS THAT I AM A CONSCIOUS HUNTER  
AND DO NOT REMOVE THE SAFETY UNTIL  
POINTING IN A SAFE DIRECTION. NEEDLESS  
TO SAY, THE TARGET WAS MISSED. THIS GUN  
IS UNSAFE. PLEASE EITHER FIX FOR GOOD  
OR DESTROY.



Mick Hamlin

# Remington Arms Company, Inc.

870 Remington Dr. P.O. Box 700

Madison, NC 27025-0700

Parts/Repairs

800-243-9700

Fax

336-548-7801

[www.remington.com](http://www.remington.com) [info@remington.com](mailto:info@remington.com)

## REPAIR DOCUMENT

## REPAIR DOCUMENT

|                                                                              |                                    |                                                                               |
|------------------------------------------------------------------------------|------------------------------------|-------------------------------------------------------------------------------|
| Repair Order Number<br>RE00050835                                            | Description/Serial Number<br>77044 | Date Received - 8/29/2002                                                     |
| Account # - R-                                                               | Model 600 Center Fire Caliber: 308 | Estimate Date - 8/28/2002                                                     |
|                                                                              |                                    | Current Date - 9/20/2002                                                      |
| Customer<br>TAYLOR & VADNEY<br>3071 BROADWAY<br><br>SCHENECTADY, NY 12306 US |                                    | Return To<br>TAYLOR & VADNEY<br>3071 BROADWAY<br><br>SCHENECTADY, NY 12306 US |
| Phone (H) (518)-375-3030                                                     |                                    | Fax                                                                           |
| Phone (W)                                                                    |                                    | Email                                                                         |

| Reported |                                           | Problems |                                | Found |                                |
|----------|-------------------------------------------|----------|--------------------------------|-------|--------------------------------|
| M123     | FORWARD TO PRODUCT SERVICE FOR INSPECTION | M123     | FORWARD TO PRODUCT SERVICE FOR | M123  | FORWARD TO PRODUCT SERVICE FOR |
| M176     | RETURNED FOR RECALL/UPDATE                | M176     | RETURNED FOR RECALL UPDATE     | M176  | RETURNED FOR RECALL UPDATE     |
| M238     | CLEAN & INSPECT                           | M239     | REPLACE TRIGGER ASSEMBLY       | M239  | REPLACE TRIGGER ASSEMBLY       |

| Technician's Comments |                                                                           |
|-----------------------|---------------------------------------------------------------------------|
| Condition             | REC'D W/ CRACKED RIB.                                                     |
| Problem/Notes         | action/dirty trigger assemble never updated. replace trigger at no charge |

| Parts and Labor       |                               |          |                |
|-----------------------|-------------------------------|----------|----------------|
| Material #            | Material Description          | Quantity | Warranty (Y/N) |
| <b>Part</b>           |                               |          |                |
| F91469                | 600 TRIGGER ASSB              | 1        | Y              |
| <b>Part Total:</b>    |                               | 1        |                |
| <b>Service</b>        |                               |          |                |
| 4000104               | ARMS SERV SHIPPING & HANDLING | 0        | Y              |
| 4000118               | GR-CLEAN                      | 1        | Y              |
| 4000119               | GR-TEST                       | 1        | Y              |
| 4000294               | GR-CHECK TPA                  | 1        | Y              |
| <b>Service Total:</b> |                               | 3        |                |

**To Whom It May Concern:**

**Concerning the items coming in for Remington Arms Company, Inc.  
that show to be Arms Service or repair- these should be redirected to  
the following address:**

**Remington Arms Company Inc  
Arms Services  
14 Hoefler Avenue  
Ilion NY 13357**