Remington Arms Co., Inc. **Product Service**

Legal Case #:2047

Case In	formation
---------	-----------

RE# **Date Opened** Date Opened(PS) **Date Closed Incident Date** Pre Lit Lit Obsolete 140247 1/19/2008 1/21/2008 1/21/2008

Customer Information

Type **Business** First Name Last Name Street City Contact State Zip Age H 405-413-3866 215 West 15th Ave Reporter BJJackson Stillwater OK 74074 E bj.jackson@okstate.edu

Incident Information

Claims Codes Repair Est. Medical Treatment Medical Status

ΡI

PD Cause:4006 Altered Adjustments or Components Unknown fires on safe release Concern: 1007 Fired on Safe Release

C

1/23/08-correspondence from repair-gun goes off when safety is pushed forward. It has done it twice. Noticed recall, sending in for repair.lw

Firearm Information

Mfg. Model/Ga. SKU Bbl. DOM Type Serial Remington CF/BA 600/222 REM 20000 A6452597 KO 5/5/1977 **Date Purchased** Where Purchased Accessories **Original Owner** AMARILLO SPTG AMARILLO TX SCOPE BASE U

CONCERN:FSR

Ammunition Information - None Defined Other Products Information - None Defined Settlement

Remington/600/CF/BA

Cash Reim. Date Cash Date Settlement Release of Claims Release Date Reimbursement Settlement APV APV

Replace TA at n/c

Repair/Replacement Repair/Replacement Cost Date 35 1/23/2008

1/23/08-replace TA at n/c.lw

Examination[Remington/CF/BA]


Part	Sub-Part	Code	Comment
	Examiner		B.TRAVIS
	Exam Date		1/21/2008
	Product Type		RF
	Action Type		A
	Assigned To		F.SUPRY
Cause	4006	Altered Adjustments or Components	TRIG SET SCREWS ALTERED
<u></u>	Description		18.5" 222 REM
	Date Code		КО
Barrel	Bore Plugged	False	
	Bulged	False	

http://cps03ap13:200/psaapp/PrintDisplay.aspx?ID=2047&Type=Case

1/24/2008

	Fired	False	
	Fired while Obstructed		
	Muzzle/Crown Condition	Slightly Worn; Functioning	
	Firing Pin	Slightly Worn; Functioning	
	Shroud	Slightly Worn; Functioning	
Bolt	Face	Slightly Worn; Functioning	
	Handle	Slightly Worn; Functioning	
	Stop	Slightly Worn; Functioning	
	Condition	Slightly Worn; Functioning	
Extractor	Cut Condition	Slightly Worn; Functioning	
	Ext/Eject Test	False	
	Block Condition	Select	
Locking	Lug Condition	Slightly Worn; Functioning	
	Notch Condition	Select	
	Exterior Condition	Slightly Worn; Functioning	
Overall	Stock Condition	Slightly Worn; Functioning	SMALL CRACK IN F/E
	Fore End Condition	Select	
Dacaivar	Condition	Slightly Worn; Functioning	
Receiver	Bulged	False	
	Description		STANDARD M/600 BOLT LOCK SAFETY
Safety	Function	Like new; Functioning	
	Sub-Assembly	Non-ISS	
	Lift	Select	.010
Sear	Notch	Slightly Worn; Functioning	
	Tests	Test Fired	False
Feeding Test	Tests	False	
	Condition	Slightly Worn; Functioning	
Trigger	Pull	Select	2#
	Altered	True	SET SCREWS ALTERED
	Sub-Assembly	Other Remington	
Non-Remington Components	Description		SCOPE BASE

Arms Services Repair & Estimate System File : Add Repair : Estimate Repair : Expedite Repair : Inquiry : Repair Tools : CSR Tools : Reports : Table Maintenance : System Maintenance : (Help :)	<u>×</u> o≥
Serial: A6452597; Model-600 MDHAWK Center: Repairman Chuck Dekanek	
Verify Repair. Fire with 18 inch bariel Caliber, 222 Produced. Status Repairing 1/21/2008-12 45:06 PM Address Information.	A Comment of the Comm
Customer C Received From Return To C Received From Name B J JACKSON	Line Control of the C
Address 1: 215 WEST 15TH STREET 215 WEST 15TH STREET Address 2: P0 Box: P0 Box: STILLWATER P0 Box: STILLWATER State: OK Zip Code: 74074 County: US State: OK Zip Code: 74074 County: US	
Contact / Condition Problems Estimate History / Status Shipping // Billing	
Date User ID Desc1 Desc2 Shipping Hold Repairing 1/19/2008/4/6/4 brygidor Closed at Expedite 1/19/2008/4/6/4 brygidor Closed at Expedite 1/19/2008/5/05/1 ArmEm Repair Received BJJackson@okstate.edi 1/19/2008/5/05/1 ArmEm Receipt BJJackson@okstate.edi 1/21/2008/9/29/4 pencer Form Product Services To: Repair Bench Passed Inspection Form Product Services To: Repair Bench Passed Inspection Form Product Services Status: Parts Hold Received Repair Location Internal Received Parts Received Repair Location Form Product Services Status: Parts Hold Form Product Services Status: Parts Hold Form Product Services Form Pr	
Repair Search <u>Close</u>	
suppy 1/21/2008 1/31/PM CASS NUM. NS SCRIC	
Start Duncht Cases Altrosoft Out in Services Repair (2) Current Cases Altrosoft Excel PSHMS.	



2047



18,54 18,54

General Repair Form

Back to Repair Services

NOTE: Please complete and print this form, and then include it with your firearm

Model Number: Mo MJK 600	Serial Number: A 6452597			
Name: BJ Jackson	Date of Purchase: 1992			
Address (no PO Boxes): 215 West 15th Aur				
City: Still water	State: 01<	Zip: 74074		
Phone (Daytime): 405-413-3866	Fax:			
E-mail Address: BJ. Jackson Ookstate	e. edu			
Please describe your problem: Gun goes off when safety is Probled Forward. It's done it twice since I have cured it. I noted the recall on this while problems the gun. Though it fixed please and but back together. Though, BJ Jackson				
500 characters left				
NOTE: Prior to shipping your firearm, contact the Repair Center for services provided and estimated repair time.				
① WARNING: DO NOT SEND LIVE OR SPENT SHELLS IN YOUR FIREARM OR IN THE SAME BOX WITH THE FIREARM. THIS IS A VIOLATION OF FEDERAL LAW. IF YOU FEEL YOU MUST SEND SPENT SHELLS PLEASE SEND THEM IN A SEPARATE PACKAGE AND INCLUDE NAME, ADDRESS (WITH ZIP CODE), TELEPHONE AND MODEL AND SERIAL NUMBER OF YOUR FIREARM.				
 :: Record the serial number of your firearm before sending it. :: Pack your firearm for safety and to prevent further damage in shipping and handling. Preferably, ship in a firearm box. (Note: Original boxes may not be returned.) :: Remove all accessories from your firearm to prevent loss or damage. :: Ship your ENSURED firearm by either UPS or Parcel Post. Remington is not responsible for damage or loss during shipment, so you may elect to purchase insurance from your carrier. 				



Visit Our Other Remington Websites
Other Sites

replace TOA under TREG. ASSIN Necroll At M/C. TRIG. Set SCHOWS ACTERED