

Remington Arms Co., Inc.
Product Service
Legal Case #:2433

Case Information

RE#	Date Opened	Date Opened(PS)	Date Closed	Incident Date	Pre Lit	Lit	Obsolete
145457	5/30/2008	6/2/2008	6/2/2008				

Customer Information

Type	Business	First Name	Last Name	Street	City	State	Zip	Age	Contact
Reporter		Larry	Six	313 Walters Rd	New Alexandria	PA	15670		H 724-468-0070

Incident Information

Claims	Codes	Repair Est.	Medical Treatment	Medical Status
PI				
PD	Cause:4038	Could Not Duplicate Concern		
S	fires on safe release	Concern:1007 Fired on Safe Release	Unknown	
C				

6/3/08-correspondence from repair-sending in for recall. gun may discharge when you take safety off. Handle had broken off bolt. lw

Firearm Information

Mfg.	Type	Model/Ga.	SKU	Serial	Bbl.	DOM
Remington	CF/BA	600/243 WIN		76012	DN	9/1/1966
Date Purchased	Where Purchased	Accessories	Original Owner			
			U			

CONCERN:FSR,HANDLE BROKE OFF BOLT

Ammunition Information - None Defined

Other Products Information - None Defined

Settlement

Remington/600/CF/BA

Settlement	Release of Claims	Release Date	Reimbursement	Cash Settlement	Reim. Date APV	Cash Date APV
Replace TA under SMP						
	Repair/Replacement Cost	Repair/Replacement Date				

6/3/08-quote sent to replace ta under smp. rifle had been updated.lw

Examination[Remington/CF/BA]

Part	Sub-Part	Code	Comment
Examination	Examiner		B.TRAVIS
	Exam Date		6/2/2008
	Product Type		RF
	Action Type		A
	Assigned To		F.SUPRY
Cause	4038	Could Not Duplicate Concern	
Barrel	Description		18.5" 243 WIN
	Date Code		DN
	Bore Plugged	False	
	Bulged	False	
	Fired	False	
	Fired while Obstructed		

	Muzzle/Crown Condition	Worn; Functioning	
Bolt	Firing Pin	Slightly Worn; Functioning	
	Shroud	Slightly Worn; Functioning	
	Face	Slightly Worn; Functioning	
	Handle	Abused; Not Functioning	BROKEN
	Stop	Slightly Worn; Functioning	
Extractor	Condition	Slightly Worn; Functioning	
	Cut Condition	Slightly Worn; Functioning	
	Ext/Eject Test	False	
Locking	Block Condition	---Select---	
	Lug Condition	Slightly Worn; Functioning	
	Notch Condition	---Select---	
Overall	Exterior Condition	Worn; Not Functioning	
	Stock Condition	Worn; Functioning	
	Fore End Condition	---Select---	
Receiver	Condition	Slightly Worn; Functioning	
	Bulged	False	
Safety	Description		STANDARD M/600 BOLT LOCK SAFETY
	Function	Like new; Functioning	
Sear	Lift	---Select---	.012
	Notch	Slightly Worn; Functioning	
	Tests	Test Fired	False
Feeding Test		False	
Trigger	Condition	Slightly Worn; Functioning	
	Pull	---Select---	N/A
	Altered	False	
	Sub-Assembly	Other Remington	

2433

DN 9/66
18.5"
.012

Remington

Factory Repair Instructions

(NOTE: Please print and complete this form, and then include it with your firearm.)

Model Number: 600		Serial Number: 76012	
Are you the original owner?: ☒ YES ☐ NO			
Name: LARRY G SIX		Date of Purchase:	
Address (no PO Boxes): 313 WALTERS RD			
City: NEW ALEXANDRIA		State: PA	Zip: 15670
Phone (Daytime): 724-468-0070		Fax:	
E-mail Address:			
☐ I would like to receive future e-mail updates from Remington.			
Please describe your problem: Recall, may discharge when you TAKE SAFETY OFF. Handle had BROKE off BOLT part find now is you have new bolt let me know Found bolt just needs repaired			
Ammunition Information:			
Manufacturer:		Type:	
Powder Weight:			
Primer Used:			
Reloader Used:			
How often do you clean the bore? (Months or Number of rounds)			
How often do you clean the action? (Months or Number of rounds)			
How often do you clean the trigger assembly? (Months or Number of rounds)			
Brand of lubricant used:			

Number:

76012

Model: 600



RE00145457

TPA HAS BEEN updated. could NOT
Duplicate concern BOLT HANDLE BROKE
Replace TPA under bolt local program for
\$20.00, Quote to repair BOLT

DL 9/23
C#
18.5#
v013

Arms Services Repair & Estimate System

Add Repair

Estimate Repair

Expedite Repair

Inquiry

Repair Tools

CSR Tools

Reports

Table Maintenance

System Maintenance

Help

Repair Inquiry

Repair Number: RE00145457

Serial: 76012 Model 500 Center Fire Caliber 243 WIN

Repairman:

Status: New 5/30/2008 9:39:58 AM

Verify Repair

Address Information

Customer:

Received From:

Return To:

Received From:

Name: LARRY G SIX

LARRY G SIX

Address 1: 313 WALTERS ROAD

313 WALTERS ROAD

Address 2:

PO Box:

City: NEW ALEXANDRIA

NEW ALEXANDRIA

State: PA Zip Code: 15670 Country: US

State: PA Zip Code: 15670 Country: US

FEL:

Contact / Condition

Problems

Estimate

History / Status

Shipping / Billing

Date	User ID	Desc1	Desc2
5/13/2008 11:34	valentds	Repair Added	
5/30/2008 9:34:4	valentds	Repair information change	
5/30/2008 9:39:5	valentds	Repair information change	
5/30/2008 9:40:1	valentds	From: Check In	To:
6/2/2008 8:47:27	supryfl	Returned to AS for repair	Bolt Lock Modification Program

Shipping Hold

InterFace Hold

Estimate Sent

Parts Received

Passed Inspection

Return As Received

Has been Approved

Internal Repair

Current Status

New

5/30/2008 9:39:58 AM

valentds

Product Services

Repair Location

ILN

Current Location

ILN

Transfer Number

Repair Search

Refresh

Close

supryfl

6/2/2008

8:47 AM

CAPS

NUM

INS

SCRL

Ustart

Inbox - Microsoft Outlook

Arms Services Repair

Start

PS 10470