Remington Arms Co., Inc. Product Service Legal Case #:2209

Case Information

RE# Date Opened Date Opened(PS) Date Closed Incident Date Pre Lit Lit Obsolete 142514 3/5/2008 3/6/2008 3/6/2008

Customer Information

First Name **Last Name** Street Age Contact Type **Business** City State Zip H 480-893-3339 3805 E Equestrian Trail 85044 Reporter James Wilcox Phoenix W 602-370-7201

Incident Information

Claims Codes Repair Est. Medical Treatment Medical Status

PΙ

PD Cause:4038 Could Not Duplicate Concern
S sending in for recall Concern:1008 Fired on Bolt Closing

Unknown

S sending in for recall C

3/7/08-correspondence from repair-sending in for recall. Occasionally discharges as the bolt is being closed.lw

Firearm Information

Mfg.TypeModel/Ga.SKUSerialBbl.DOMRemingtonCF/BA600/350 REM MA61069AN3/1/1966

Date Purchased Where Purchased Accessories Original Owner

U

CONCERN:FBC

Ammunition Information - None Defined
Other Products Information - None Defined

Settlement

Remington/600/CF/BA

Settlement Release of Claims Release Date Reimbursement Cash Reim. Date Cash Date Settlement APV APV

Replace TA at

n/c

Repair/Replacement
Cost
Solution
35
Repair/Replacement
Date
37/7/2008

3/7/08-replacing TA at n/c. Cust sent in check, checking w/ AR to reimburse customer.lw

Examination[Remington/CF/BA]

Part	Sub-Part	Code	Comment
Examination	Examiner		B.TRAVIS
	Exam Date		3/6/2008
	Product Type		RF
	Action Type		A
	Assigned To		F.SUPRY
Cause	4038	Could Not Duplicate Concern	HAS NOT BEEN UPDATED
Barrel	Description		19" 350 REM MAG
	Date Code		AN
	Bore Plugged	False	
	Bulged	False	
	Fired	False	
	Fired	False	

http://cps03ap13:200/psaapp/PrintDisplay.aspx?ID=2209&Type=Case

3/10/2008

	Fired while Obstructed		
	Muzzle/Crown Condition	Slightly Worn; Functioning	
Bolt	Firing Pin	Slightly Worn; Functioning	
	Shroud	Slightly Worn; Functioning	
	Face	Slightly Worn; Functioning	
	Handle	Slightly Worn; Functioning	
	Stop	Slightly Worn; Functioning	
Extractor	Condition	Slightly Worn; Functioning	
	Cut Condition	Slightly Worn; Functioning	
	Ext/Eject Test	False	
	Block Condition	Select	
Locking	Lug Condition	Slightly Worn; Functioning	
	Notch Condition	Select	
	Exterior Condition	Slightly Worn; Functioning	
Overall	Stock Condition	Slightly Worn; Functioning	
	Fore End Condition	Select	
Receiver	Condition	Slightly Worn; Functioning	
	Bulged	False	
Safety	Description		STANDARD M/600 BOLT LOCK SAFETY
	Function	Like new; Functioning	
Sear	Lift	Select	.005
	Notch	Slightly Worn; Functioning	O/S DOUBLE SEAR
	Tests	Test Fired	False
Feeding Test		False	
Trigger	Condition	Slightly Worn; Functioning	O/S NOT UPDATED
	Pull	Select	4#
	Altered	False	
	Sub-Assembly	Other Remington	

Fig. Arms, Services, Repails & Estimate System File: Add Repair .: Estimate Repair: Expedite Repair: Cinquiry: - Repair Tools: CSR Tools: SReports: Table Maintenance System Maintenance. Help	XGE
Repair Inquiry	
Repair Number: RE00142514 Serial: 61069 Model 600 Center Fire Caliber: 350 Repairment Repairment Verify Repair Status: New 3/5/2008 8:51:58 AM	
Address Information Customer C	
State: PZ Zip Code: 85044 Country: US State: PZ Zip Code: 85044 Country: US FFL FFL FFL FFL FFL FFL FFL FFL FFL FF	
Repair Search Close	
supyll 3/6/2008 10.01/AM EAES NUM INS SCRL #FSERT OphboxAlicosofkOuth Amis Service Repetate 科特Bibliografs 《Keurenisesse Alicowal)	(JPE Jacayam

LAURA,
The check should be returned to
the customer - this rifle falls under
the n/c m/600 update procedure.

Fred

James J Wilcox 3805 E Equestrian Trail Phoenix, AZ 85044-3008 480-893-3339 602-370-7201

February 20, 2008



Remington Arms Company, Inc Attention: Arms Services 14 Hoefler Ave

ILION, N.Y. 13557

Enclosed please find Model 600 Magnum, 350 caliber rifle, Serial Number 61060. This firearm has a Model 600 magnum recall associated with it. The problem is that it occasionally discharges as the bolt is being closed, and before it is fully engaged.

Please find a check for repair and shipping charges for \$32.00 enclosed.

If you have any questions, please contact me at:

Day time

602-470-2737

Evening

480-893-3426

Cell

602-370-7201

Please return to:

Jim Wilcox


3805 E. Equestrian Trail

Phoenix, Arizona 85044

could not duplicate concern. replace TPA, checks one r, chen under TNEG. ASSIM RECALL AT N/C

230145

Sincerely,





March 10, 2008

James Wilcox 3805 E Equestrian Trail Phoenix, AZ 85044

Subject: Model 600 Serial #61060

Repair: 142514

Dear Mr. Wilcox,

We received your rifle and check for \$32.00 to cover the cost of the repair. We are returning your check to you as we have covered your repair under warranty and there is no charge to you. Your firearm should be completed shortly and shipped back to you via UPS.

We appreciate you giving us the opportunity to be of service to you and we hope that our actions will keep you as a loyal Remington customer.

Sincerely,

Laura Watson

Consumer Affairs Administrator Remington Arms Company

Phone: 800-243-9700 ext 8789

Fax: 336-548-7890

E-mail: laura.watson@remington.com