

Remington Arms Co., Inc.
Product Service
Legal Case #:2131

Case Information

RE#	Date Opened	Date Opened(PS)	Date Closed	Incident Date	Pre Lit	Lit	Obsolete
140931	2/11/2008	2/12/2008	2/12/2008				

Customer Information

Type	Business	First Name	Last Name	Street	City	State	Zip	Age	Contact
Reporter	Longacres	Longacres		365 Fulwiler Rd	Abilene	TX	79603		W 325-672-9521

Incident Information

Claims	Codes	Repair Est.	Medical Treatment	Medical Status
PI				
PD	Cause:4038 Could Not Duplicate Concern		Unknown	
S	Fires when bolt handle is dropped Concern:1008 Fired on Bolt Closing			
C				

2/13/08-correspondence from repair-sending in for trigger recall. fires when bolt handle is dropped.lw

Firearm Information

Mfg.	Type	Model/Ga.	SKU	Serial	Bbl.	DOM
Remington	CF/BA	660/350 REM MA		119858	OR	7/1/1968
Date Purchased	Where Purchased	Accessories	Original Owner			
		SCOPE BASE	U			

CONCERN:FBC

Ammunition Information - None Defined

Other Products Information - None Defined

Settlement

Settlement	Release of Claims	Release Date	Reimbursement	Cash Settlement	Reim. Date APV	Cash Date APV
Replace TA at n/c						
	Repair/Replacement Cost	Repair/Replacement Date				
	35	2/13/2008				

2/13/08-Replace TA at n/c under recall.lw

Examination[Remington/CF/BA]

Part	Sub-Part	Code	Comment
Examination	Examiner		B.TRAVIS
	Exam Date		2/12/2008
	Product Type		RF
	Action Type		A
	Assigned To		F.SUPRY
Cause	4038	Could Not Duplicate Concern	TRIG ASSM HAS A STICKY LUBRICATION RESIDUE
Barrel	Description		20" 350 REM MAG
	Date Code		OR
	Bore Plugged	False	
	Bulged	False	
	Fired	False	

	Fired while Obstructed		
	Muzzle/Crown Condition	Slightly Worn; Functioning	
Bolt	Firing Pin	Slightly Worn; Functioning	
	Shroud	Slightly Worn; Functioning	
	Face	Worn; Functioning	
	Handle	Slightly Worn; Functioning	
	Stop	Slightly Worn; Functioning	
Extractor	Condition	Slightly Worn; Functioning	
	Cut Condition	Slightly Worn; Functioning	
	Ext/Eject Test	False	
Locking	Block Condition	---Select---	
	Lug Condition	Slightly Worn; Functioning	
	Notch Condition	---Select---	
Overall	Exterior Condition	Slightly Worn; Functioning	
	Stock Condition	Slightly Worn; Functioning	
	Fore End Condition	---Select---	
Receiver	Condition	Slightly Worn; Functioning	
	Bulged	False	
Safety	Description		STANDARD M/660 BOLT LOCK SAFETY
	Function	Like new; Functioning	
Sear	Lift	---Select---	.009
	Notch	Like new; Functioning	
	Tests	Test Fired	False
Feeding Test		False	
Trigger	Condition	Slightly Worn; Functioning	DIRTY/STICKY
	Pull	---Select---	4#
	Altered	False	
	Sub-Assembly	Other Remington	
Non-Remington Components	Description		SCOPE BASE

RECEIVED
FEB 13 2008
BY: *[Signature]*



Made in U.S.A.

(325)

672-9521

REPAIR TAG

No. 0613 Date 1-23-08

Owner Longone's Inc

Address 358 Chestnut

Promised Abilene TX 79602

REPAIRS	CHARGES
Trigger Recoil ?	
Fires when Bolt Andk is Dropped	
AMT. DUE	

No. 0613 Promised

CLAIM CHECK

NO WORK DELIVERED WITHOUT THIS CHECK

Serial Number:

119858

Model: 660



RE00140931

2131

4#
OR 7/68
.009
20"

could not duplicate concern.
Trigger Assm. has a partially dried
& sticky residue causing parts
to work sluggish. Replace
TRA, check over, clean under
1979 recall. AT N/C

#230145