
Remington Arms Co., Inc. Product Service Legal Case #:4220

				Legal Case	e#:4220						
Case Infor	mation										
RE#		Opened	Date Opened(e Closed	Incide	ent Date	Pre	Lit l	Lit	Obsolete
185353		/2010	1/11/2010	1/1	11/2010						
	Information	First Name	I4 M	Storest	C:+	C4-4-	7:- A		(Contac	
Туре	Business	First Name	Last Name	Street	City	State	-	ge	_	.ontac 4-692-	-
Reporter		Keith & Justin	Barr	16 Lutz Lane	Port Matilda	PA	16870	E			inters.com
Incident In	ıformation										
	Claims			Codes			Repair Est.		dical tment		Medical Status
ΡΙ							234				
PD		Cause:4	015 Improper	r Maintenance							
S		Concern	11025 Unexpla	ined Discharge - I	No Mention of			Unk	nown		
('	ent off while	e concer.	Safety Po	osition							
unload	•	our renair form -	He was hunting	and gun would n	ot on on Safe I	Inloade	d aun-then a	oun went	on Safa	Los	ded gun
				e gun & it went o		, invade	a gan-mon g	San Wont	JII Guile	<u>L</u> ou	5411
Firearm In	formation										
Mfg		Tv	pe	Model/G	a. SI	ai .	Serial	Bbl.		DO	M
Remin	_	CF/	_	700/300 SA		124			9/26/2		:10:42 AN
Date Pur	chased	Where P	urchased	Accessor	ies Origina	l Owne	r				
	· ·	ERRY S SPORT		T	Ţ	J					
CONCER	N:FIRED W	HILE UNLOAD	ING 				····				
Ammunitio	on Informati	on ·									
Mi		T	ype	Cal./	Ga.	SKU	UPC	DOM	1	Mfg	g. Code
Remir			t PSP/65 gr	300 SA		*				PR3	00SM2
Conc		O	ther	Facto	•	eload					
0	•			Υ		N			-1		
Other Prod	lucts Informa	ation - None Defi	ned								
Settlement											
				Remington/70	00/CF/BA						
Settlei	ment	Release of Cla	aims	Release Date	Reimbur	sement	Cas Settlen		Reim. I APV		Cash Dat APV
Repair (Settlen	ient	ALV		AFV
J		epair/Replacem	ent Cost Repa	ir/Replacement l	Date						
		\$47.23		1/14/2010							
		Could not duplica o charge - goodw		ger & trigger pin	rusted, trigger v	vorks sl	uggish. Rep	lace trig	ger asse	mbly,	check ove
Examination	on[Remingto	n/CF/BA]									
II Too.se4	11	Sub_Part	II .	Code	II .		C^.	mmant			

Part	Sub-Part	Code	Comment	
	Examiner		B.TRAVIS	
	Exam Date		1/11/2010	
Examination	Product Type		RF	
	Action Type		A	
	Assigned To		F.SUPRY	· · · · · · · · · · · · · · · · · · ·
Cause	4015	Improper Maintenance		

	Description		24" 300 SAUM
	Date Code	1	DW
	Bore Plugged	False	
Barrel	Bulged	False	Ī
}	Fired	False	
	Fired while Obstructed		
	Muzzle/Crown Condition	Slightly Worn; Functioning	7
	Firing Pin	Slightly Worn; Functioning	
	Shroud	Slightly Worn; Functioning	
Bolt	Face	Slightly Worn; Functioning	
ļ	Handle	Slightly Worn; Functioning	
	Stop	Slightly Worn; Functioning	WORKS SLUGGISH
	Condition	Slightly Worn; Functioning	
Extractor	Cut Condition	Slightly Worn; Functioning	
[Ext/Eject Test	False	
	Block Condition	Select	
Locking	Lug Condition	Slightly Worn; Functioning	
	Notch Condition	Select	
	Exterior Condition	Slightly Worn; Functioning	
Overall	Stock Condition	Slightly Worn; Functioning	
	Fore End Condition	Select	
Descione	Condition	Slightly Worn; Functioning	
Receiver	Bulged	False	
	Description		STANDARD M/700 SAFETY
Safety	Function	Like new; Functioning	
	Sub-Assembly	ISS	
	Lift	Select	.011
Sear	Notch	Like new; Functioning	
	Tests	Test Fired	False
Feeding Test	lests	False	
	Condition	Slightly Worn; Functioning	TRIG AND PIN RUSTED TRIG WORKS SLUGGISH
Tuinner	Pull	Select	8.5#
Trigger	Altered	False	
1	Sub-Assembly	M/700 Non-Bolt Lock]

lepair Inquiry	APPENDENT	September 1995	87 S.O. (1975)	nance System Mainte			
epair Number RE00185353 S	eriak G6279665 Model 700 (ch barrel Caliber: 300 REM S	Center Fire with 24 Repairm	en Bruce Trav	is and the second			
enty Repair P	oduced: 09/26/2002	State	us: Repairing 1/11/2010	10:52:03 AM			
dress Information Customer	Received From	Return To:	4 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	eived From	Here a group of		100
Name: KEITH BARR / JUSTIN BAR dress 1: 116 LUTZ LANE	R - 12 State to the transport er	KEITH BARR / JU:	STIN BARR		100		10 5 0
tess 2 City PORT MATILDA	P0 8ox [PORT MATILDA	PO Box			relative to	
State: IPA Zip Code: 16870	Country: US	State: PA Zip Code: 168	70 Country	JS .			123.75
		MITHH					
Contact / Condition Proble	ems Est	imale History		ng/Billing			付付 [4]
		esc2 F-s		it Status pairing		14.53	
	Repair Added From: Check In T	U	nterFace Hold 1/11/2010	0 10:52:03 AM ystem			
1/8/2010 12:05:0 EmailSenk ArmEmail 1/8/2010 12:05:1 EmailVerifie ArmEmail			Surrate Seria Repa	air Bench			
		takuer ParteHold	assed Inspection	r Location ILN	d parenger		
	Immediate SAP Allocatio			t Location ILN			
41 8 8 1		CONTRACTOR	nternal Repair Transf	er Number	A Charles San	the state of the state of	4.4
	All angents and in our California	<u>)</u> 71	nternal Repair Transf	er Number			
Repair Search		Tal	nternal Repair Transf	<u>Close</u>			
 		2 F:	rternal Hepati	Providence (Co.)			
 	and dispersion		rternal Hepati	Providence (Co.)			
 		J F.	rternal Hepati	Providence (Co.)			
- The state of th			rternal Hepati	Providence (Co.)			
- The state of th			rternal Hepati	Providence (Co.)			
- To to t a a a constituent de la constituent d	agenta at time and the second		rternal Hepati	Providence (Co.)			
- To to t a a a constituent de la constituent d			rternal Hepati	Providence (Co.)			
- The state of th			rternal Hepati	Providental Control			
- The state of th			rternal Hepati	Providental Control			
 			rternal Hepati	Providental Control			
- The state of th			rternal Hepati	Providental Control			
 			rternal Hepati	Providental Control			
	agendarii me edit me e		rternal Hepati	Providental Control			



Cs 1.7.10

L

4220

Remington

Factory Repair Instructions

•	NOTE: Please	 	 111	. 1 1 14	 	

Model Number: 700	Serial Number: 66279665	
Are you the original owner?: XYES NO		
Name: REITHL. BARR / JUSTEN BARR	Date of Purchase: 2003	
Address (no PO Boxes): 16 Lutz Lut		i
		•
city: Part Matilda	State: Pa. Zip: 16870	
Phone (Daytime): -814-883-6351	EART ENMIS KETTHE THE PRINTER	5.com
E-mail Address: Home . 814-692-5351	′	
would like to receive future e-mail updates from R	temington. Sarb	I
Please describe your problem: went hun.	Ling in morning, Shot at deep	~
"MESTED." DUT HOOTHER ROLLA	d'in aun franted the mes	100 the
GUN Would Not 9	ODN SAFE (UNLoaded of	en. Then.
	loaded our Again huntil	
Rest of the day. Game	e pack to camp west	to unboad
gan. E gun, went off	. Why: OSTIONS - give me	1714
MONEY BOCK OR REPLACE	it. I know that if you	
the same and hock to		- ₹
Ammunition Information:		->
Manufacturer: Regulator Folk	Type: 300 Repuring to SA WHER III	ત <i>વ</i>
Other (i.e. bullet weight/type, shot size, powder):	165-GR: CORE,-LOKT PSP	
PR 300 SM Z		
Handload Information:	I (I do not Reload)	
Powder Used:	Powder Weight:	
Case/Hull Used:	Primer Used:	\$ ·
Bullet Type/Shot Size:	Reloader Used:	•
Firearms Care (Cleaning and Lubrication):		
Brand of cleaning solution used: Him 17/1	<u></u>	
How often do you clean the bore? (Months or Number of	rounds) - EVERY FrAGE LEE USE IL	•
How often do you clean the action? (Months or Number of		Divinia,
How often do you clean the trigger assembly? (Months o		it.
	7	-
Brand of lubricant used: Howait		

PS 10557

and the state of t	
How often do you lubricate the bore? (Months or Number of rounds) - This GUN 15 ON. #3 Box C	of Shelt
How often do you lubricate the action? (Months or Number of rounds) ERERY time I used it	
How often do you lubricate the trigger assembly? (Months or Number of rounds) Every fine We user	it.
新维斯斯·斯斯特斯斯·斯斯斯斯·斯斯斯斯斯斯斯斯斯斯斯斯斯斯斯斯斯斯斯斯斯斯斯斯	
Have you reviewed the cleaning and maintenance recommendations on our web site or in our owners manual? YES YES YES	
Comments: I am, 56 YEARS OK- NEVER have I EVER had a proble	in
Like this! I have other Remington dun's & NIEVER a DRABIUM	
When was the last time that your firearm was serviced by a Remington authorized repairman/gunsmith? - Na o Hick	12 GUNS
What were the services performed? NEVER had to go & have Services - do to the	7
This is only the third box of Shells If crou have Questions	- 1
Call1-814-883-5351-1-814-692-5351 Keith L Back.	
Ship your INSURED firearm by either UPS or Parcel Post to:	
REMINGTON ARMS CO., INC	
ATTN: Arms Service Divison	
14 Hoefler Ave	
Ilion, NY 13357	
N YOUR FIREARM OR IN THE SAME BOX WITH THE IF YOU FEEL YOU MUST SEND SPENT SHELLS PLEASE	

ME, ADDRESS (WITH ZIP CODE), TELEPHONE AND -

mage in shipping and handling. Preferably, was the second oss or damage.....

le the box. Shipments without a proper

st. Remington is not responsible for... purchase insurance from your carrier.

Charge repairs will be processed using the following guidelines: Not service

:: Repairs \$75.00 and under will be completed and returned to you C.O.D. (To avoid C.O.D. Charges, please

:: For Repairs over \$75.00, you will receive a written estimate detailing the nature of the repair, applicable taxes and shipping. You will have 30 days to approve the repair estimate. Repairs can be paid by check, money order, or credit card (American Express, Discover, MasterCard, or VISA). If you wish, you can expedite repairs over \$75.00 by setting a pre-authorized amount that can be billed to your credit card.

could not duplicate concern.
Thig + Thig. PIW Musted Thig.
works Sluggish hyphacipal,
chech overly clear AT M/C.
Function tist.

230145