

Remington Arms Co., Inc.
Product Service
Legal Case #:4267

Case Information

RE#	Date Opened	Date Opened(PS)	Date Closed	Incident Date	Pre Lit	Lit	Obsolete
186156	1/13/2010	1/21/2010	1/21/2010				

Customer Information

Type	Business	First Name	Last Name	Street	City	State	Zip	Age	Contact
Reporter	Martin's True Value		Martin's True V	4215 McMasters Ave	Hannibal	MO	63401		
Incident		David	Carr	11176 Hwy O	Hannibal	MO	63401		

Incident Information

Claims	Codes	Repair Est.	Medical Treatment	Medical Status
PI				
PD				
S	fired on safety release	Cause:4038 Could Not Duplicate Concern Concern:1007 Fired on Safe Release	Unknown	
C				

1/28/10 Per letter with rifle, he sent the rifle several years ago for the same problem of firing on safe release. He has not shot it much since then. On Jan 5th he went to sight it in and fired a .270 round and went to fire another and when he took the rifle off safety it fired on it's own.cm

Firearm Information

Mfg.	Type	Model/Ga.	SKU	Serial	Bbl.	DOM
Remington	CF/BA	700/270 WIN	20000	6597912	RR	11/1/1968
Date Purchased	Where Purchased	Accessories	Original Owner			
	SOUTHRN GN DISTR MIAMI FL		U			
CONCERN:FSR						

Ammunition Information - None Defined

Other Products Information - None Defined

Settlement

Remington/700/CF/BA

Settlement	Release of Claims	Release Date	Reimbursement	Cash Settlement	Reim. Date APV	Cash Date APV
------------	-------------------	--------------	---------------	-----------------	----------------	---------------

Per Ilion inspect/decision,
replace TPA, clean at n/c.

Repair/Replacement Cost	Repair/Replacement Date
75.64	1/28/2010

1/28/10 Per Ilion, could not duplicate concern. Trig assm updated 6/02. Trig return sluggish, rusty. Replace TPA, check over, clean at n/c.cm

Examination[Remington/CF/BA]

Part	Sub-Part	Code	Comment
Examination	Examiner		B.TRAVIS
	Exam Date		1/21/2010
	Product Type		RF

	Action Type		A
	Assigned To		F.SUPRY
Cause	4038	Could Not Duplicate Concern	
Barrel	Description		22" 270 WIN
	Date Code		RR
	Bore Plugged	False	
	Bulged	False	
	Fired	False	
	Fired while Obstructed		
	Muzzle/Crown Condition	Slightly Worn; Functioning	
Bolt	Firing Pin	Slightly Worn; Functioning	
	Shroud	Slightly Worn; Functioning	
	Face	Worn; Functioning	
	Handle	Slightly Worn; Functioning	
	Stop	Slightly Worn; Functioning	
Extractor	Condition	Slightly Worn; Functioning	
	Cut Condition	Slightly Worn; Functioning	
	Ext/Eject Test	False	
Locking	Block Condition	---Select---	
	Lug Condition	Slightly Worn; Functioning	
	Notch Condition	---Select---	
Overall	Exterior Condition	Slightly Worn; Functioning	
	Stock Condition	Slightly Worn; Functioning	
	Fore End Condition	---Select---	
Receiver	Condition	Slightly Worn; Functioning	
	Bulged	False	
Safety	Description		STANDARD M/700 SAFETY
	Function	Like new; Functioning	
	Sub-Assembly	Non-ISS	
Sear	Lift	---Select---	.010
	Notch	Like new; Functioning	
	Tests	Test Fired	False
Feeding Test		False	
Trigger	Condition	Like new; Functioning	
	Pull	---Select---	6#
	Altered	False	
	Sub-Assembly	M/700 Non-Bolt Lock	

start | Windows | Home Services | 11:31 AM

$$\begin{array}{r} 27 \\ 33.64 \\ 15. \\ \hline 75.64 \end{array}$$

RECEIVED
JAN 25 2010

BY: _____

Serial Number:

6597912

Model: 700



RE00186156

could not duplicate concern.
TRIQ. ASSM. updated 6/02.
TRIQ. returns sluggish, rusty.
replace TPA, check over, clean
OT N/C
#230145

1/6/10

Dear Sirs,

22"
R711/6K
G#1
010

Per instructions from customer service I am sending this rifle to you for repair.

Several years ago there was a recall on Rem 700 Rifles because they were firing when you took the rifle off safety. I was hunting and I took my rifle off safety and it fired on its own. I ejected the shell and chambered another round and it went off as soon as the bolt closed. I

I sent it to Rem and they repaired the recall item. This is my deer hunting rifle so I only shoot it during firearms deer season. I have not shot it much since the repair was made.

On January 5th I went to sight it in for 100 grain bullets because I was putting a scope put on my 22.250 and I was going to use the .270 for Coyotes in the interim. I fired the .270 one time and checked my shot. I adjusted my scope for the needed correction. When I went to shoot again and took the rifle off safety it fired on its own. It gave me the same sick feeling I had several years ago.

I told my friend who is a benchrest shooter. We went out yesterday so he could see what I was telling him and it did it again.

I am glad about one thing. I was by myself at the shooting range. and my friend was standing behind me yesterday I believe you can make my rifle right because apparently it was only a bandaid repair before. Thank you in advance for your time and consideration.

David Lynn@localnet.com

DAVID CARR
11176 Highway 0
HANNING, MO. 63401
localnet.com