

Remington Arms Co., Inc.
Product Service
Legal Case #:4266

Case Information

RE#	Date Opened	Date Opened(PS)	Date Closed	Incident Date	Pre Lit	Lit	Obsolete
186228	1/14/2010	1/21/2010	1/21/2010				

Customer Information

Type	Business	First Name	Last Name	Street	City	State	Zip	Age	Contact
Incident		Danny	Clark	571 County Rd 46	Florence	AL	35634		H 256-767-4924

Incident Information

Claims	Codes	Repair Est.	Medical Treatment	Medical Status
PI				
PD				
S	Cause:4006	Altered Adjustments or Components	Unknown	
	Concern:1007	Fired on Safe Release		
C				
1/28/10 Per note with rifle, sometimes the gun will fire when the safety is taken off.cm				

Firearm Information

Mfg.	Type	Model/Ga.	SKU	Serial	Bbl.	DOM
Remington	CF/BA	700/308 WIN	25745	C6532290	DK	9/25/1990
Date Purchased	Where Purchased	Accessories	Original Owner			
	HORTON DIST. CO. INC. *	SCOPE,RINGS,BASE,BIPOD	U			
	LEW					

CONCERN:FSR

Ammunition Information - None Defined

Other Products Information - None Defined

Settlement

Remington/700/CF/BA

Settlement	Release of Claims	Release Date	Reimbursement	Cash Settlement	Reim. Date APV	Cash Date APV
Per Ilion inspect/decision, replace TPA, clean at 1/2 normal charges						
	Repair/Replacement Cost	Repair/Replacement Date				
	75.64	1/28/2010				

1/28/10 Per Ilion, trigger set screws altered. Will follow down. Replace TPA, check over, clean at 1/2 normal charges.cm

Examination[Remington/CF/BA]

Part	Sub-Part	Code	Comment
Examination	Examiner		B.TRAVIS
	Exam Date		1/21/2010
	Product Type		RF

	Action Type		A
	Assigned To		F.SUPRY
Cause	4006	Altered Adjustments or Components	
Barrel	Description		24" 308 HB
	Date Code		DK
	Bore Plugged	False	
	Bulged	False	
	Fired	False	
	Fired while Obstructed		
	Muzzle/Crown Condition	Slightly Worn; Functioning	
Bolt	Firing Pin	Slightly Worn; Functioning	
	Shroud	Slightly Worn; Functioning	
	Face	Slightly Worn; Functioning	
	Handle	Slightly Worn; Functioning	
	Stop	Slightly Worn; Functioning	
Extractor	Condition	Slightly Worn; Functioning	
	Cut Condition	Slightly Worn; Functioning	
	Ext/Eject Test	False	
Locking	Block Condition	---Select---	
	Lug Condition	Slightly Worn; Functioning	
	Notch Condition	---Select---	
Overall	Exterior Condition	Slightly Worn; Functioning	
	Stock Condition	Slightly Worn; Functioning	
	Fore End Condition	---Select---	
Receiver	Condition	Slightly Worn; Functioning	
	Bulged	False	
Safety	Description		STANDARD M/700 SAFETY
	Function	Like new; Functioning	
	Sub-Assembly	Non-ISS	
Sear	Lift	---Select---	N/A
	Notch	Like new; Functioning	
	Tests	Test Fired	False
Feeding Test		False	
Trigger	Condition	Slightly Worn; Not Functioning	WILL FOLLOW DOWN MIN TRIGGER RETURN
	Pull	---Select---	1.5#
	Altered	True	SET SCREWS ALTERED
	Sub-Assembly	M/700 Non-Bolt Lock	
Non-Remington Components	Description		SCOPE,RINGS,BASE,BIPOD

Arms Services Repair & Estimate System

File Add Repair Estimate Repair Expedite Repair Inquiry Repair Tools CSR Tools Reports Table Maintenance System Maintenance Help

Repair Inquiry

Repair Number: **RE00186228** Serial: C6532290 Model 700 Center Fire Caliber: Repairman: **Chuck Dekanek**
 Verify Repair 223 REM Produced: 09/25/1990 Status: **Repairing 1/21/2010 6:00:23 AM**

Address Information

Customer: ☒ Received From Return To: ☐ Received From

Name: **DANNY CLARK** **DANNY CLARK**

Address 1: **571 COUNTY RD 46** **571 COUNTY RD 46**

Address 2: **FLORENCE** **FLORENCE** PO Box: **FLORENCE** PO Box:

City: **FLORENCE** **FLORENCE** State: **AL** Zip Code: **35634** Country: **US** State: **AL** Zip Code: **35634** Country: **US**

FFL: **FLORENCE**

Contact / Condition	Problems	Estimate	History / Status	Shipping / Billing
Date	Code	User ID	Desc1	Current Status
1/14/2010 7:10:5	New	thomaspe	Repair Added	Repairing
1/14/2010 7:14:1	Update	thomaspe	Repair information change	1/21/2010 6:00:23 AM
1/20/2010 1:00:5	Expedite	pencer1	From: Check In	System
1/20/2010 1:20:4	Expedite	dekanekcg	From: Repair Bench	Repair Bench
1/21/2010 5:09:2	Maint	Travisbw	Repair Maintenance	Repair Location
1/21/2010 5:58:3	Estimate	dekanekcg	Estimate Update	ILN
1/21/2010 6:00:2	Repairing	System	Immediate SAP Allocation	Current Location
				ILN
				Transfer Number

☐ Shipping Hold ☐ InterFace Hold ☐ Estimate Sent ☒ Parts Received ☐ Passed Inspection ☐ Return As Received ☐ Has been Approved ☐ Internal Repair

Repair Search **Refresh** **Close**

start 1/21/2010 11:37 AM CAPS NUM INS SCRL

Arms Services Re...

27
 33.64
 15.
 75.64

RECEIVE
 JAN 25 2010

BY:

CS 1/11/10

4266

24"
D/K 9/90
1.54

Attention:

Sometimes the gun
will fire when the
safety is taken off.

Danny Clark

571 County Road 46

Florence, AL 35634

Phone: 256-767-4924 'Home'

Serial
Number:

C6532290

Model: 700



RE00186228

Trig. set screws altered.
will follow down. Replace
TPA check over, clear
AT 1 1/2 normal charges.

Quote