

Remington Arms Co., Inc.
Product Service
Legal Case #:4106

Case Information

RE#	Date Opened	Date Opened(PS)	Date Closed	Incident Date	Pre Lit	Lit	Obsolete
182921	12/11/2009	12/14/2009	12/14/2009				

Customer Information

Type	Business	First Name	Last Name	Street	City	State	Zip	Age	Contact
Incident		Tom	Hall	731 Sweet Ridge	Prattville	AL	36066		H 334-365-9108 E hallfam@knology.net

Incident Information

Claims	Codes	Repair Est.	Medical Treatment	Medical Status
PI				
PD	Cause:4038	Could Not Duplicate Concern		
S	Fired on bolt closing	Concern:1008	Fired on Bolt Closing	Unknown
C				

12/16/09 Per note with rifle, after loading the gun he moved the bolt forward to chamber a round and at that time the gun discharged. The safety was on.cm

Firearm Information

Mfg.	Type	Model/Ga.	SKU	Serial	Bbl.	DOM
Remington	CF/BA	700/308 WIN	84207	G6861914	KD	5/4/2009 10:46:15 AM

Date Purchased	Where Purchased	Accessories	Original Owner
	BILL HICKS & CO LTD	TWO PIECE SCOPE BASE	U

CONCERN:FBC

Ammunition Information - None Defined

Other Products Information - None Defined

Settlement

Remington/700/CF/BA

Settlement	Release of Claims	Release Date	Reimbursement	Cash Settlement	Reim. Date APV	Cash Date APV
Replace TPA, test at no charge to restore confidence						

Repair/Replacement Cost	Repair/Replacement Date
69.46	12/16/2009

12/16/09 Per Ilion inspection/decision, could not duplicate concern, check over, replace TPA, function test at no charge to restore confidence in rifle.cm

Examination[Remington/CF/BA]

Part	Sub-Part	Code	Comment
	Examiner		B.TRAVIS
	Exam Date		12/14/2009

Examination	Product Type		RF
	Action Type		A
	Assigned To		F.SUPRY
Cause	4038	Could Not Duplicate Concern	
Barrel	Description		20" 308 WIN HB
	Date Code		KD
	Bore Plugged	False	
	Bulged	False	
	Fired	False	
	Fired while Obstructed		
	Muzzle/Crown Condition	Like new; Functioning	
Bolt	Firing Pin	Like new; Functioning	
	Shroud	Like new; Functioning	
	Face	Slightly Worn; Functioning	
	Handle	Like new; Functioning	
	Stop	Slightly Worn; Functioning	
Extractor	Condition	Slightly Worn; Functioning	
	Cut Condition	Slightly Worn; Functioning	
	Ext/Eject Test	False	
Overall	Exterior Condition	Like new; Functioning	
	Stock Condition	Like new; Functioning	
	Fore End Condition	---Select---	
Receiver	Condition	Slightly Worn; Functioning	
	Bulged	False	
Safety	Description		STANDARD XMP SAFETY
	Function	Like new; Functioning	
Tests	Test Fired	False	
	Feeding Test	False	
Trigger	Condition	Like new; Functioning	
	Pull	---Select---	3.5#
	Altered	False	
	Sub-Assembly	X-Mark Pro	
Non-Remington Components	Description		TWO PIECE SCOPE BASE

12-08-09

4106

After loading the
gun I moved the bolt
forward to chamber a
round at ~~that~~ time
the gun discharged. The
safety was on.

TOM HALL
731 Sweet Ridge mailing address
Prattville, AL
36066

E-mail:-

HALLFam@Knology.net

Phone # 334-365-9108

could not duplicate concern
check out, replace TPA, Function
test at H/C to restore confidence
in rifle.

From: Shipped through: Laser Copy Inc 103 N Memorial Dr PRATTVILLE, AL 36067 (334)358-3880	Ship Date: 08DEC09 ActWgt: 10.4 LB CAD: 8393671/GSES0100 Account: S *****	Pat # 156297-4
TO ATTN ARMSERVICE DIV/REPAIR REMINGTON ARMS COMP INC 14 HOEFLER AVE ILION, NY 13357		(555)000-0000
Ref: (PCS)HALL Inv: PKG: 15507 SH: 14741 PO: Dept:		FedEx Ground
Serial Number: G6861914		G
Model: 700		
		
RE00182921		

2011
KD5109
3.5#
013