Remington Arms Co., Inc. Product Service Legal Case #:4333

Case information

RE# Date Opened Date Opened(PS) Date Closed Incident Date Pre Lit Lit Obsolete 188128 2/2/2010 2/3/2010 2/3/2010

Customer Information

Type **Business** First Name Last Name Street City Zip Contact State Age W 877-276-9027 Reporter **Hunts Guns** Shelton **Hunts Guns** 505 E. Allison Dr. 70546 Jennings LA F 337-246-3424

Incident Information

Claims Codes Repair Est. Medical Treatment Medical Status

ΡI

PD Cause:4038 Could Not Duplicate Concern
S Concern:1008 Fired on Bolt Closing

Unknown

C Slam Fire

Dealer reported: Slam fired with round in chamber while closing bolt. Customer is very leery about loading gun. dmf

Firearm Information

 Mfg.
 Type
 Model/Ga.
 SKU
 Serial
 Bbl.
 DOM

 Remington
 CF/BA
 700/22-250 REM
 27512
 E6762480
 OV
 7/13/2001
 12:47:51 PM

Date Purchased Where Purchased Accessories Original Owner

NICHOLS DRY GOODS CO

U

CONCERN:SLAM FIRES

Ammunition Information - None Defined Other Products Information - None Defined Settlement

CHEMEN

Remington/700/CF/BA

2/5/2010

Settlement Release of Claims Release Date Reimbursement Cash Settlement APV APV

Per factory - repair @ n/c to restore confidence in rifle

Repair/Replacement Cost Repair/Replacement Date

\$47.23


2/5/10: Per Fred S. - Could not duplicate concern. Replace trigger assembly, check over, clean to restore confidence in rifle. dmf

Examination[Remington/CF/BA]

Part	Sub-Part	Code	Comment
Examination	Examiner		B.TRAVIS
	Exam Date		2/3/2010
	Product Type		RF
	Action Type		A
	Assigned To		F.SUPRY
Cause	4038	Could Not Duplicate Concern	
Barrel	Description		24" 22-250 REM
	Date Code		OV
	Bore Plugged	False	
	Bulged	False	
	Fired	False	
	Fired while Obstructed		
	Muzzle/Crown Condition	Slightly Worn; Functioning	

ļ	Firing Pin	Slightly Worn; Functioning	l
Bolt	Shroud	Slightly Worn; Functioning	
	Face	Slightly Worn; Functioning	SOME BRASS WASH
	Handle	Slightly Worn; Functioning	
	Stop	Slightly Worn; Functioning	
Extractor	Condition	Slightly Worn; Functioning	
	Cut Condition	Slightly Worn; Functioning	
	Ext/Eject Test	False	
Locking	Block Condition	Select	
	Lug Condition	Slightly Worn; Functioning	
	Notch Condition	Select	
Overall	Exterior Condition	Slightly Worn; Functioning	
	Stock Condition	Slightly Worn; Functioning	
	Fore End Condition	Select	
Receiver	Condition	Slightly Worn; Functioning	
Receiver	Bulged	False	
Safety	Description		STANDARD M/700 SAFETY
	Function	Like new; Functioning	
	Sub-Assembly	ISS	
	Lift	Select	.015
Sear	Notch	Like new; Functioning	
	Tests	Test Fired	False
Feeding Test	16212	False	
Trigger	Condition	Like new; Functioning	
	Pull	Select	5.5#
	Altered	False	
	Sub-Assembly	M/700 Non-Bolt Lock	

Arms Services Rep								
File Add Repair Estimate Road Repair Inquiry	epair Expedite Rep	air Inquiry Repair Tool	s CSR Tools Reports T	able Maintenance Syste	m Maintenance Help			
Repair Number: RE00188126	8 Serial: E67624 22250 REM P	180 Model 700 Center Fire Cali roduced: 07/13/2001	1		4	1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1		
-Address Information	l digitario.			ing 2/3/2010 8:14:50 AM		The state of		
Customer: Name: HUNTS GUNS LL	C	eceived From Return	To: TS:GUNS:LLC	← Received From		E Land		
Address 1: 505 ALLISON DRIVE Address 2	PO Box		LISON DRIVE	O Bax		hang a	4.4	
City: JENNINGS State: LA Zip Code: 170	546 Cou	JENNII Intry: US State: LA	NGS Zip Code: 170546	Country US				
		~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~	72 053 01 2G 02617					
Contact / Condition	Problems	Estimate	History / Status	Shipping / Billing Current Status				
2/2/2010 7:29:55 New 2/2/2010 7:31:45 Update	User ID valentds valentds	Desc1 Desc Repair Added Repair information cha	Shipping Hold	Estimating 2/3/2010 8:14:50 AM	411	E FER All S	建 基本 []	Mil.
2/3/2010 8:14:50 Maint	Travisbw	Repair Maintenance Statu	us: Estim	valentds Repair Bench Repair Location	4.0			
	4.174		Passed Inspection Return As Receive	ILN				e e e e e e e e e e e e e e e e e e e
			☐ Has been Approve ☐ Internal Repair	(11.51	177.0			
	and the second seconds.							13
Repair <u>S</u> earch			<u>Re</u>	fresh <u>C</u> lose				
				ida i		A Residence of		
1 (1) 1 (1)								
	i na proposaniem Lieu i Lieu							100 40
		ender de	i dida				till i l	
		4 5 1 4 5 6 6						
All Carlos			- 					
di di	The state of the s	distraction	gjer en er er skrige		Programme Company			
			production of the second		ne argun			
ing the state of	78.2		effe					
Selfo Facility (1995) and appropriate to the control of the contro		tis – Territor Vinden	ate in the				10.30	di Salah
Pyrque	2/3/2010 (8	.40 AM	NUM INS	I SCAL		* * * * * * * * * * * * * * * * * * * *		
	-	Arms Services Re.L.			**************************************		* P T T (Dena.



U.S. Department of Justice

Bureau of Alcohol, Tobacco, Firearms and Explosives

Federal Firearms License

(18 U.S.C. Chapter 44)

ATF Form 8 (5310.11) Revised September 2008

In accordance with the provisions of Title I, Gun Control Act of 1968, and the regulations issued thereunder (27 CFR Part 478), you are licensed to engage in the business specified in this license, within the limitations of Chapter 44. Title 18, United States Code, and the regulations issued thereunder, until the expiration date shown. See "WARNINGS" and "NOTICES" on reverse. ATF - Chief, FFLC 5-72-053-01-2G-02617 Direct ATF 244 Needy Road Correspondence To Martinsburg, WV 2540 Chief, Federal Firearms Licenting Center July 1, 2012 Name **HUNTS GUNS LLC** Premises Address (Changes? Nonfy the File **505 E ALLISON DR** JENNINGS, LA 70546-Type of License 01-DEALER IN FIREARMS OF FITHER THAN DESTRUCTIVE DEVICES (Changes? Notify the FFLC of any changes.) Purchasing Certification Statemen The licensee named above shall use a copy of this license to assist a transferor of firearms to verify the identity and the licensed status of the licensee as provided by 27 CFR Part 478. The signature on each copy must be an original signature. A faxed, scanned or e-mailed copy of the licensee will assignature intended to be an original signature is acceptable. The signature must be that of the Federal Firearms Licensee (FFL) or a responsible person of the Fill figurify that this is a true copy of a license issued to the licensee named above to engage in the bissiness specified above under "Type of License." HUNTS GUNS LLC 505 E ALLISON DR JENNINGS, LA 70546-Letter)WNER Licensee/Responsible Person Signature Position/Title SHELTON HUNT
Printed Name

THIS MODEL IS KNOWN TO SLAM FIRE WITH ROUND IN CHAMBER WHILE CLOSING BOLT, CUSTOMER IS VERY LEERY ABOUT LOADING GUN, HE IS A DIEAARD REMINISTON FAM THANK YOU! SHELTON HUNT, HUNT'S GUNS LLC

PH. 877-276-9027 FAV 337-246-3424 could not dupliente concerne replace TPA, checkown, clear To restone confidence in rifle.

238145

E6762480 700

CS 2-1-10

Brand of lubricant used:

Remington.

Factory Repair Instructions (NOTE: Please print and complete this form, and then include it with your firearm.) Serial Number: E6762480 Model Number: Are you the original owner?: Date of Purchase: Name: Address (no PO Boxes): City: State: Zip: Phone (Daytime): Fax: E-mail Address: I would like to receive future e-mail updates from Remington. Please describe your problem: GUN. MANY Ammunition Information: Manufacturer: Type:---Other (i.e. bullet weight/type, shot size, powder): Handload Information: Powder Weight: Powder Used: Case/Hull Used: Primer Used: Reloader Used: Bullet Type/Shot Size: Firearms Care (Cleaning and Lubrication): RXM:01L Brand of cleaning solution used: How often do you clean the bore? (Months or Number of rounds) How often do you clean the action? (Months or Number of rounds) How often do you clean the trigger assembly? (Months or Number of rounds) 4