Remington Arms Co., Inc. Product Service Legal Case #:4028

Case Information

RE# Date Opened Date Opened(PS) Date Closed Incident Date Pre Lit Lit Obsolete 181216 11/23/2009 11/24/2009 11/24/2009

Customer Information

Type Business First Name Last Name Street City State Zip Age Contact

Reporter Peter R. Itao 13225 Timber Park Dr. Platte City MO 64079 H 913-684-7695

E peter.itao@us.army.mil

Incident Information

Claims Codes Repair Medical Medical Est. Treatment Status

ΡI

PD Cause: 4038 Could Not Duplicate Concern
S Unexplained Discharge - No

Concern: 1025 Unexplained Discharge - No Unknown Mention of Safety Position

C Gun discharges without pulling trigger

Customer wrote on repair form - Gun accidentally discharges without pulling the trigger. dmf

Firearm Information

Mfg.TypeModel/Ga.SKUSerialBbl.DOMRemingtonCF/BA700/7MM REM MA*A6681819EQ 10/1/1978

Date Purchased Where Purchased Accessories Original Owner

SIMMONS GUN SPEC OLATHE KS U

CONCERN: ACCIDENTALLY DISCHARGES

Ammunition Information - None Defined Other Products Information - None Defined Settlement

Remington/700/CF/BA

Settlement Release of Claims Release Date Reimbursement Cash Reim. Cash Settlement Date APV Date APV

Repair under BLSM program

Repair/Replacement Cost Repair/Replacement Date

\$60.38 11/25/2009

11/25/09: Per Fred S. - Could not duplicate concern. Replace trigger, check over, clean under BLSM program. dmf

Examination[Remington/CF/BA]

Part	Sub-Part	Code	Comment
Examination	Examiner		B.TRAVIS
	Exam Date]	11/24/2009
	Product Type		RF
	Action Type		A
	Assigned To]	F.SUPRY
Cause	4038	Could Not Duplicate Concern	

http://cps03ap13:200/psaapp/PrintDisplay.aspx?ID=4028&Type=Case

11/25/2009

	Description		24" 7MM REM MAG
	Date Code		EQ
	Bore Plugged	False	
Barrel	Bulged	False	
	Fired	False	
	Fired while Obstructed		_
	Muzzle/Crown Condition	Slightly Worn; Functioning	
	Firing Pin	Slightly Worn; Functioning	
3	Shroud	Slightly Worn; Functioning	
Bolt	Face	Slightly Worn; Functioning	
	Handle	Slightly Worn; Functioning	
	Stop	Slightly Worn; Functioning	
	Condition	Slightly Worn; Functioning	
Extractor	Cut Condition	Slightly Worn; Functioning	
	Ext/Eject Test	False	
	Block Condition	Select	
Locking	Lug Condition	Slightly Worn; Functioning	
Locking	Notch Condition	Select	
	Exterior Condition	Slightly Worn; Functioning	
Overall	Stock Condition	Slightly Worn; Functioning	
	Fore End Condition	Select	
D	Condition	Slightly Worn; Functioning	
Receiver	Bulged	False	
Safety	Description		STANDARD M/700 BOLT LOCK SAFETY
Safety	Function	Like new; Functioning	
	Lift	Select	.010
Sear	Notch	Slightly Worn; Functioning	
	Tests	Test Fired	False
Feeding Test	lests	False	
	Condition	Slightly Worn; Functioning	
Tricas	Pull	Select	5.5#
Trigger	Altered	False	
	Sub-Assembly	M/700 Bolt Lock]

4028



24" 24" 2010

General Repair Form

Back to Repair Services

NOTE: Please complete and print this form, and then include it with your firearm

Model Number: Model 700 7mm Rem Mag	Serial Number: A6681819						
Name: Peter R. Itao	Date of Purchase: 1978						
Address (no PO Boxes): 13225 Timber Park Drive							
City: Platte City	State: MO	Zip: 64079					
Phone (Daytime): (913) 684-7695	Fax:						
E-mail Address: peter.itao@us.army.mil							
Please describe your problem:							
Gun accidentally discharges without pulling the trigger.							
Want to get it fixed through your Safety Modification Program.		•					
		:					
378 characters left		,					
NOTE: Prior to shipping your firearm, contact the Repair Center for services provided and estimated repair time.							
① WARNING: DO NOT SEND LIVE OR SPENT SHELLS IN YOUR FIREARM OR IN THE SAME BOX WITH THE FIREARM. THIS IS A VIOLATION OF FEDERAL LAW. IF YOU FEEL YOU MUST SEND SPENT SHELLS PLEASE SEND THEM IN A SEPARATE PACKAGE AND INCLUDE NAME, ADDRESS (WITH ZIP CODE), TELEPHONE AND MODEL AND SERIAL NUMBER OF YOUR FIREARM.							
Record the serial number of your firearm before sending it. Pack your firearm for safety and to prevent further damage in shipping and handling. Preferably, ship in a firearm box. (Note: Original boxes may not be returned.) Remove all accessories from your firearm to prevent loss or damage. Ship your INSURED firearm by either UPS or Parcel Post. Remington is not responsible for damage or loss during shipment, so you may elect to purchase insurance from your carrier.							

A6681819 Model: 700

RF00181216

Visit Our Other Websites

Other Sites

could not duplicate concern.

The hace TPA, chein over, clear

under bolt Lock Program

for \$ 10.00 + S+H.

Quote

	Uiry	3 F (4) 121		DOMESTIC AND REAL	To the state of the state of				1,000
Repair Number: R		Serial: A66818	319 Model 700 Center Fire C	aliber: Repairman:	Bruce Travis		Alle		4.7
/erify Repair		7 MM REM M	AG Produced: 10/23/1978	Service of the Control of the Control	ovalHold 11/24/2009 6:45	MAB	1.	is also provide at	April 1
ddress Inform		A A		in Tax	Received Fra				170 4 60
Name: PETE	RITAO	***************************************		TERITAO	riccered Fla				
Address 1: 13225 1 Address 2:	TIMBER PARK DRIV	PO Box		25 TIMBER PARK DRIVE	PO Box				200
City: PLATTI	E CITY		PLA	TTE CITY					
State: MU	Zip Code: 64079	Cou	tana hagif qaja sararainti ay rasanlah ay ay barani da sarara	Zip Code: 64079	Country US			光点 特别的	ne to the
Contact / Cond		<u> 3 - 3</u>			OUT OF THE				
- 14 - W. 143	property.	Problems	Estimate	History / Status	Shipping / Billin Current Status	9	i de production	医乳毒剂 溢	
Date 11/23/2009 5:5	Code 3: New	User ID VALENT DS	Desc1 Repair Added	Shipping Hok	ApprovalHold		and profession	1.4	
11/23/2009 5:5 11/24/2009 6:3		VALENTDS Travisbw	Repair information change Repair Maintenance	InterFace Ho	Travisbw	BAM .	eries participation	Figure State of Course	Spanner State
11/24/2009 6:4 11/24/2009 6:4	5: Estimate	Travisbw	Estimate Update	Parts Receive	Hepair Location				
11/24/2003 6.44	6.] Approvamoid	System	Immediate SAP Allocation	Passed Inspe				7.1.3.1.4	
				☐ Has been Ap	proved ILN				3.1
اللا				internal Repa	Transfer Number			2.5	
, de la de		1 1 2 20		and the state of t	and the second s				
				15t 14t 15 15t 14 14 4 6	Defrach	11.000.000.00		and the second of the second	and the Colombia and the Colombia
Repair Se	earch				Refresh Clo	se			
Repair Se	earch		4 3 - 4 4 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	_	<u>R</u> efresh <u>C</u> lo	ise J	e search	A NOTE OF	
Repair <u>S</u> e	earch		tor to	9 9 9 9 9 9 1 4 1 2 3 4 3 4 4	Refresh Clo		en e		
Hepair <u>S</u> e	arch		fine distributes of		Refresh Clo				
Hepair <u>S</u> e	erch		in de la company		Befresh Clo				
Hepair <u>S</u> e	arch		Total of the second of the sec		Befresh Clo		Carrierania Carrierania Carrierania Carrierania Carrierania		
Repair <u>Ş</u> e	Parch		The Tollows The T		Befresh Clo				
Repair <u>S</u> e	arch				Befresh Co				
Repair Se	earch				Befresh Clo				
Repair 28	earch				Befresh Co				
Mepali 28	Anch				Befresh Co				
Repair 28	arch				Befresh Co				
Repair 28	arch				Befresh Coo				
Repair 28	Arch				Befresh Co				
Repair 2e		24/2009 8			Befresh Coc				

	ZC.	[2]	I	VI	
Ŋ	EC Nov	2	5	2009	
В	Y:				