Remington Arms Co., Inc. Product Service Legal Case #:3794

Case Information

RE# Date Opened Date Opened(PS) Date Closed Incident Date Pre Lit Lit Obsolete 175244 9/16/2009 9/17/2009 9/17/2009

Customer Information

State Zip Contact Type **Business** First Name Last Name Street City Age H 989-895-0985 1215 Fraser St. Reporter Jody Opdycke Bay City MI 48708 E jmcz1215@netscape.net

Incident Information

Claims Codes Repair Est. Medical Treatment Medical Status

PΙ

PD Cause:4038 Could Not Duplicate Concern

Concern:1007 Fired on Safe Release

Unknown

S Rifle fired on its own C

Customer reported: Rifle fired on its own 3 times the first time he went shooting. Also, the front sling mount is off center. There is a flaw in the wood on the left side and the finish is chipped off. dmf

Firearm Information

Mfg.

Type

Model/Ga.

SKU

Serial Bbl.

DOM

Remington

Date Purchased

CF/BA

GANDER WAREHOUSE #1/Leban

700/7MM REM MA

**2580**3

G6733993 AC 3/7/2008 8:18:06 PM

11/17/2008

Where Purchased

Accessories

Original Owner

Y

CONCERN: FIRED ON IT'S OWN 3 TIMES

Ammunition Information - None Defined Other Products Information - None Defined Settlement

Remington/700/CF/BA

Settlement

Release of Claims

Release Date

Reimbursement

Cash Settlement Reim. Date APV Cash Date APV

Repair at no charge

Repair/Replacement

Repair/Replacement Date

Cost \$205.19

9/21/2009

9/21/09: Per Fred S. - Could not duplicate concern. Replacing trigger assemb. to restore confidence in rifle at n/c. dmf

Examination[Remington/CF/BA]

Part	Sub-Part	Code	Comment
	Examiner		B.TRAVIS
	Exam Date		9/17/2009
Examination	Product Type		RF
	Action Type		A
	Assigned To	<u></u>	F.SUPRY
Cause	4038	Could Not Duplicate Concern	
Barrel	Description		24" 7MM REM MAG
	Date Code	]	AC
	Bore Plugged	False	
	Bulged	False	
	Fired	False	
	Fired while Obstructed		
	Muzzle/Crown Condition	Slightly Worn; Functioning	

	<del>=====================================</del>		<del>==</del>
Bolt	Firing Pin	Slightly Worn; Functioning	
	Shroud	Slightly Worn; Functioning	
	Face	Slightly Worn; Functioning	
	Handle	Slightly Worn; Functioning	
	Stop	Slightly Worn; Functioning	
	Condition	Slightly Worn; Functioning	
Extractor	Cut Condition	Slightly Worn; Functioning	
	Ext/Eject Test	False	
	Block Condition	Select	
Locking	Lug Condition	Slightly Worn; Functioning	
	Notch Condition	Select	
	Exterior Condition	Slightly Worn; Functioning	
Overall	Stock Condition	Slightly Worn; Functioning	
	Fore End Condition	Select	
Receiver	Condition	Slightly Worn; Functioning	
	Bulged	False	
0.64	Description		STANDARD M/700 X-MARK PRO SAFETY
Safety	Function	Like new; Functioning	
Sear	Lift	Select	.012
	Notch	Like new; Functioning	
	Total	Test Fired	False
Feeding Test	Tests	False	
Trigger	Condition	Like new; Functioning	
	Puli	Select	4.5#
	Altered	False	
	Sub-Assembly	X-Mark Pro	

Factory Repair Instructions
(NOTE: Please print and complete this form, and then include it with your firearm.)

Control Provide Action	, , , , , , , , , , , , , , , , , , , ,				
Model Number: 700 BDL, DLX	Serial Number: G6733993				
Are you the original owner?:					
Name: Jody Opdycke	Date of Purchase: 11-17-08				
Address (no PO Boxes): 1215 FRaseR St.					
City: Bay City	State: M1.   Zip: 48708				
Phone (Daytime): 989-895-0985	Fax:				
E-mail Address: JMCZ1215@netscape, net  would like to receive future e-mail updates from Remington.					
Please describe your problem: Rifle went	off (fixed) on its own				
3 times the first "+	ime I went shooting				
I only fixed 1 box (20	2 Rounds) I didn't clean				
it for fear of maybe	brakeing something # in it.				
Also the front sling	mount is turned off center.				
And there is a flow in	the wood on the Left				
side between the two 1	Slack dots. And the finish				
is chipped off on one of the black dots on the deft					
Ammunition Information:					
Manufacturer: Rem, 7mm Rem Mag	Type:				
Other (i.e. bullet weight/type, shot size, powder):					
	and the second s				
Handload Information:					
Powder Used:	Powder Weight:				
Case/Hull Used:	Primer Used:				
Bullet Type/Shot Size:	Reloader Used:				
Firearms Care (Cleaning and Lubrication):					
Brand of cleaning solution used: UICN CIFAN					
How often do you clean the bore? (Months or Number of rounds)					
How often do you clean the action? (Months or Number of rounds)					
How often do you clean the trigger assembly? (Months or Number of rounds)					
Brand of lubricant used:					

How often do you lubricate the bore? (Months or Number of rounds)

How often do you lubricate the action? (Months or Number of rounds)

How often do you lubricate the trigger assembly? (Months or Number of rounds)

Have you reviewed the cleaning and maintenance recommendations on our web site or in our owners manual?

YES NO

Comments:

When was the last time that your firearm was serviced by a Remington authorized repairman/gunsmith? nevek

What were the services performed? Uone

Ship your INSURED firearm by either UPS or Parcel Post to:

## **REMINGTON ARMS CO., INC**

ATTN: Arms Service Divison 14 Hoefler Ave Ilion, NY 13357

WARNING: DO NOT SEND LIVE OR SPENT SHELLS IN YOUR FIREARM OR IN THE SAME BOX WITH THE FIREARM. THIS IS A VIOLATION OF FEDERAL LAW. IF YOU FEEL YOU MUST SEND SPENT SHELLS PLEASE

IAME, ADDRESS (WITH ZIP CODE), TELEPHONE AND

G6733993

Model: 70



RE00175244

dina it

lamage in shipping and handling. Preferably, be returned.)

: loss or damage.

ide the box. Shipments without a proper

Post. Remington is not responsible for purchase insurance from your carrier.

iidelines:

include your credit card number and expiration date with your gun)

:: For Repairs over \$75.00, you will receive a written estimate detailing the nature of the repair, applicable taxes and shipping. You will have 30 days to approve the repair estimate. Repairs can be paid by check, money order, or credit card (American Express, Discover, MasterCard, or VISA). If you wish, you can expedite repairs over \$75.00 by setting a pre-authorized amount that can be billed to your credit card.

could not diplicate concern. replace TPA to restone confidence in refle + + N/C

upproprity

: Also if you could went bought This Kitle I wanted one with a detachable clip the store told me that it didn't come with a. detachable clip Later after buying it I found out that it does come with a detachable clip. I talked to the store's manager and he only had excusses. However If you could please send me a parts List and cost for everything I will need to convert this Rifle it would make me very happy.

Thank You in advance

Jody Cydycke

Jody Cpdycke

Gander Mountain 174 (989)791-3500 www.gandermountain.com Mon-Sat 9am-9pm Sundays 10am-6pm

O.C 1 1/4INSPR SLNG W/S.SWV	
051057208130	19.99 T
REGULAR PRICE	19.99 N
PROMOTION % MRKDN(10%)	2.00-N
ENTER PROMO ID # gander card	
REM 700 BDL DLX 7MM 24 NONEM	
047700258034	799.99 T
REGULAR PRICE	799.99 N
SERIAL NUMBER 25803 G6733993	
PROMOTION % MRKDN(5%)	40.00-N
ENTER PROMO ID # gander card	
OUD TOTAL	4377 00
SUBTOTAL	\$777.98
SALES TAX 6%	\$46.68
TOTAL	\$824.66
GANDER - PLCC	\$824.66
XXXXXXXXXXXXX2478	
EXPIRY: XX/XX	
AUTH# 006010	
001- STANDARD PLAN	

Receipt required for all Returns and Exchanges

ITEMS 2 Brian P 11-17-2008 12:58:38 0174 25 160154 0483

> Uncertified Statewide Bait Emerald Shiners, Sucker Minnows Retail License #7416 Cerification#

Sarms Services Repair & Estimate System	
File Add Repair Estimate Repair Expedite Repair Inquiry Repair Tools CSR Tools Reports Table Maintenance System	n Maintenance Help
Repair Inquiry	
Repair Number: RE00175244 Serial: G6733933 Model 700 Center Fire with 24 Repairman: Dale Lewis inch barrel Caffer: 7 MM REM MAG BDL DLX	and a responsible to the second residence of the second
Verity Repair Produced: 03/07/2008 Status: Repairing 9/17/2009 11:52:03 AM	
Address Information Customer: GReceived From Return To: Received From	4
Name: JODY OPDYCKE JODY OPDYCKE	
Address 1: 1215 FRASER ST. 1215 FRASER ST. PO Box PO Box	· 在参考性。全性是特殊的。
City: BAY CITY BAY CITY State: MI Zip Code: [48708 Country: US State: MI Zip Code: [48708 Country: US	· · · · · · · · · · · · · · · · · · ·
FFL: C C C C C C C C C C C C C C C C C C C	the war arm and dealers for the last
Contact / Condition Problems Estimate History / Status Shipping / Billing	
Part Typ Description Need Inv Kit Avail Recy Writ Price Parts 00	
F202345LS P: 700 STOCK BDL L/A U M 90GL VEND# - H3	
4000114 S GR-SHIPPING & HANOLING (GUN FIEPAIR) 11 3 .0 0 0 0 0 Ship/Handling .00	
4000294 S GRICHECK TPA 1 0 0 0 0 Y Ext State lax   .UU	year, grange returned and the decide of the forms the state of
Total: .00	
Charge Town	
Repair Search Close	
	·春春春季春春春秋的图形图片图。
	. And a second of the Consequence of the Consequenc
经经验 医外腺性炎 化化二甲基甲基甲基甲基甲基甲基甲基甲基甲基甲基甲基甲基甲基甲基甲基甲基甲基甲基甲	
to a screen and a design of the above the state of the st	companies to the second enterior of the second enterior
and the second	and the second of the second of the second
	and the second s
	医克里特氏 医二乙基甲基 经证据
The state of the s	in the contract of the contrac
<b>"我是在这些为某事体是不可能的关系的。"</b>	A STATE OF THE PARTY OF THE PAR
Conserves Res. Grande General Conserves Res.	Can compare the

DECEIVE I SEP 2 1 2009 BY: