

Remington Arms Co., Inc.  
Product Service  
Legal Case #:4198

## Case Information

RE#	Date Opened	Date Opened(PS)	Date Closed	Incident Date	Pre Lit	Lit	Obsolete
184790	1/5/2010	1/5/2010	1/5/2010				

## Customer Information

Type	Business	First Name	Last Name	Street	City	State	Zip	Age	Contact
Incident	Port Authority of NY NJ Police		Port Authority	241 Erie St Room 321	Jersey City	NJ	07310		

## Incident Information

Claims	Codes	Repair Est.	Medical Treatment	Medical Status
PI				
PD				
S	fired without pulling trigger, safe off	Cause:4038 Could Not Duplicate Concern Concern:1006 Unexplained Discharge Safe OFF		Unknown
C				

1/8/10 Per letter with rifle, they allege this firearm had an unintended discharge when the operator had placed his thumb on the safety switch. The operator had initially attempted to fire the weapon but the trigger wouldn't move. While verifying that the weapon was off of safe the weapon discharged.cm

## Firearm Information

Mfg.	Type	Model/Ga.	SKU	Serial	Bbl.	DOM
Remington	CF/BA	700/308 WIN	25709	E6733411	CV	4/18/2001 10:59:14 AM

  

Date Purchased	Where Purchased	Accessories	Original Owner
	NY-NJ PORT AUTHORITY	SCOPE BASE,RINGS,SLING,BIPOD,PADDED COMB	U

CONCERN:DELAYED DISCHARGE

Ammunition Information - None Defined

Other Products Information - None Defined

## Settlement

Remington/700/CF/BA

Settlement	Release of Claims	Release Date	Reimbursement	Cash Settlement	Reim. Date APV	Cash Date APV
Per Ilion inspection/decision replace TPA, clean at 1/2 normal charges						

  

Repair/Replacement Cost	Repair/Replacement Date
64.73	1/8/2010

1/8/10 Per Ilion, could not duplicate concern. Action/trigger assm dirty. Sand in action and trig assm. Replace TPA, check over, clean at 1/2 normal cost.cm

## Examination[Remington/CF/BA]

Part	Sub-Part	Code	Comment
Examination	Examiner		B.TRAVIS
	Exam Date		1/5/2010
	Product Type		RF
	Action Type		A
	Assigned To		F.SUPRY
Cause	4015	Improper Maintenance	SAND ON ACTION UNDER STK AND TPA
	Description		26" 308 WIN POL
	Date Code		CV

Barrel	Bore Plugged	False	
	Bulged	False	
	Fired	False	
	Fired while Obstructed		
	Muzzle/Crown Condition	Slightly Worn; Functioning	
Bolt	Firing Pin	Slightly Worn; Functioning	
	Shroud	Slightly Worn; Functioning	
	Face	Slightly Worn; Functioning	
	Handle	Slightly Worn; Functioning	
	Stop	Slightly Worn; Functioning	
Extractor	Condition	Slightly Worn; Functioning	
	Cut Condition	Slightly Worn; Functioning	
	Ext/Eject Test	False	
Locking	Block Condition	---Select---	
	Lug Condition	Slightly Worn; Functioning	
	Notch Condition	---Select---	
Overall	Exterior Condition	Slightly Worn; Functioning	
	Stock Condition	Slightly Worn; Functioning	
	Fore End Condition	---Select---	
Receiver	Condition	Slightly Worn; Functioning	
	Bulged	False	
Safety	Description		STANDARD M/700 SAFETY
	Function	Like new; Functioning	
	Sub-Assembly	Non-ISS	
Sear	Lift	---Select---	.015
	Notch	Like new; Functioning	
	Tests	Test Fired	False
Feeding Test		False	
Trigger	Condition	Slightly Worn; Functioning	SAND IN TRIG ASSM
	Pull	---Select---	4#
	Altered	False	
	Sub-Assembly	M/700 Non-Bolt Lock	
Non-Remington Components	Description		SCOPE BASE,RINGS,SLING,BIPOD,PADDED COMB

## Repair Search

$$\begin{array}{r} 20.25 \\ 15. \text{---} \\ 17.50 \\ 12. \text{---} \\ \hline 64.73 \end{array}$$

RECEIVED  
JAN 06 2010

BY: \_\_\_\_\_

SERIAL # E6733411

PA # 7501

4198

269  
4E  
015  
CV 4/01

THIS WEAPON EXPERIENCED AN UNINTENDED  
DISCHARGE WHEN THE OPERATOR HAD PLACED HIS  
THUMB ON THE SAFETY SWITCH. THE OPERATOR  
HAD INITIALLY ATTEMPTED TO FIRE THE WEAPON  
BUT THE TRIGGER WOULDN'T MOVE. WHILE VERIFYING  
THAT THE WEAPON WAS "OFF OF SAFE" THE

WEAPON DISCHARGED.

SHIPMENT FROM	
UPS ACCOUNT NO.	V 3 W 4 6 2
REFERENCE NUMBER 115G02	
DAVID HOWARD	TELEPHONE 201 23-3111
PANYNJ	
241 ERIE ST RM 302	
JERSEY CITY	NJ 07310 1303

Serial Number: E6733411

Model: 700



RE00184790

could not duplicate concern.  
Action/trig. assm. dirty. Sawd in  
Action & trig. assm. replace TPA,  
check over, clean & 1/2 normal  
cost.

Quote