

Remington Arms Co., Inc.

Product Service

Legal Case #:4014

Case Information

RE#	Date Opened	Date Opened(PS)	Date Closed	Incident Date	Pre Lit	Lit	Obsolete
181040	11/19/2009	11/20/2009	11/20/2009				

Customer Information

Type	Business	First Name	Last Name	Street	City	State	Zip	Age	Contact
Incident		Leonard	Simmons	452 Hatcher Hill Dr	McDowell	VA	24458		H 540-396-3550

Incident Information

Claims	Codes	Repair Est.	Medical Treatment	Medical Status
PI				
PD	Cause:4015 Improper Maintenance		Unknown	
S	fires on safe release	Concern:1007 Fired on Safe Release		
C				

11/23/09 Per note with rifle, gun will fire when you lock bolt and take off safety.cm

Firearm Information

Mfg.	Type	Model/Ga.	SKU	Serial	Bbl.	DOM
Remington	CF/BA	700/3006 SPR	25793	B6519569	XD	12/1/1983
Date Purchased	Where Purchased	Accessories	Original Owner			
	GREEN TOP SPTG GLEN ALLEN VA		U			

CONCERN:FSR

Ammunition Information - None Defined

Other Products Information - None Defined

Settlement

Remington/700/CF/BA

Settlement	Release of Claims	Release Date	Reimbursement	Cash Settlement	Reim. Date APV	Cash Date APV
Replace TPA, clean at 1/2 normal charges						

Repair/Replacement Cost	Repair/Replacement Date

11/23/09 Trigger contaminated from a partially dried & sticky lubrication residue causing trigger to bind and work sluggish. Replace TPA, clean at 1/2 normal charges.cm

Examination[Remington/CF/BA]

Part	Sub-Part	Code	Comment
Examination	Examiner		B.TRAVIS
	Exam Date		11/20/2009
	Product Type		RF
	Action Type		A
	Assigned To		F.SUPRY
Cause	4015	Improper Maintenance	
Barrel	Description		22" 3006 SPR
	Date Code		XD
	Bore Plugged	False	
	Bulged	False	
	Fired	False	
	Fired while Obstructed		
	Muzzle/Crown Condition	Slightly Worn; Functioning	

Bolt	Firing Pin	Slightly Worn; Functioning	BROWN LUBE ON FIR PIN HEAD
	Shroud	Slightly Worn; Functioning	
	Face	Slightly Worn; Functioning	
	Handle	Like new; Functioning	
	Stop	Slightly Worn; Not Functioning	BINDS/SLUGGISH
Extractor	Condition	Slightly Worn; Functioning	
	Cut Condition	Slightly Worn; Functioning	
	Ext/Eject Test	False	
Locking	Block Condition	---Select---	
	Lug Condition	Slightly Worn; Functioning	
	Notch Condition	---Select---	
Overall	Exterior Condition	Slightly Worn; Not Functioning	
	Stock Condition	Slightly Worn; Functioning	
	Fore End Condition	---Select---	
Receiver	Condition	Slightly Worn; Functioning	
	Bulged	False	
Safety	Description		STANDARD M/700 SAFETY
	Function	Like new; Functioning	
	Sub-Assembly	Non-ISS	
Sear	Lift	---Select---	.012
	Notch	Like new; Functioning	
		Test Fired	False
Feeding Test	Tests	False	
Trigger	Condition	Slightly Worn; Not Functioning	TRIGGER WILL STAY BACK FORM LUBRICATION CONTAMINATION
	Pull	---Select---	8#
	Altered	True	SET SCREWS ALTERED
	Sub-Assembly	M/700 Non-Bolt Lock	

File Add Repair Estimate Repair Expedite Repair Inquiry Repair Tools CSR Tools Reports Table Maintenance System Maintenance Help

Repair Number:	RE00181040	Serial: 86519563 Model 700 Center Fire Caliber:	Repairman:	Bruce Travis
Verify Repair		30-06 SPRG Produced: 01/24/1984	Status:	ApprovalHold 11/20/2009 8:51:25 AM

Customer:		Received From		Return To:		Received From	
Name:	LEONARD SIMMONS			LEONARD SIMMONS			
Address 1:	452 HATCHER HILL DR			452 HATCHER HILL DR			
Address 2:		PO Box:			PO Box:		
City:	MCDOWELL			MCDOWELL			
State:	VA	Zip Code:	24458	State:	VA	Zip Code:	24458
		Country:	US			Country:	US

Contact / Condition		Problems		Estimate	History / Status	Shipping / Billing
					☐ Shipping Hold ☐ Interface Hold ☒ Estimate Sent ☐ Parts Received ☐ Passed Inspection ☐ Return As Received ☐ Has been Approved ☐ Internal Repair	Current Status ApprovalHold 11/20/2009 8:51:25 AM Travisbw ApproveRack Repair Location ILN Current Location ILN Transfer Number
Date	Code	User ID	Desc1			
11/19/2009 8:42	New	schultsom	Repair Added			
11/19/2009 8:43	Expedite	schultsom	From: Check In			
11/20/2009 7:57	Maint	Travisbw	Repair Maintenance			
11/20/2009 8:51	Estimate	Travisbw	Estimate Update			
11/20/2009 8:52	ApprovalHold	System	Immediate SAP Allocation			
11/20/2009 10:11	Expedite	pencel	From: Repair Bench			
11/20/2009 3:37	ApprovalHold	Balchjob	Quotation Control			

Repair Search

Refresh

Close

supryll	11/20/2009	4:03 PM	NUM	INS	SCB
---------	------------	---------	-----	-----	-----

408PM

RECEIVED
NOV 23 2009

BY: _____

PS 11058

CS 11-18-04

Leonard Simmons

4014

XD 12/83
22"
8#
012

452 Hatcher Hill DR.

McDowell, VA 24458

540-396-3558

Gun will Fire when you Lock
Bolt and Take off Safety

Serial Number: **B6519569**

Model: **700**



RE00181040

TRIG. ASSM CONTAMINATED FROM A
PARTIALLY DRIED & STICKY LUBRICATION
RESIDUE CAUSING TRIG. TO BIND & WORK
SLUGGISH. REPLACE TPA, CHECK OVER,
CLEAN AT 1/2 NORMAL CHARGES.

Quote