

Remington Arms Co., Inc.

Product Service

Legal Case #:4209

Case Information

RE#	Date Opened	Date Opened(PS)	Date Closed	Incident Date	Pre Lit	Lit	Obsolete
185181	1/7/2010	1/8/2010	1/8/2010				

Customer Information

Type	Business	First Name	Last Name	Street	City	State	Zip	Age	Contact
Incident		Steve	Sparks	134 Branchwood Rd	Statesville	NC	28625		H 704-876-4419 C 704-682-3440

Incident Information

Claims	Codes	Repair Est.	Medical Treatment	Medical Status
PI				
PD				
S fired on bolt closing	Cause:4038 Could Not Duplicate Concern Concern:1008 Fired on Bolt Closing		Unknown	
C				

1/11/10 Per letter with rifle, he had shot a deer and more deer were coming straight to his stand so he gently pulled the bolt back pulled the brass out and slowly pushed the bolt forward to prevenet spooking them. When he pushed the bolt down the rifle fired. He purchased the rifle new in '85 and has had a gunsmith set the trigger pull at 3 lbs. He had never had it discharge like this before. Has not been able to duplicate the incident since.cm

Firearm Information

Mfg.	Type	Model/Ga.	SKU	Serial	Bbl.	DOM
Remington	CF/BA	700/7MM REM MA	20000	A6860265	AA	3/13/1980
Date Purchased	Where Purchased	Accessories	Original Owner			
	JW MURCHISON WILMINGTON NC	SCOPE BASE	U			

CONCERN:FBC

Ammunition Information - None Defined

Other Products Information - None Defined

Settlement

Remington/700/CF/BA

Settlement	Release of Claims	Release Date	Reimbursement	Cash Settlement	Reim. Date APV	Cash Date APV
Per Ilion inspect/decision replace TPA, clean at \$20 + S&H						
	Repair/Replacement Cost	Repair/Replacement Date				
	82.23	1/11/2010				

1/11/10 Per Ilion, could not duplicate concern. Trigger set screws altered. Replace TPA, check over, clean under BLSM program price.cm

Examination[Remington/CF/BA]

Part	Sub-Part	Code	Comment
	Examiner		B.TRAVIS
	Exam Date		1/8/2010

Examination	Product Type		RF
	Action Type		A
	Assigned To		F.SUPRY
Cause	4038	Could Not Duplicate Concern	
Barrel	Description		24" 7MM REM MAG
	Date Code		AA
	Bore Plugged	False	
	Bulged	False	
	Fired	False	
	Fired while Obstructed		
	Muzzle/Crown Condition	Slightly Worn; Functioning	
Bolt	Firing Pin	Slightly Worn; Functioning	
	Shroud	Slightly Worn; Functioning	
	Face	Slightly Worn; Functioning	
	Handle	Slightly Worn; Functioning	
	Stop	Slightly Worn; Functioning	
Extractor	Condition	Slightly Worn; Functioning	
	Cut Condition	Slightly Worn; Functioning	
	Ext/Eject Test	False	
Locking	Block Condition	---Select---	
	Lug Condition	Slightly Worn; Functioning	
	Notch Condition	---Select---	
Overall	Exterior Condition	Slightly Worn; Functioning	
	Stock Condition	Slightly Worn; Functioning	
	Fore End Condition	---Select---	
Receiver	Condition	Slightly Worn; Functioning	
	Bulged	False	
Safety	Description		STANDARD M/700 BOLT LOCK SAFETY
	Function	Like new; Functioning	
Sear	Lift	---Select---	.008
	Notch	Slightly Worn; Functioning	
	Tests	Test Fired	False
Feeding Test		False	
Trigger	Condition	Slightly Worn; Functioning	
	Pull	---Select---	3#
	Altered	True	SET SCREWS ALTERED
	Sub-Assembly	M/700 Bolt Lock	
Non-Remington Components	Description		SCOPE BASE

12/31/09

4209

RECEIVED
JAN 11 2010

2411
AA380
3A
008

Dear repair shop,

BY:.....

I have talked with someone in the repair shop yesterday and they recommended that I send the rifle in for repair.

Just for a brief summary I would like to explain my problem. I shot a deer and the remaining deer came straight to my stand, I did not want to chamber the next round and spook them so I gently pulled the bolt back and picked the empty case out of the gun and slid the bolt back slowly placing the loaded round in the chamber. When I pushed the bolt down the gun fired. Nothing was close to the trigger.

I purchased the rifle new around 1985. I had a gunsmith set the trigger pull when I purchased the gun. The trigger pull was set to 3 lbs. I have never had the gun discharge like this before. I have placed SEVERAL rounds in gun since I have had it. Never had ANY trouble with rifle prior to yesterday. I placed a round in the gun and slowly opened and shut the bolt about 25 times similar to when the gun discharged earlier and it worked fine with no discharges.

Your help with this would be greatly appreciated.

SERIAL NUMBER A 6860265
Remington 700 7mm mag.

Thanks,

Steve Sparks
134 Branchwood Rd.
Statesville, NC 28625
704-876-4419
704-682-3440

20.23
27
35
82.23

Serial Number: A6860265

Model: 700



RE00185181

could not duplicate concern.
Trig. Set screws altered.
Replace TPA, check over, clean
upden bolt + lock program
for \$20.00 + s+h.

Quote