

Remington Arms Co., Inc.
Product Service
Legal Case #:4092

Case Information

RE#	Date Opened	Date Opened(PS)	Date Closed	Incident Date	Pre Lit	Lit	Obsolete
182529	12/8/2009	12/9/2009	12/9/2009	11/28/2009			X

Customer Information

Type	Business	First Name	Last Name	Street	City	State	Zip	Age	Contact
Reporter		Harold R.	Veeder	511 Egypt St. PO Box 443	Cairo	NE	68824		H 308-485-4322 W 308-485-4661

Incident Information

Claims	Codes	Repair Est.	Medical Treatment	Medical Status
PI				
PD	Cause:4013	Broken or Missing Parts		
S	Concern:1007	Fired on Safe Release	Unknown	
C	Fired on Safe release			

Customer reported in a letter - Purchased the gun some years ago. Shot it a lot. Sighting it in for deer season this year and pushed the safety off & the gun fired. No injuries. dmf

Firearm Information

Mfg.	Type	Model/Ga.	SKU	Serial	Bbl.	DOM
Remington	ML/BA	700/50 CAL	27580	ML063996	CR	4/10/1997
Date Purchased	Where Purchased	Accessories	Original Owner			
	SIMMONS GUN SPECIALTIES INC	AFT MKT 209 PRIMER KIT	U			

CONCERN:FSR

Ammunition Information - None Defined

Other Products Information - None Defined

Settlement

Remington/700/ML/BA

Settlement	Release of Claims	Release Date	Reimbursement	Cash Settlement	Reim. Date APV	Cash Date APV
Per Fred S. - Repair at no charge						
	Repair/Replacement Cost	Repair/Replacement Date				
	\$38.33	12/11/2009				

12/11/09: Per Fred S. - Connector broken, check over, replace trigger assembly at no charge. dmf

Examination[Remington/ML/BA]

Part	Sub-Part	Code	Comment
Examination	Examiner		B.TRAVIS
	Exam Date		12/9/2009
	Product Type		RF
	Action Type		A

	Assigned To		F.SUPRY
Cause	4013	Broken or Missing Parts	
Barrel	Description		24" 50 CAL SS
	Date Code		CS
	Bore Plugged	False	
	Bulged	False	
	Fired	False	
	Fired while Obstructed		
	Muzzle/Crown Condition	Slightly Worn; Functioning	
Bolt	Firing Pin	---Select---	AFT MKT
	Shroud	Slightly Worn; Functioning	
	Face	---Select---	
	Handle	Slightly Worn; Functioning	
	Stop	---Select---	
Overall	Exterior Condition	Slightly Worn; Not Functioning	
	Stock Condition	Slightly Worn; Functioning	
	Fore End Condition	---Select---	
Receiver	Condition	Slightly Worn; Functioning	
	Bulged	False	
Safety	Description		STANDARD M/700 SAFETY
	Function	Like new; Functioning	
Sear	Lift	---Select---	N/A
	Notch	Slightly Worn; Functioning	
	Tests	Test Fired	False
Feeding Test		False	
Trigger	Condition	Slightly Worn; Not Functioning	CONNECTOR BROKEN
	Pull	---Select---	N/A
	Altered	False	
	Sub-Assembly	M/700 Non-Bolt Lock	
Non-Remington Components	Description		AFT MKT 209 PRIMER KIT

Arms Services Repair & Estimate System

File Add Repair Estimate Repair Expedite Repair Inquiry Repair Tools CSR Tools Reports Table Maintenance System Maintenance Help

Repair Inquiry

Repair Number: RE00182529 Serial: ML063996 Model 700ML Center Fire Repeirment: Bruce Travis
 Verify Repair Caliber: .50 Produced: 04/10/1997 Status: Inspected 12/9/2009 9:42:43 AM

Address Information

Customer: Received From Return To: Received From
 Name: HAROLD R VEEDER HAROLD R VEEDER
 Address 1: PO BOX 443 PO BOX 443
 Address 2: 511 EGYPT ST PO Box 511 EGYPT ST PO Box
 City: CAIRO CAIRO
 State: NE Zip Code: 68824 Country: US State: NE Zip Code: 68824 Country: US

FFL:

Contact / Condition	Problems	Estimate	History / Status	Shipping / Billing
Date	Code	User ID	Desc1	Desc2
12/9/2009 8:40:0	Expedite	Travisbw	From: Repair Bench	To: Parts Rack
12/9/2009 8:50:2	Estimate	Travisbw	Estimate Update	Status: Partst
12/9/2009 8:52:0	Repairing	System	Immediate SAP Allocation	
12/9/2009 8:56:5	Expedite	Travisbw	From: Parts Rack	To: Repair Be
12/9/2009 8:57:2	Expedite	Travisbw	From: Repair Bench	To: Final Insp
12/9/2009 8:58:3	Expedite	pencecl	From: Final Inspect	To: Repair Be
12/9/2009 9:37:0	Expedite	lawsonmj	From: Repair Bench	To: Final Insp
12/9/2009 9:42:4	Inspected	lawsonmj	Final Inspection	Warranty

☐ Shipping Hold
☐ Interface Hold
☐ Estimate Sent
☒ Parts Received
☒ Passed Inspection
☐ Return As Received
☐ Has been Approved
☐ Internal Repair

Current Status
 Inspected
 12/9/2009 9:42:43 AM
 lawsonmj
 Packing
 Repair Location
 ILN
 Current Location
 ILN
 Transfer Number

Repair Search

Refresh

Close

Broken connector- replacing Trigger
 assembly w/c.

FRED

RECEIVED
 DEC 10 2009

BY:.....

Serial
Number:

ML063996

Model: 700ML



RE00182529

Remington

I purchased this gun ~~shortly~~ new shortly
after they came out. Shot it a lot.
Sighting it in for deer season November
28th. Placed on sand bags. Pushed
safety off and it fired. Lucky no
one was hurt.

CR4/97
24"

Took gun to local gunsmith. He
called Remington for parts. He parts He
told me the sear is broke in trigger.
Please try to fix.

Thank You
Harold Veeder

Day time phone work 308 485 4661

Home Phone

308 485 4322

connector broken.
check over, replace TRA.
AT X/C
#230145

Harold R. Veeder
PO Box 443
511 Egypt St
Cairo NE 68824