Remington Arms Co., Inc. Product Service Legal Case #:5306

Inforn	

RE#	Date O	pened	Date Opened(PS)	Date Closed	d	Incide	ent Date		Pre Lit	Lit	Obsolete
217399	1/4/2	.011	12/6/2010	1/6/2011		12/5	5/2010				
Customer In	nformation										
Туре	Business	First Name	Last Name	Street	City	State	Zip	Age		Cont	act
Incident		Ken	Baldwin	3218 Golden Eye	Katy	TX	77493			1 832-43 paldwi@	7-3636 gmail.com
Incident Inf	ormation									_	

Incident Information

Claims Codes Repair Est. Medical Treatment **Medical Status**

ΡI

PD Cause: 4038 Could Not Duplicate Concern S

Unknown Concern: 1008 Fired on Bolt Closing

C FBC

12/6/10: Customer called in. He stated that while dry firing the gun on 12/5/10 he closed the bolt & heard the firing pin drop. No damage, No injury. df

Firearm Information

Mfg. Type Model/Ga. SKU DOM Scrial Bbl. CF/BA 700/270 WIN Remington n/a 6496477 RU 11/1/1971 **Date Purchased** Where Purchased Accessories **Original Owner** JOHNS SPTG GD CANTON OHIO TWO PIECE BASE N

CONCERN:FBC

Ammunition Information - None Defined Other Products Information - None Defined Settlement

Remington/700/CF/BA

Cash Reim. Date Cash Settlement Release of Claims Release Date Reimbursement Settlement APV Date APV

Per Ilion - Quote to repair under BLM program

Repair/Replacement Repair/Replacement Date Cost \$45.40 1/18/2011

12/6/10: Sending ARS, Itr, form, box. Box order# 1165575. df 1/18/11: Per Ilion - Could not duplicate concern. TA dirty & sticky. Replace TA, clean & test fire under BLM program - quote. Cust. apprvd repair & pd by credit card. df

Examination[Remington/CF/BA]

Part	Sub-Part	Code	Comment
	Examiner Examiner		B.TRAVIS
	Exam Date		1/6/2011
Examination	Product Type		RF
	Action Type		A
	Assigned To		T.NAGLE
Cause	4038	Could Not Duplicate Concern	
	Description		22" 270 WIN
	Date Code		RU
Barrel	Bore Plugged	False	
	Bulged	False	
	Fired	False	
	Fired while Obstructed		_

http://cps03ap13:200/psaapp/PrintDisplay.aspx?ID=5306&Type=Case

1/18/2011

	Muzzle/Crown Condition	Slightly Worn; Functioning	
	Firing Pin	Slightly Worn; Functioning	
Bolt	Shroud	Slightly Worn; Functioning	
	Face	Slightly Worn; Functioning	
	Handle	Slightly Worn; Functioning	
	Stop	Slightly Worn; Functioning	BINDS
	Condition	Slightly Worn; Functioning	
Extractor	Cut Condition	Slightly Worn; Functioning	
	Ext/Eject Test	False	
	Block Condition	Select	
Locking	Lug Condition	Slightly Worn; Functioning	
	Notch Condition	Select	
	Exterior Condition	Slightly Worn; Functioning	
Overall	Stock Condition	Slightly Worn; Functioning	
_	Fore End Condition	Select	
Receiver	Condition	Slightly Worn; Functioning	
Receiver	Bulged	False	
	Description		M/700 BOLT LOCK SAFETY
Safety	Function	Like new; Functioning	
	Sub-Assembly	Non-ISS	
	Lift	Select	.009
Sear	Notch	Slightly Worn; Functioning	SLUGGISH
	Tests	Test Fired	False
Feeding Test	16313	False	
	Condition	Slightly Worn; Functioning	DIRTY,STICKY
Trigger	Pull	Select	7#
	Altered	False	
	Sub-Assembly	M/700 Bolt Lock	
Non-Remington Components	Description		TWO PIECE BASE

CODY 7# 1009

5306

December 6, 2010

Ken Baldwin 3218 Golden Eye Katy, TX 77493 Ph: 832-437-3636

Ref: #5306

Dear Mr. Baldwin,

Enclosed is a prepaid UPS shipping label to cover shipment of your firearm to our factory for examination.

Please include a copy of this letter to put inside the shipping container. The letter inside is important as sometimes the outside label gets damaged in transit and we want to be sure the firearm is logged in correctly. Mark the ends of the box with "Product Service". Product Service will be inspecting the firearm and will contact me with the results.

I hope that this action will keep you a loyal Remington customer.

Sincerely, D. Fulcher Consumer Affairs Administrator Remington, H&R, Marlin Phone: 1-800-243-9700

Fax: 336-548-7872

JAN 1 2 2011

BY:----

enclosure

6496477 Model: 700 could not Suplicate CONCERN

T. A. DIRTY & STICKY. Replace

TRA, clean + Test fire

Under BLP for \$20.00 + ship

Quota

Remington Arms Company, Inc. • 870 Remington Drive • P.O. Box 700 • Madison, NC 27025 Phone 800-243-9700 • www.remington.com

270

Print	Reset					
Model Number: 700	Serial Number: 6496477					
Are you the original ow	ner?: 🖾 YES 🕱 N	10				
Name: Kenneth Baldwin	Date of F 6-15-	Purchase: 0음				
Address (no	PO Boxes):					
3218 Golden Eye	State: 77	7in: 171/02				
City: Katy Phone	State: 7X	Zip: 77493				
(Daytime): 832 - 374 - 688	Fax:					
E-mail Address:(if e-mail address is provid- be sent) KBALDWI @ GMAI		ipt and shipment will				
E-mail A						
I would like to receive future e						
Gun sometimes drops the firing pin when bolt is operated. This happens without pulling the trigger. Has fired when moved off safety to fire, This also happens without pulling trigger. This has happened for Least the post year, most recently Thanksiving Day. No one has been hurt by the problem.						
Ammunition Information:						
Manufacturer: Tederal Type: Power-Shok						
Other (i.e. bullet weight/type, shot size,						
powder): 130 grain soft Point						
Handload Information:						
Powder Used: Powder Weight.						
Case/Hull Used: Primer Used:						
Bullet Type/Shot Size:	Bullet Type/Shot Size: Reloader Used:					
Firearms Care (Cleaning and Lubrication):						

Brand of cleaning solution used: Hoppes Powder Solvent
How often do you clean the bore? (Months or Number of rounds) Lien Use
How often do you clean the action? (Months or Number of rounds) Every Use
How often do you clean the trigger assembly? (Months or Number of rounds)
Brand of lubricant used: Rem Oil
How often do you lubricate the bore? (Months or Number of rounds) Every Use
How often do you lubricate the action? (Months or Number of rounds)
How often do you lubricate the trigger assembly? (Months or Number of rounds)
Have you reviewed the cleaning and maintenance recommendations on our web site or in our owners manual? > YES YES NO Not specific to this
When was the last time that your firearm was serviced by a Remington authorized repairman/gunsmith?)
What were the services performed?)
Ship your INSURED firearm by either UPS or Parcel Post to:
Remington Arms Co., Inc. Attn: Arms Service Division 14 Hoefler Avenue Ilion, NY 13357
☐ WARNING: DO NOT SEND LIVE OR SPENT SHELLS IN YOUR FIREARM OR IN THE SAME BOX WITH THE FIREARM. THIS IS A VIOLATION OF FEDERAL LAW. IF YOU FEEL YOU MUST SEND SPENT SHELLS PLEASE SEND THEM IN A SEPARATE PACKAGE AND INCLUDE NAME, ADDRESS (WITH ZIP CODE), TELEPHONE AND MODEL AND SERIAL NUMBER OF YOUR FIREARM.
:: Record the serial number of your firearm before sending it. :: Pack your firearm for safety and to prevent further damage in shipping and handling. Preferably, ship in a firearm box. (Note: Original boxes may not be returned.) :: Remove all accessories from your firearm to prevent loss or damage. :: Provide a return address on both the outside and inside the box. Shipments without a proper

return address will be refused.

:: Ship your INSURED firearm by either UPS or Parcel Post. Remington is not responsible for

damage or loss during shipment, so you may elect to purchase insurance from your carrier.

Charge repairs will be processed using the following guidelines:

:: Repairs \$75.00 and under will be completed and returned to you C.O.D. (To avoid C.O.D. Charges, please include your credit card number and expiration date with your gun)

:: For Repairs over \$75.00, you will receive a written estimate detailing the nature of the repair, applicable taxes and shipping. You will have 30 days to approve the repair estimate. Repairs can be paid by check, money order, or credit card (American Express, Discover, MasterCard, or VISA). If you wish, you can expedite repairs over \$75.00 by setting a pre-authorized amount that can be billed to your credit card. We process checks electronically through Check21.



Remington Arms Company, Inc. 870 Remington Drive P. O. Box 700 Madison, NC 27025-0700

ARS LABEL REQUEST FORM

DATE:		12/6/2010	REQUESTED BY:	Dell
QUANTITY:	1		WEIGHT PER PKG:	10 lbs
RLEASE CHECKONE MEDIA COORDINATOR TO MAIL			I WILL MAIL	XXXXX
DESCRIPTION:	Ref # 5306 rifle	·		

LABEL INFORMATION

MAIL LABEL TO: Ken Baldwin
3218 Golden Eye
Katy, TX 77493
Ph: 832-437-3636

RETURN ITEM TC Remington Arms
Attn: Product Service
Ilion, NY

WENEASE COMPLETE AND PARTIS OF THIS FORM AND SEND FOR THE MEDIA COORDINATION

4XX596 DEC 7, 2010 ALL CURR USD 1 OF 1 SVC GNDCOM ACT WT 10.0 LBS TRACKING# 1Z4XX5969065680163 REF 1:KEN BALDWIN/CD/DMF REF 2:5306/RIFLE

HANDLING CHARGE 0.00 SINGLE-PIECE PUB RATE CHRGS: SVC T/P USD DV 0.00 COD 0.00 RS 0.50 DC 0.00 DGD 0.00 SD 0.00 AH 0.00 PR 0.00 SP 0.00 TOT PUB CHG 10.54 PUB+HANDLING 10.54







