

Remington Arms Co., Inc.

Product Service

Legal Case #:4624

Case Information

RE#	Date Opened	Date Opened(PS)	Date Closed	Incident Date	Pre Lit	Lit	Obsolete
197686	6/22/2010	6/25/2010	6/25/2010				

Customer Information

Type	Business	First Name	Last Name	Street	City	State	Zip	Age	Contact
Reporter	Beikirch Ammunition Corp		Beikirch Ammuni	PO Box 151 930 Linden Ave	East Rochester	NY	14445		W 585-248-3660
Incident		Carl	Bestor						H 377-1858 C 645-3216

Incident Information

Claims	Codes	Repair Est.	Medical Treatment	Medical Status
PI				
PD	Cause:4038	Could Not Duplicate Concern		
S	fired when bolt closed twice	Concern:1008 Fired on Bolt Closing	Unknown	
C				

6/30/10 Per note with rifle, the customer purchased it used from someone and it seems like some trigger adjustments were attempted and twice the rifle has gone off when the bolt was closed.cm

Firearm Information

Mfg.	Type	Model/Ga.	SKU	Serial	Bbl.	DOM
Remington	CF/BA	700/3006 SPR	20000	A6411404	BO	1/26/1977
Date Purchased	Where Purchased	Accessories	Original Owner			
	C F WOLFERTZ ALLENTOWN PA	SEE THRU SCOPE RINGS	U			

CONCERN:FBC

Ammunition Information - None Defined

Other Products Information - None Defined

Settlement

Remington/700/CF/BA

Settlement	Release of Claims	Release Date	Reimbursement	Cash Settlement	Reim. Date APV	Cash Date APV
Per Ilion, replace TPA at BLSM program price, \$20 + S&H						
Repair/Replacement Cost	Repair/Replacement Date					

6/30/10 Per Ilion, could not duplicate concern. Replace TPA under bolt lock program for \$20, check over and clean.cm

Examination[Remington/CF/BA]

Part	Sub-Part	Code	Comment
Examination	Examiner		B.TRAVIS
	Exam Date		6/25/2010
	Product Type		RF
	Action Type		A
	Assigned To		F.SUPRY
Cause	4038	Could Not Duplicate Concern	
Barrel	Description		22" 3006 SPR
	Date Code		BO
	Bore Plugged	False	
	Bulged	False	
	Fired	False	

	Fired while Obstructed		
	Muzzle/Crown Condition	Slightly Worn; Functioning	
Bolt	Firing Pin	Slightly Worn; Functioning	
	Shroud	Slightly Worn; Functioning	
	Face	Slightly Worn; Functioning	
	Handle	Slightly Worn; Functioning	
	Stop	Slightly Worn; Functioning	
Extractor	Condition	Slightly Worn; Functioning	
	Cut Condition	Slightly Worn; Functioning	
	Ext/Eject Test	False	
Locking	Block Condition	---Select---	
	Lug Condition	Slightly Worn; Functioning	
	Notch Condition	---Select---	
Overall	Exterior Condition	Slightly Worn; Functioning	
	Stock Condition	Slightly Worn; Functioning	
	Fore End Condition	---Select---	
Receiver	Condition	Slightly Worn; Functioning	
	Bulged	False	
Safety	Description		STANDARD M/700 BOLT LOCK SAFETY
	Function	Like new; Functioning	
Sear	Lift	---Select---	.007
	Notch	Like new; Functioning	
	Tests	Test Fired	False
Feeding Test		False	
Trigger	Condition	Slightly Worn; Functioning	
	Pull	---Select---	4#
	Altered	False	
	Sub-Assembly	M/700 Bolt Lock	
Non-Remington Components	Description		SEE THRU SCOPE RINGS

Arms Services Repair & Estimate System

File Add Repair Estimate Repair Expedite Repair Inquiry Repair Tools CSR Tools Reports Table Maintenance System Maintenance Help

Repair Inquiry

Repair Number: RE00197686 Serial A6411404 Model 700 Center Fire Caliber 3006 SPRG Produced: 01/26/1977 Repairman: James Garney Status: InvoiceHold 6/29/2010 11:20:46 AM

Address Information

Customer: Received From Return To: Received From
Name: BEIKIRCH AMMUNITION CORPORATION BEIKIRCH AMMUNITION CORPORATION
Address 1: 930 LINDEN AVE 930 LINDEN AVE
Address 2: PO Box PO Box
City: EAST ROCHESTER EAST ROCHESTER
State: NY Zip Code: 144450151 Country: US State: NY Zip Code: 144450151 Country: US

FFL:

Contact / Condition	Problems	Estimate	History / Status	Shipping / Billing
				Current Status
Date	User ID	Desc1	Desc2	
6/22/2010 1:17:2	valentds	Repair Added		Shipping Hold
6/24/2010 11:20	penceil	From: Check In	To: Repair Bench	InterFace Hold
6/25/2010 10:06	Travisbw	Repair Maintenance	Status: New	Estimate Sent
6/25/2010 1:15:4	gamseyjk	Estimate Update	Status: Repairing	Parts Received
6/25/2010 3:10:2	penceil	From: Repair Bench	To: Gallery	Passed Inspection
6/26/2010 9:06:1	perrellavc	From: Gallery	To: Final Inspect	Return As Received
6/29/2010 11:20	gamseyjk	Final Inspection	COD	Has been Approved
				Internal Repair

Repair Search

Refresh

Close

supply 16/29/2010 11:31 AM NUM INS

start

Inbox - Microsoft ...


Arms Services Re...

Part Search by M...

DMS - Deal top

DMS - Serial Num...

11:31 AM



BEIKIRCH

AMMUNITION CORPORATION

P.O. Box 151 • 930 LINDEN AVE. • EAST ROCHESTER, N.Y. 14445-0151

PHONES (585) 248-3660 248-3434 FAX (585) 248-3973 (800) 622-3006 ORDERS ONLY!

Invoice Date 6-18-10

Customer # _____

TO Remington Arms Co.
Arms Service Dept.
Attn: New York 13357

Order Date _____

TERMS: NET 20 DAYS FROM D.O.I.
1 1/2% PER MONTH AFTER 20 DAYS

INVOICE

PHONE _____

AMOUNT

Serial A6411404					
Att Service:					
Enclosed please find					
this model 700 BDL 30-06 for the					
following reason - Customer purchased					
it used from someone and it seem					
like some trigger adjustment were					
attempted and twice the risk has					
gone off when the bolt was closed.					
Please checkover and repair as					
necessary to make it safe. Thank you					
Sincerely,					
Carl Bestar.					
645-3216 Cell					
377-1858 Home					
could not duplicate concern					
replace TPA, under bolt lock					
program cost 20.00, checkover					
+ clean.					
Quote					

Serial Number:

A6411404

Model: 700



RE00197686

Invoice - NO BILL TO FOLLOW!

801/77
22"
4#
1007