Remington Arms Co., Inc. Product Service Legal Case #:4869

Case Information

RE# **Date Opened** Date Opened(PS) **Date Closed Incident Date** Pre Lit Lit Obsolete 10/27/2010 12/7/2010

212935

12/6/2010 **Customer Information**

First Last Type Business Street City State Zip Age Contact

Name Name

C 928-205-9245 419 W. Misty Sage Saratoga

Reporter Kevin **Bigelow** UT 84045 E Way Springs pkbigelow86@hotmail.com

Incident Information

FSR

Claims Codes Repair Est. **Medical Treatment Medical Status**

PΙ

PD Cause:4054 As received Follows Down

Unknown Concern:1007 Fired on Safe Release

S \mathbf{C}

10/27/10 Per call from Bigelow, he has a 700 Yth that he bought 4-5 yrs ago. His daughter was using - put a round in the chamber, fired on safe release. During a hunt recently it did the same.cm

Firearm Information

Model/Ga. SKU Mfg. Type Serial Bbl. **DOM** 3/11/2002 7:37:46 G6238390 AW Remington CF/BA 700/243 WIN n/a

AM

Original Date Where Purchased Accessories Purchased Owner

ACUSPORT (MT) TWO PIECE SCOPE

Y CORPORATION **BASE**

CONCERN:FSR

Ammunition Information - None Defined

Other Products Information - None Defined

Settlement

Remington/700/CF/BA

Reim. Cash **Release of Claims** Settlement **Release Date** Reimbursement Date Date Settlement APV APV

Per Ilion, replace trig assm, clean at no charge

> Repair/Replacement Repair/Replacement

Cost Date

47.23 12/10/2010

10/27/10 Sending box, emailing ARS.cm 12/12/10 Per Ilion, will follow down. Trigger assm dirty/rusty, trigger will not return properly. Replace trigg assm, clean and test fire at no charge. Emailed Bigelow results and told him to email or call with any questions.cm

Examination[Remington/CF/BA]

Part	Sub-Part	Code	Comment
Tait	Sub-Part	Code	Comment

http://cps03ap13:200/psaapp/PrintDisplay.aspx?ID=4869&Type=Case


12/12/2010

Cash

Examination	Examiner] .	B.TRAVIS
	Exam Date	1	12/7/2010
	Product Type		RF
	Action Type		Ā
	Assigned To		T.NAGLE
Cause	4054	As received Follows Down	
Barrel	Description		20" 243 WIN
	Date Code	Ī	AW
	Bore Plugged	False	
	Bulged	False	
	Fired	False	
	Fired while Obstructed		•
	Muzzle/Crown Condition	Slightly Worn; Functioning	
Bolt	Firing Pin	Slightly Worn; Functioning	
	Shroud	Slightly Worn; Functioning	
	Face	Slightly Worn; Functioning	
	Handle	Slightly Worn; Functioning]
	Stop	Slightly Worn; Functioning	
Extractor	Condition	Slightly Worn; Functioning	
	Cut Condition	Slightly Worn; Functioning	
	Ext/Eject Test	False	
Locking	Block Condition	Select	
	Lug Condition	Slightly Worn; Functioning	
	Notch Condition	Select	
	Exterior Condition	Slightly Worn; Functioning	METAL RUSTY
Overall	Stock Condition	Slightly Worn; Functioning	
	Fore End Condition	Select	
Receiver	Condition	Slightly Worn; Functioning	
	Bulged	False	
	Description		STANDARD M/700 SAFETY
Safety	Function	Like new; Functioning	
•	Sub-Assembly	ISS	
Sear	Lift	Select	N/A
	Notch	Like new; Functioning	
	Tanto	Test Fired	False
Feeding Test	Tests	False	
Trigger	Condition	Slightly Worn; Not Functioning	DIRTY/RUSTY TRIG WILL NOT RETURN
	Pull	Select	1#
	Altered	False	
	Sub-Assembly	M/700 Non-Bolt Lock	
Non-Remington Components	Description		TWO PIECE SCOPE BASE

http://cps03ap13:200/psaapp/PrintDisplay.aspx?ID=4869&Type=Case

12/12/2010



DEC -8 2010

27. 27. 27

4869

70" 1th AW 3/02

October 27, 2010

Kevin Bigelow 419 W. Misty Sage Way Saratoga Springs, UT 84045

Subject: #4869, Model 700

Dear Mr. Bigelow,

Regarding your contact with Remington and the incident you incurred, you should receive an email with the prepaid UPS ground shipping label for shipment of the firearm to our factory within 24 hours. Please include a copy of this letter with the firearm. The letter inside is important as sometimes the outside label gets damaged in transit and we want to be sure the firearm is logged in correctly. Please mark the ends of the box with "Supry".

I apologize for the inconvenience that this incident has caused and I hope that these actions will keep you as a loyal Remington customer.

Sincerely,

Christy Mitchell Consumer Affairs Administrator Phone: 800-243-9700, ext 8684 christy.mitchell@remington.com

G6238390 Model: 700 RF00212935 WILL Follow down. Trig ASM.
DIRTY/PUSTY, TRIG. WILL NOT RETURN
PROPERLY. Replace TPA, C GAN +
TOST FIRE AT 14/C
23045

Remington Arms Company, Inc. • 870 Remington Drive • P.O. Box 700 • Madison, NC 27025 Phone 800-243-9700 • www.remington.com



Remington Arms Company, Inc. 870 Remington Drive P. O. Box 700 Madison, NC 27025-0700

ARS LABEL REQUEST FORM

DATE:	10/27/2010 REQUESTED BY: christy	
QUANTITY:	1 WEIGHT PER PACKAGE:	10
PLEASECHECKONER MEDIA COORDINATOR TO MAIL	email to: pkbigelow86@hotmail.com WILL MAIL	
DESCRIPTION:	700	

LABEL INFORMATION

MAIL LABEL TO: Kevin Bigelow
Email to him

419 W. Misty Sage Way
Saratoga Springs, UT 84045

RETURN ITEM TO: Remington Product Service

THEASE COMPLETE ALL PARTIS OF THIS FORM AND SEND TO THE MEDIA COORDINATOR

4XX596 OCT 27, 2010 ALL CURR USD SYC CNDCOR: ACT HI 10.0 LBS TREEFINCH 124XX596906812903 RSF 1:KEVIN BIGELOW/SUP/CHPISTY REF 2.760 1 OF 1 HARDLING CHARGE 0.00 STHOLE-PIECE PUB RATE CHRUS: SVC T/P USD DV 6 66 DC 8 66 COD RS 1.00 SD 0.00 0.00 DOD 0.0છ AH 6 60 PR 9.30 SP 6.00 701 PUE CHG 17.29 PUB-HANALTNG

pkbigelow86@hotmail.com



