

Remington Arms Co., Inc.
Product Service
Legal Case #:5311

Case Information

RE#	Date Opened	Date Opened(PS)	Date Closed	Incident Date	Pre Lit	Lit	Obsolete
212376	12/3/2010	12/6/2010	12/6/2010				

Customer Information

Type	Business	First Name	Last Name	Street	City	State	Zip	Age	Contact
Reporter	Bolsa Gunsmithing		Bolsa Gunsmithi	7404 Bolsa Ave	Westminster	CA	92683		W 714-894-9100

Incident Information

Claims	Codes	Repair Est.	Medical Treatment	Medical Status
PI				
PD	Cause:4038	Could Not Duplicate Concern		
S	Fired on bolt closing	Concern:1008 Fired on Bolt Closing	Unknown	
C				

12/19/10 Per note with rifle, closed bolt and a round went off.cm

Firearm Information

Mfg.	Type	Model/Ga.	SKU	Serial	Bbl.	DOM
Remington	CF/BA	700/30-06 SPR	25773	C6795587	KN	5/24/1993
Date Purchased	Where Purchased	Accessories	Original Owner			
	WAL-MART WAREHOUSE #3R	SCOPE,TWO PIECE BASE,RINGS,SHELL HOLDER	U			

CONCERN:FBC

Ammunition Information - None Defined

Other Products Information - None Defined

Settlement

Remington/700/CF/BA

Settlement	Release of Claims	Release Date	Reimbursement	Cash Settlement	Reim. Date APV	Cash Date APV
Per Ilion, replace TPA, clean at 1/2 normal charges						
	Repair/Replacement Cost	Repair/Replacement Date				

12/19/10 Per Ilion, could not duplicate concern. Trig assm set screws altered, has excessive overtravel. Min trigger to trigger guard clearance. Replace TPA, clean, test fire at 1/2 normal cost.cm

Examination[Remington/CF/BA]

Part	Sub-Part	Code	Comment
Examination	Examiner		B.TRAVIS
	Exam Date		12/6/2010
	Product Type		RF
	Action Type		A
	Assigned To		T.NAGLE
Cause	4038	Could Not Duplicate Concern	MIN TRIG TO TRIG GUARD CLEARANCE
Barrel	Description		22" 30-06 SPR
	Date Code		KN
	Bore Plugged	False	
	Bulged	False	
	Fired	False	

	Fired while Obstructed		
	Muzzle/Crown Condition	Slightly Worn; Functioning	
Bolt	Firing Pin	Slightly Worn; Functioning	
	Shroud	Slightly Worn; Functioning	
	Face	Slightly Worn; Functioning	
	Handle	Slightly Worn; Functioning	
	Stop	Slightly Worn; Functioning	
Extractor	Condition	Slightly Worn; Functioning	
	Cut Condition	Slightly Worn; Functioning	
	Ext/Eject Test	False	
Locking	Block Condition	---Select---	
	Lug Condition	Slightly Worn; Functioning	
	Notch Condition	---Select---	
Overall	Exterior Condition	Slightly Worn; Functioning	
	Stock Condition	Slightly Worn; Functioning	
	Fore End Condition	---Select---	
Receiver	Condition	Slightly Worn; Functioning	
	Bulged	False	
Safety	Description		STANDARD M/700 SAFETY
	Function	Like new; Functioning	
	Sub-Assembly	Non-ISS	
Scar	Lift	---Select---	N/A, SCOPE MOUNTED
	Notch	Slightly Worn; Functioning	
	Tests	Test Fired	False
Feeding Test		False	
Trigger	Condition	Slightly Worn; Functioning	
	Pull	---Select---	3#
	Altered	True	SET SCREWS ALTERED EXCESSIVE OVER TRAVEL
	Sub-Assembly	M/700 Non-Bolt Lock	
Non-Remington Components	Description		SCOPE, TWO PIECE BASE, RINGS, SHELL HOLDER

5311
BOLSA GUNSMITHING

7404 BOLSA AVENUE • WESTMINSTER, CALIFORNIA 92683
(714) 894-9100 • FAX (714) 898-9164
www.bolsagunsmithing.com

HOURS:
Mon-Fri. 8:00 a.m. to 5:30 p.m.
Closed Saturday & Sunday

SHIPPED TO: <i>REMINGTON ARMS</i>	Make: <i>Remington</i>	Shipped Date: <i>11-19-10</i>
	Model: <i>700</i>	Gauge of Cal.: <i>30-06</i>
	Serial No: <i>C6795587</i>	

REPAIR INSTRUCTIONS

22"

CLOSED BOLT AND A

ILN 5/93

3#

Round WENT off

PLEASE REPAIR

*Shipped with sling,
scope & Ammo holder*

THANK YOU!

Shipped Via: <i>Fedex</i>	Weight:	Reference No: <i>184210</i>	Packed By:	Value:
------------------------------	---------	--------------------------------	------------	--------

REMARKS:

SHIPPED NOV 19 2010

Serial
Number:

C6795587

Model: **700**



RE00212376

Could not duplicate concern.
T.A. set screws altered, has
Excessive overtravel. Min. + RTG to
trig guard clearance. Replace TPA,
clean + test fire AT 1/2 normal
cost

Quote

magletj - ILN/Prod

RECEIVED
JUN 10 1964

BY: _____









