				Remin	gton Arms Co	o., Inc.							
				Р	roduct Servic	e							
				Le	gal Case #:53	48							
Case Inform	mation												
RE#	Date	Opened	Date Opened(PS) Date		Date Clos	sed Incident Date		Pre Lit Lit Obsole		Obsolete			
217770	1/0	5/2011	12/1/2	2010	1/18/201	1							
Customer I	nformation	1											
Туре	Business	First Name	Last Name Street		eet	City State		e Zip	Zip Age		Contact H 913-608-5796 E lescarruth1@att.net		
Incident Les		Les	Carruth 6414 W 133		Ird Terrace Ove		erland Park KS		66209				
ncident In	formation												
	Claims			Codes			Repair	Est.	Medica	l Treatr	nent	Me	dical Stat
PI													
	n floorboa	rd of truck	Cause:4038	Could Not I	Juplicate Cond	cern				1			
PD hole i	n floorboa when safe			Could Not I 7 Fired on Saf	•	cern			Ur	known			
PD hole i S Fired C	when safe	ty released	Concern:100	7 Fired on Saf	e Release								
PD hole is S Fired C 12/7/10 Per Remington safety has b	when safe r email sen for the Mo been releas	ty released t to Remington odel 700. Spec ed and/or the l		7 Fired on Saf 101125-00007 ondering if a fi closed."cm 1/1	e Release 2, "Could you ix has ever bee 8/11 Per letter	pleas en mae	de to preve	nt the a	here has	ever bee I firing	of this	s gun	when the
PD hole is S Fired C 12/7/10 Per Remington safety has to was closing	when safe r email sen for the Mo been releas g the bolt a	ty released t to Remington odel 700. Spec ed and/or the l	Concern:100 n.com, incid #1 cifically, I'm wo bold has been c	7 Fired on Saf 101125-00007 ondering if a fi closed."cm 1/1	e Release 2, "Could you ix has ever bee 8/11 Per letter	pleas en mae	de to preve	nt the a	here has	ever bee I firing	of this	s gun	when the
PD hole i S Fired C 12/7/10 Per Remington safety has t was closing	when safe r email sen for the Mo been releas g the bolt a	ty released t to Remington odel 700. Spec ed and/or the l	Concern:100 n.com, incid #1 cifically, I'm wo bold has been c	7 Fired on Saf 101125-00007 ondering if a fi closed."cm 1/1 rd of the truck.	e Release 2, "Could you ix has ever bee 8/11 Per letter	pleas en mae	de to preve with rifle, i	nt the a	here has	ever bee I firing	of this red ins	s gun	when the pickup as
PD hole i S Fired C 12/7/10 Pen Remington safety has t was closing Firearm Inf	when safe r email sen for the Mo been releas g the bolt a formation	ty released t to Remington odel 700. Spec ed and/or the l nd put a hole i	Concern:100 n.com, incid #1 sifically, I'm wo bold has been c in the floorboar	7 Fired on Saf 101125-00007 ondering if a fi closed."cm 1/1 rd of the truck.	e Release 2, "Could you x has ever bet 8/11 Per letter cm	pleas en mae	de to preve with rifle, i	nt the a n early SKU n/a	here has accidentz '80's, th	ever bee I firing e gun fir	of this red ins	s gun side a	when the pickup as DOM
PD hole is S Fired C 12/7/10 Per Remington safety has t was closing Firearm Inf N Rem	when safe r email sen for the Mo been releas g the bolt a formation Mfg.	ty released t to Remington odel 700. Spec ed and/or the l nd put a hole i	Concern:100 n.com, incid #1 :ifically, I'm we bold has been o in the floorboar Type	7 Fired on Saf 101125-00007: ondering if a fi closed."cm 1/1 rd of the truck. N 700/: A	2, "Could you (x has ever bea 8/11 Per letter cm Model/Ga.	please en mac sent	de to preve with rifle, i	nt the an early	here has accidentz '80's, th	ever bee d firing e gun fir Seria	of this red ins	s gun side a Bbl.	when the

Settlement

Settlement	Release of Claims	Release Date	Reimbursement	Cash Settlement	Reim. Date (APV	Cash Date APV
Repair at no charge as gesture of goodwill						
R	epair/Replacement Cost	Repair/Replacement Date				
	114.90	1/18/2011				

12/7/10 Mailing ARS.cm 1/18/11 Emailed inspection info to Carruth. Offered to replace trigger with new one without bolt lock at no charge. Awaiting reply.cm 1/18/11 Per email from Carruth, he approves repair.cm

Examination[Remington/CF/BA]

Part	Sub-Part	Code	Comment
	Examiner		B.TRAVIS
	Exam Date		1/7/2011
Examination	Product Type		RF
	Action Type		A
	Assigned To		T.NAGLE
Cause	4038	Could Not Duplicate Concern]
	Description		24" 222 REM MAG
	Date Code		BP
Barrel	Bore Plugged	False	
	Bulged	False	

http://cps03ap13:200/psaapp/PrintDisplay.aspx?ID=5348&Type=Case

2/1/2011

÷

•	Fired	False]
	Fired while Obstructed	}	_
·	Muzzle/Crown Condition	Slightly Worn; Functioning]
	Firing Pin	Slightly Worn; Functioning	
	Shroud	Slightly Worn; Functioning	
Bolt	Face	Slightly Worn; Functioning	
	Handle	Slightly Worn; Functioning	
	Stop	Slightly Worn; Functioning	
	Condition	Slightly Worn; Functioning	
Extractor	Cut Condition	Slightly Worn; Functioning]
	Ext/Eject Test	False	
	Block Condition	Select	
Locking	Lug Condition	Slightly Worn; Functioning]
	Notch Condition	Select	
	Exterior Condition	Slightly Worn; Functioning	· · ·
Overall	Stock Condition	Slightly Worn; Functioning	7
	Fore End Condition	Select	
	Condition	Slightly Worn; Functioning	
Receiver	Bulged	False	
	Description]	M/700 BOLT LOCK SAFETY
Safety	Function	Like new; Functioning]
	Sub-Assembly	Non-ISS]
	Lift	Select	.006
Sear	Notch	Slightly Worn; Functioning]
	Tests	Test Fired	False
Feeding Test		False]
	Condition	Slightly Worn; Functioning	STICKY, TRIGGER WORKS SLUGGISH
Trigger	Pull	Select	4#
1115501	Altered	True	TRIG PULL ADJ
	Sub-Assembly	M/700 Bolt Lock	
Non-Remington Components	Description]	TWO PIECE BASE

•



381/6 1006 4th

December 1, 2010

Les Carruth 6414 W. 133rd Terrace Overland Park, KS 66209

Subject: #5348, Model 700

Dear Mr. Carruth,

Enclosed is the UPS ground prepaid shipping label for shipment of the firearm for inspection at our factory. Please include a copy of this letter with the firearm. The letter inside is important as sometimes the outside label gets damaged in transit and we want to be sure the firearm is logged in correctly. Please mark the ends of the box with "Product Service".

I apologize for the inconvenience that this incident has caused and I hope that these actions will keep you a loyal Remington customer.


Sincerely,

Christy Mitchell Consumer Affairs Administrator Phone: 800-243-9700, ext 8684 christy.mitchell@remington.com

BY:....

enclosure





Remington Arms Company, Inc. • 870 Remington Drive • P.O. Box 700 • Madison, NC 27025 Phone 800-243-9700 • www.remington.com

222 RW

NOTE: Please complete and print this form, and then include it with your firearm.

۰....

.

.

Model Number: 700 ADL	Serial Number: 258309
Are you the original owner?: 🕅 YES 🔽 NO	
Name: LES CARRUTH ~	Date of Purchase: Approx 1974
Address (no PO Boxes): 6414 W. 1	
city: Overland Park	State: KS Zip: 66209
Phone (Daytime): 9/3 - 608-5790	
E-mail Address: (if e-mail address is provided, notificati sent) 105 carruth 1 @ att. Net	on of receipt and shipment will be
E-mail Address:	
I would like to receive future e-mail updates from R	emington.
Please describe your problem and date of occurrence	:e:
See Attached let	tes
	÷.
500 characters left	
Ammunition Information:	
Manufacturer: VANOUS Monufacture	Туре:
Other (i.e. bullet weight/type, shot size, powder):	
Handload Information:	
Powder Used:	Powder Weight:
Case/Hull Used:	Primer Used:
Bullet Type/Shot Size:	Reloader Used:

12-15-10

Remington Arms Company, Inc. 870 Remington Dr. Madison, NC 27025

Dear Sir:

I was attempting to fill out your forms for the enclosed Remington 700 ADL, and thought a letter might provide you with more information.

The rifle was purchased (new) at a Gibson's store in Brownwood, TX approx. the summer of 1974. It was used numerous times with both factory ammunition (various brands) and some reloads (again various components).

I can remember 2 times the accidental discharges happened, but can't tell you which kind of ammunition was used. The first incident happened in 1975 while hunting. The last time was in the early 80's. The circumstances were as follows:

1. The gun fired inside a pickup as I was closing the bolt. The damage was a <u>hole</u> in the <u>floorboard</u> of the truck.

2. The gun fired as it was being unloaded after hunting. It was in a safe direction and there was no damage or injury.

In general, I shot 4-5 boxes of ammunition in the gun/year. Since the last incident, I have been a bit apprehensive and the gun hasn't been used. The gun was well taken care of up to the early 80's incident and has had no modifications or work done on it.

The last lubricant (and what I currently use on my other guns) was Remington Rem.Oil w/Teflon.

If you have any other questions, I can be contacted at:

Les Carruth 6414 W 133rd Terrace Overland Park, KS 66209 <u>lescarruth1@att.net</u> 913-608-5796 (H) 903-521-4269 (C)

Yours traily,

a Count

Les Carruth

Firearn	s Care (Cleaning and Lubrication):
Brand o	f cleaning solution used:
How oft	en do you clean the bore? (Months or Number of rounds) & Hur each use
How oft	en do you clean the bore? (Months or Number of rounds) after each use en do you clean the action? (Months or Number of rounds) after each use
	en do you clean the trigger assembly? (Months or Number of rounds) after each u:
Brand o	f lubricant used:
How oft	en do you lubricate the bore? (Months or Number of rounds)
How of	en do you lubricate the action? (Months or Number of rounds)
How oft	en do you lubricate the trigger assembly? (Months or Number of rounds)
	ou reviewed the cleaning and maintenance recommendations on our web site or in our owners man
When w	ras the last time that your firearm was serviced by a Remington authorized
repairm	an/gunsmith?) at factory when New
What w	ere the services performed?)
1	Remington Arms Co., Inc. Attn: Arms Service Division 14 Hoefler Avenue Ilon, NY 13357
FIREAR THEM II	NING: DO NOT SEND LIVE OR SPENT SHELLS IN YOUR FIREARM OR IN THE SAME BOX WITH TH M. THIS IS A VIOLATION OF FEDERAL LAW. IF YOU FEEL YOU MUST SEND SPENT SHELLS PLE N A SEPARATE PACKAGE AND INCLUDE NAME, ADDRESS (WITH ZIP CODE), TELEPHONE AND M NUMBER OF YOUR FIREARM.
:: Pack y ship in :: Remo :: Provic	d the serial number of your firearm before sending it. your firearm for safety and to prevent further damage in shipping and handling. Preferably, a firearm box. (Note: Original boxes may not be returned.) ve all accessories from your firearm to prevent loss or damage. le a return address on both the outside and inside the box. Shipments without a proper address will be refused.

•'

.

Incident - 101125-000072 - Model 700

Reference # 101125-000072 Status Unresolved Assigned To Not specified SLA Not specified Queue CSR

Date Created

11/25/2010 04:41 PM

Initial Response None

Last Updated

11/25/2010 04:41 PM

Customer SmartSense +2 (on -3 to +3 scale)

Staff SmartSense 0 (on -3 to +3 scale) Model 700

Discussion Thread

Customer (Les Carruth) Re: Model 700 ADL, 222 rem.mag., serial # 258309

Could you please let me know if there has ever been a recall by Remington for the Model 700. Specifically, I'm wondering if a fix has ever been made to prevent the accidental firing of this gun when the safety has been released and/or the bold has been closed.

This has happened to me and I would like to know your remedy.

Thank you,

Les Carruth lescarruth1@att.net 913-608-5796

Primary Contact

First Name: Les Last Name: Carruth Organization:

Login: lescarruth1@att.net Title: Contact Type: Emáil: lescarruth1@att.net Email - Alternate #1:

Email - Alternate #2: Office Phone:

Mobile Phone: Fax: Assistant Phone: Home Phone:

> Street City State/Province Postal Code Country

Additional Information

5349

11/25/2010 04:41 PM

http://remington.custhelp.com/cgi-bin/remington.cfg/php/admin/display/inc_print.php?p_sid=... 11/30/2010



• • • •

Remington Arms Company, Inc. 870 Remington Drive P. O. Box 700 Madison, NC 27025-0700

ARS LABEL REQUEST FORM

DATE:	12/7/2010 REQUESTED BY:	christy	
QUANTITY:	1 WEIGHT PER PACKAG	GE:	10
REASE CHECKIONER MEDIA COORDINATOR TO MAIL	I WILL MAIL	xxx	
DESCRIPTION:	700		

LABEL INFORMATION

MAIL LABEL TO:	Les Carruth 6414 W 133rd Terrace Overland Park, KS 66209	
RETURN ITEM TO:	Rem Prod Serv	

REASE COMPLETE ALL PARTS OF THIS FORM AND SEND TO THE MEDIA COORDINATOR

 4XX596
 DEC 8, 2010
 ALL CURR USD
 1 OF 1

 SVC GNDCOM
 ACT WT 10.0 LBS
 1 OF 1

 TRACKING# 124XX5969066117094
 REF 1:LES CARRUTH/CD/CM
 REF 2:700

 HANDLING CHARGE 0.00
 SINGLE-PIECE PUB RATE CHRGS:
 SVC T/P USD

 DV 0.00
 COD 0.00
 RS 0.50

 DV 0.00
 DGD 0.00
 SD 0.00

 AH 0.00
 PR 0.00
 SP 0.00

 TOT PUB CHG 9.45
 PUB+HANDLING 9.45

