Remington Arms Co., Inc. Product Service Legal Case #:4929

Case Infor	mation									
RE#	E# Date Opened		Date Opened(PS	6) Date Closed	d Incident Date		e P	re Lit	Lit	Obsolete
210465	5 11/16/2010		11/2/2010	12/7/2010	10/	10/26/2010				
Customer	Information	n								
Туре	Business	First Name	Last Name	Street	City	State	Zip	Age		Contact
Incident		Robert	Clifford	5324 Willow Ln.	Vermilior	OH	44089			40-967-2556 40-213-7101
Incident In	formation									
C	Claims		Codes			Repair Est. Medical Treatment Medical Status				
PI										
PD Shot h truck S	iole in renta	Cause.40	ause:4038 Could Not Duplicate Concern oncern:1007 Fired on Safe Release			Unknown				
C FSR										
unload the	gun & whe	en he switched	from Safe to Fir	Gun was loaded ins e, the gun went off & . He feels that it can	& shot a hol	e in the t	ruck. No			
Firearm In	formation									
Mfg.		Туре		Mode	I/Ga. SKU		CU	Ser	ial 1	Bbl. DOM
Reming	Remington		CF/BA		REM MA n/a		6871	367	PZ 6/1/1975	
Date Pure	chased	Where Purchased		Access	sories	Original)riginal Owner			
	· PA	AUL BUNYAN MINNEAPOLIS MN		IS MN SCOPE	BASE	BASE Y				
CONCERN	N.COD									

CONCERN:FSR

Ammunition Information - None Defined Other Products Information - None Defined Settlement Remington/700/CF/BA Cash Reim. Cash **Release of Claims Release Date** Settlement Reimbursement Date Date Settlement APV APV Repair @, n/c goodwill gesture Repair/Replacement Repair/Replacement Date Cost 12/7/2010 \$79.73

11/2/10: Sending ARS, letter, form & box. Box order# 1154670. df 11/22/10: I left customer a msg to call me. I will have the factory remove the bolt lock & replace the trigger @ n/c - gesture of goodwill. df 12/1/10: Cust. called me back. He agreed to repair but stated he will never trust rifle again. I went over the report w/him. I will close case when I get parts listing. df 12/7/10: Got parts list - closed case. df

Examination[Remington/CF/BA]

Part	Sub-Part	Code	Comment		
	Examiner		F.SUPRY		
	Exam Date		11/17/2010		

http://cps03ap13:200/psaapp/PrintDisplay.aspx?ID=4929&Type=Case

12/7/2010

.

.

	Product Type		RF
Examination	Action Type		A
	Assigned To]	F.SUPRY
Cause	4038	Could Not Duplicate Concern	
	Description		24" 7MM REM MAG
	Date Code]	PZ
	Bore Plugged	False	1
Barrel	Bulged	False	
Darrei	Fired	False	
	Fired while Obstructed		-
	Muzzle/Crown Condition	Slightly Worn; Functioning	
	Firing Pin	Slightly Worn; Functioning	Ĩ
	Shroud	Slightly Worn; Functioning	
Bolt	Face	Slightly Worn; Functioning	
	Handle	Slightly Wom; Functioning	1
	Stop	Slightly Worn; Functioning	
	Condition	Slightly Worn; Functioning	
Extractor	Cut Condition	Slightly Worn; Functioning	
	Ext/Eject Test	False	
	Block Condition	Select	
Locking	Lug Condition	Slightly Worn; Functioning	
	Notch Condition	Select	1
	Exterior Condition	Slightly Worn; Functioning]
Overall	Stock Condition	Slightly Worn; Functioning	1
	Fore End Condition	Select	
D	Condition	Slightly Worn; Functioning]
Receiver	Bulged	False]
	Description]	STANDARD M/700 BOLT LOCK SAFETY
Safety	Function	Like new; Functioning]
	Sub-Assembly	Non-ISS]
	Lift	Select	.007
Sear	Notch	Slightly Worn; Functioning]
	T	Test Fired	False
Feeding Test	Tests	False]
	Condition	Slightly Worn; Functioning	FUNCTIONS OKAY FAIRLY CLEAN
Teleson	Pull	Select	6#
Trigger	Altered	False	
	Sub-Assembly	M/700 Bolt Lock]
Non-Remington Components	Description		SCOPE BASE

12/7/2010

rmRe	pairMain :	FGI Repairs	na si Ne Ceran Astrophysicaetae	e ferter ungestandster v	na nana angar Ng pananana	epinenter strategian.	in an	an a	an a	n ing sa na minana ing sa na minana. Nang sa na	
			lepair Expe				CSR Tools	Reports	Table Maintenance	System	
					:				<u> </u>		
	æ	frmREInquir	y . Repair Inc	uiry	ana ing mangana ang mangan Sa sa	t Burger and the	en e		and the second		
	1975		RE0021046	Senal P		idel 700 (Center F					
	100	Verily Repairs		MM RÉI					is: Parked 11/17/2010 7	40 17 AM	
										43 I I AM	
	54 	じょう りゅうやい しんどうしょう	Customer 🔆			· · · Received In	m Return T	0	С й	eceived from	
		Name /	ROBERT CLIFF	DRD		ATISO B.	ROBERT	CLIFFORD			
		際といる場所	5324 WILLOW I	ANE	tetet	<u> </u>	5324 WIL	LOW LANE	РО Вок		
		Address 2	VERMILION		PO Box,	<u></u>	VERMILIO	<u></u>	PO Box		
		And the second second	OH Zip Cod	é 44089	Country	US		p Code 440	89 Country US		11월 21일 12일 - 12일 12일 - 12일
				n na ana ang sa sa sa sa sa sa Tang sa	-1010-045 -1010-045	FFL.			<u>г так так так так так так так так так так</u>	<u></u>	
		And the state of some								and the second second	
	wir S	Lontact / Londit		Estimate Thisu	ily / Status	Shipping / Billing				Status	
	Č1	2. In the second second second second	the second s			AMPENTER S		Shipping H	no APa	rked	00
		11/16/20107 11/16/20107		VALENTDS	Repair Ac From: Cho		1 132	Cinterface H Estimate Se	A F A R Y & B F	0 7 49 17 AM	.00
		11/17/2010 7		Travisbw	· · ·	aintenance	Status: Estim	Parts Recei	and the state of the second of the	Services	00
		11/17/20107			•	PS Back Rack	hats far allow	, Passed Inst Return as P	lection / S	LN	.00
						,		Has Been A	a contraction of the state of the contraction of the	ocation	00
						al de la caracteria de la	THE PARTY AND AND A TO A	 Internal Rep 	2		es
					an a	业业的学习和为 4.5.2.2.2.4.0.0.0		Exclude TA			
	20	Repair Se	arch.						Refres	h Close	
	. 17	\$1. E. M. 17 48	an a	16) 7 19 57 5	els Exhibits		MARCHESS	N. 18 . 34	and the second	AND THE REAL PROPERTY	19 19 19 19 19 19 19 19 19 19 19 19 19 1
				Cl.	A states		and the second second				
			- '								
	i ka c							í í	SfrmRfl	× 🖫 frmREI	6 TX
120200	Contraction of the second second						NAGLETJ	U 1914-1714		7 2010	A second second second
nagie	tj. ILN/Prod	R. M. M. W. K.	A STATISTICS	oarMain 🐴 🗧	Sec. Barthe	不 行。""你们,你们们们	SCARAGARANOS MIL	10 gal - 1 gal	A STATE AND A STAT	はなな見たない。「「「「「」」	and the second

DECERVED NOV 1 8 2010 BY:_____

PS 12201

COPY

226/7

00

November 2, 2010

Robert Clifford 5324 Willow Ln. Vermilion, OH 44089 Ph: 440-967-2556

Ref: # 4929

Dear Mr. Clifford,

Enclosed is a prepaid UPS shipping label to cover shipment of your firearm to our factory for examination.

Please include a copy of this letter to put inside the shipping container. The letter inside is important as sometimes the outside label gets damaged in transit and we want to be sure the firearm is logged in correctly. Mark the ends of the boxes with the name "Supry". Mr. Supry will be inspecting the firearm and will contact me with the results.

I hope that this action will keep you a loyal Remington customer.

Sincerely, D. Fulcher Consumer Affairs Administrator Remington, H&R, Marlin Phone: 1-800-243-9700 Fax: 336-548-7872



Remington Arms Company, Inc. • 870 Remington Drive • P.O. Box 700 • Madison, NC 27025 Phone 800-243-9700 • www.remington.com

FROM: ROBERT CLIFFORD

. .

۰,

The incident occurred on October 26, 2010 while hunting in Montana. The rifle was laying in an open soft case on the back seat of the rental Suburban. At the end of the day I went to unload the rifle. In order to do that, I had to take the safety off, bolt the rifle to remove the shell from the chamber and unload the magazine. When I took the safety off, the rifle discharged, shooting the bullet through the case, the surface of the seat and exiting through the door of the truck. Fortunately, no one was in the path of the bullet!

I no longer have any confidence in this rifle whatsoever and continue to be negatively affected by this incident. I do not want to sell or trade the rifle and have someone else have a potential accident with it. I would prefer that Remington replace it with another rifle of equal or greater value and one that does not require putting the safety in the "off" position in order to bolt it and remove ammunition. I look forward to your response and if you have further questions, do not hesitate to call.

Home phone: 440-967-2556 Cell phone: 440-213-7101



Model Number: 700	Serial Number: 687/387
Are you the original owner?: XYES INO	
	Date of Purchase: French - m > 1071
	Date of Purchase: EST, EANLy DMid 1970'S
Address (no PO Boxes): 5324 Willo	
city: VERMILION	State: 0H Zip: 44089
Phone (Daytime):440-967-2556	Fax:
E-mail Address: (if e-mail address is provided, notificat	
sent) PMC_5324@AOL.CO	
E-mail Address:	emington.
Please describe your problem and date of occurren	
	. i
	¥
500 characters left	
Arnmunition Information:	
Manufacturer: REMINGTON	Type: Express Core. LOUT
Other (i.e. bullet weight/type, shot size, powder):	GR TIMM ROM, MAGNIM
Handload Information:	····
Powder Used:	Pawder Weight.
Cese/Hull Used:	Primer Used:
Bullet Type/Shot Size:	Reloader Üsed:
Firearms Care (Cleaning and Lubrication): CLEAN	ed + Lobricated AFTER EACH
Brand of cleaning solution used: 140 ppes	Howing Trip.
fow often do you clean the bore? (Months or Number o	frounds)
How often do you clean the action? (Months or Number	of rounds)
	or Number of rounds)
low often do you clean the trigger assembly? (Months of	
How often do you clean the trigger assembly? (Months of Brand of lubricant used: Hoppers	

http://www.remington.com/support/repair_services/factory_repair_form.asp

....

`

11/24/2009

· ·	nd maintenance recommendations on our web site or in our owners manual?	
YES NO NOT I	RECENTLY	
When was the last time that your fir	rearm was serviced by a Remington authorized	
repairman/gunsmith?) NEVE		
What were the services performed?	n <u>aila</u>	
what were the services penormeon	?) <u>··· /P</u>	
Ship your INSURED firearm by eith	her UPS or Parcel Post to:	
Remington Arms Co.,	Inc.	
Attn: Arms Service Div		
14 Hoefler Avenue		
llion, NY 13357		
·		
	OR SPENT SHELLS IN YOUR FIREARM OR IN THE SAME BOX WITH THE	
	FEDERAL LAW, IF YOU FEEL YOU MUST SEND SPENT SHELLS PLEASE SEND ND INCLUDE NAME, ADDRESS (WITH ZIP CODE), TELEPHONE AND MODEL AND	
SERIAL NUMBER OF YOUR FIREAR		
:: Record the serial number of your fire	earm before sending it.	
:: Pack your firearm for safety and to p	prevent further damage in shipping and handling. Preferably,	
ship in a firearm box. (Note: Original :: Remove all accessories from your fi		
.: Privide a return address on both the	e outside and inside the box. Shipments without a proper	
return address will be refused.		
:: Ship your INSURED firearm by eithe	er UPS or Parcel Post, Remington is not responsible for	
demage or loss during snipment, so	you may elect to purchase insurance from your carrier.	
Charge repairs will be processed using	g the following guidelines:	
	mpleted and returned to you C.O.D. (To avoid C.O.D. Charges, please include your	
credit card number and expiration date	e with your gun)	
	ceive a written estimate detailing the nature of the repair, applicable taxes and shipping.	
	repair estimate. Repairs can be paid by check, money order, or credit card (American	

© 2009 Remington Arms Company, Inc. All Rights Reserved. Investor Relations | Other Remington Brand Products | Legal Notices | About Us Visit Our Other Websites

• ••



.

.

http://www.remington.com/support/repair_services/factory_repair_form.asp

11/24/2009



· · ·

Remington Arms Company, Inc. 870 Remington Drive P. O. Box 700 Madison, NC 27025-0700

ARS LABEL REQUEST FORM

DATE:		11/2/2010	REQUESTED BY:	Dell
QUANTITY:		1	WEIGHT PER PACK	(A) 10 lbs
RIEASECHECKONE MEDIA COORDINATOR TO MAIL			 WILL MAIL 	XXXXXX
DESCRIPTION:	Ref# 4929 Rifle			

LABEL INFORMATION

MAIL LABEL TO: Robert Clifford 5324 Willow Ln. Vermilion, OH 44089 Ph: 440-967-2556

RETURN ITEM TC Remington Arms Attn: Product Service Ilion, NY

PLEASE COMPLETE ALL PARTS OF THIS FORM, AND SEND TO THE MEDIA COORDINATION

 4XX596
 NOV 2, 2010
 ALL CURR USD
 i of 1

 SVC GNDCOM
 ACT UT 10.0 LBS
 i of 1

 TRACKINGH 124XX5969066222058
 I REF 1:ROBERT CLIFFORD/CD/UMF

 REF 1:ROBERT CLIFFORD/CD/UMF

 REF 2:4929/RIFLE

 HANDLING CHARGE 0.00

 SINGLE-PIECE PUB RATE CHRGS.
 SVC T/P USD

 DV 0.60
 COD 0.00
 RS 0.50

 DC 0.00
 BCD 0.00
 SD 0.00

 AH 0.00
 PR 0.00
 SP 0.00

 TOT PUB CHC 8 24
 PUB+HANDLING 8.24







