Remington Arms Co., Inc. Product Service Legal Case #:5061

	-	~	. •
Case	ln.	tom	ation

RE# **Date Opened** Date Opened(PS) **Date Closed Incident Date** Pre Lit Lit Obsolete

11/9/2010

Customer Information

Business First Name Last Name Street City Type State Zip Age Contact

101 Donaldson Rd West Incident Terry Eades Blenheim SC 29516

Incident Information

Medical Medical Codes Claims Repair Est. **Treatment** Status

ΡI

PD Fired when pushing round

Cause:4079 Other - Unexamined

Unknown Concern: 1008 Fired on Bolt Closing

S into chamber

C

11/11/10 Per email sent to Remington.com, incid 101025-000191, "I have a Model 700 30-06 that I love. However, when recently sighting in my scope, the rifle fired as soon as I jacked the next cartridge into the chamber. My finger was nowhere near the trigger. Where can I get this fixed?".cm

Firearm Information

Mfg.

Type

Model/Ga.

SKU

Serial Bbl. **DOM**

Remington **Date Purchased**

CF/BA Where Purchased

700/30-06 Accessories

n/a **Original Owner**

U

Ammunition Information - None Defined Other Products Information - None Defined

Settlement

Remington/700/CF/BA

Release of Claims Settlement

Release Date

Reimbursement

Cash Settlement Reim. Date Cash Date APV APV

Repair/Replacement

Repair/Replacement

Cost

Date

11/11/10 Emailing ARS and letter.cm

Examination[Remington/CF/BA]

Sub-Part Code Part Comment Reference # 101025-000191

Status Updated

Assigned To Administrators Christy -

Product Ammunition

SLA

Not specified

Queue CSR

Date Created 10/25/2010 09:42 PM

Initial Response 11/09/2010 10:11 PM

Last Updated 11/10/2010 10:26 AM

Customer SmartSense +1 (on -3 to +3 scale)

Staff SmartSense +1 (on -3 to +3 scale)

Model 700 repair

Discussion Thread

Customer (1 Terry)

Address is Terry Eades 101 Donaldson Rd W Blenheim SC 29516

On Nov 9, 2010, Remington Information wrote:

Response (Christy -)

11/09/2010 10:11 PM

11/10/2010 10:26 AM

Mr. Eades, I apologize for the delay in responding. I can email a prepaid UPS ground shipping label to pay shipping of your rifle to our factory for a free inspection. Let me know what address to put on the label as the return address. It will require an adult signature upon delivery.

5061

Customer (1 Terry)

10/25/2010 09:42 PM

I have a Model 700 30-06 that I love.

However, when recently sighting in my scope, the rifle fired as soon as I jacked the next cartridge into the chamber. My finger was nowhere near the trigger.

Where can I get this fixed?

Thanks, Terry Eades

Primary Contact

First Name: 1 Last Name: Terry Organization:

Login: petvet62@hughes.net

Title:

Contact Type:

Email: petvet62@hughes.net

Email - Alternate #1: Email - Alternate #2: Office Phone:

Mobile Phone: Fax:

Assistant Phone: Home Phone:

Street City State/Province Postal Code Country

Additional Information

http://remington.custhelp.com/cgi-bin/remington.cfg/php/admin/display/inc_print.php?p_sid=... 11/11/2010



Remington Arms Company, Inc. 870 Remington Drive P. O. Box 700 Madison, NC 27025-0700

ARS LABEL REQUEST FORM

DATE:	11/11/2010	REQUESTED BY:	christy			
QUANTITY:	1	WEIGHT PER PACKAGE:		10		
RUEASE CHECK ONE N MEDIA COORDINATOR TO MAIL	Email to him at: petvet62@hughes.net	I WILL MAIL				
DESCRIPTION:	700					
LABEL INFORMATION						
MAIL LABEL TO:	Terry Eades 101 Donaldson Rd W Blenheim, SC 29516 Email to him at: petvet62@hughes.net Rem Prod Serv					
· ,		NOV 11, 2010 ALL CURR ACT WT 10.0 LBS XX5969067618407 ADES/CD/CM	usp 1 OF 1)B		

petvet62@hughes.net

HANDLING CHARGE 0.00 SYSINGLE-PIECE PUB RATE CHRGS: SYDV 0.00 COD 0.00 DGD 0.00 DGD 0.00 PR 0.00 PR 0.00 PUB+HANDLING TOT PUB CHG 9.24 SVC T/P USD RS 1.00 SD 0.00 0.00 9.24 SP

) First Live