Remington Arms Co., Inc. Product Service Legal Case #:5379

Case Information

RE# Date Opened Date Opened(PS) Date Closed Incident Date Pre Lit Lit Obsolete
213587 12/9/2010 12/10/2010 12/10/2010

Customer Information

Type **Business** First Name Last Name Street City State Zip Age Contact 5244 Cobblestone Rd Sheffield Village W 440-934-8222 Reporter Gander Mt Gander Mt OH 44035

Incident Information

Claims Codes Repair Est. Medical Treatment Medical Status

PΙ

C

PD Cause:4038 Could Not Duplicate Concern

S Fires on bolt closing

Concern:1008 Fired on Bolt Closing

Unknown

12/19/10 Per note with rifle, gun has went off 2 times when chambering rounds plus seem to be a lot of brass in and around the extrator and ejector.cm

Firearm Information

Mfg. Type Model/Ga. SKU Serial Bbl. DOM

Remington CF/BA 700/243 WIN 27495 G6226926 LX 2/10/2003 9:39:12 AM

Date Purchased Where Purchased Accessories Original Owner

BILL HICKS & CO LTD SCOPE BASE U

CONCERN:FBC

Ammunition Information - None Defined
Other Products Information - None Defined
Settlement

Remington/700/CF/BA

Settlement Release of Claims Release Date Reimbursement Cash Reim. Date Cash Date
Settlement APV APV

Per Ilion, replace TPA at no charge to restore confidence

Repair/Replacement Repair/Replacement

Cost Date 47.23 12/19/2010

12/19/10 Per Ilion, could not duplicate concern. Trig assm is dirty. Replace TPA to restore confidence in rifle at no charge.cm

Examination[Remington/CF/BA]

Part	Sub-Part	Code	Comment
	Examiner		B.TRAVIS
	Exam Date		12/10/2010
	Product Type		RF
	Action Type		A
	Assigned To		T.NAGLE
Cause	4038	Could Not Duplicate Concern	
Barrel	Description		26" 243 WIN HB
	Date Code		LX
	Bore Plugged	False	
	Bulged	False	
	Fired	False	
	Fired while Obstructed		_
	Muzzle/Crown Condition	Slightly Worn; Functioning	

http://cps03ap13:200/psaapp/PrintDisplay.aspx?ID=5379&Type=Case

12/19/2010

	Firing Pin	Slightly Worn; Functioning	
Bolt Extractor Locking Overall	Shroud	Slightly Worn; Functioning	
	Face	Slightly Worn; Functioning	
	Handle	Slightly Worn; Functioning	
	Stop	Slightly Worn; Functioning	
	Condition	Slightly Worn; Functioning	
	Cut Condition	Slightly Worn; Functioning	
	Ext/Eject Test	False	
	Block Condition	Select	
	Lug Condition	Slightly Worn; Functioning	·
	Notch Condition	Select	
	Exterior Condition	Slightly Worn; Functioning	
	Stock Condition	Slightly Worn; Functioning	
	Fore End Condition	Select	
	Condition	Slightly Worn; Functioning	·
Receiver	Bulged	False	
	Description		STANDARD M/700 SAFETY
	Function	Like new; Functioning	
	Sub-Assembly	ISS	
Sear ·	Lift	Select	.009
	Notch	Slightly Worn; Functioning	
	Tests	Test Fired	False
Feeding Test	1 ests	False	
Trigger	Condition	Slightly Worn; Functioning	DIRTY
	Pull	Select	4.5#
	Altered	False	
	Sub-Assembly	M/700 Non-Bolt Lock	
Non-Remington Components	Description		SCOPE BASE



Service Request

Service Order # 4422

SHIPPED TO VENDOR/STORE:

Remington Repair FFL# 6-16-00726 14 Hoefler Ave

Ilion, NY 13357 Attn: service dept.

Date Shipped: 11/23/2010

Phone: (800) 243-9700

RETURN SHIP TO:

Gander Mountain, FFL# 4-34-093-01-7B-0116

Attn: Gun Parts Dept. 5244 Cobblestone Rd Sheffield Village, OH 44035

FIREARM INFORMATION:

Manufacturer: Remington Arms Co Inc.

Rifle Type:

Serial Number: G6226926

Model: 700 Cal/Ga.: 243 win.

Cased?:

DESCRIPTION OF ITEM RETURNED:

- (1) complete rifle
- (2) good

REASON FOR RETURN:

gun has went off (2) times when chambering rounds, plus seem to be a lot of brass in & around extractor & ejector.

ATTENTION VENDOR

Please contact me with any questions or concerns.

Josh Armstrong (440) 934-8222

BILLING INFORMATION:

Please include the service order number on all invoices and correspondence:

SHIP TO ABOVE ADDRESS

Forward all invoices to.

Gander Mountain Company

Attn: Roy Christensen

180 E. Fifth Street Suite 1300

St. Paul, MN 55101

could not diplicate workens. T.A. is DIRty. Replace TPA TO rustone confidence in rifte AT H/C

#230145

₿G6226926

Model:

700













