

Remington Arms Co., Inc.

Product Service

Legal Case #:4967

Case Information

RE#	Date Opened	Date Opened(PS)	Date Closed	Incident Date	Pre Lit	Lit	Obsolete
209140	11/3/2010	11/4/2010	11/16/2010				

Customer Information

Type	Business	First Name	Last Name	Street	City	State	Zip	Age	Contact
Incident		Jimmy B	Gunter Jr	3706 Brakefield Dairy Rd	Jasper	AL	35503		H 205-387-8316

Incident Information

Claims	Codes	Repair Est.	Medical Treatment	Medical Status
PI				
PD shot hole in wall, furniture	Cause:4006 Altered Adjustments or Components			
S Fired when cycling the bolt	Concern:1025 Unexplained Discharge - No Mention of Safety Position		Unknown	
C				

11/16/10 Per letter with rifle, "after a trip to the firing range, (I) was unloading (his) rifle, by cycling the ammo, using the bolt. (He) had removed a couple of rounds when (he) cycled the bolt, the rifle fired, shot a hole through a wall, two pieces of furniture and out a window! This is the only time it happened, so to be on the safe side, (he) stored it in (his) gun safe until after talking with one of (our) reps named Logan." He would like to take advantage of our Safety Mod Program.cm

Firearm Information

Mfg.	Type	Model/Ga.	SKU	Serial	Bbl.	DOM
Remington	CF/BA	700/30-06 SPR	n/a	A6829565	EV	10/18/1979
Date Purchased	Where Purchased	Accessories	Original Owner			
7/17/1981	WALTER CRAIG SELMA AL	TWO PIECE BASES	U			

CONCERN:FBC,WENT THRU WALL AND FURNITURE

Ammunition Information - None Defined

Other Products Information - None Defined

Settlement

Settlement	Release of Claims	Release Date	Reimbursement	Cash Settlement	Reim. Date APV	Cash Date APV
Replace TPA, clean at 1/2 normal charges						
	Repair/Replacement Cost	Repair/Replacement Date				

11/16/10 Per Ilion, Trig assm not of Rem Mfg (Timney TPA installed). Quote to replace TPA at 1/2 normal charges or return as received. I spoke with Gunter and he agreed to pay \$75.50 + tax to have the trigger replaced with a Remington factory trigger.cm

Examination[Remington/CF/BA]

Part	Sub-Part	Code	Comment
	Examiner		B.TRAVIS

Examination	Exam Date	11/4/2010	
	Product Type	RF	
	Action Type	A	
	Assigned To	F.SUPRY	
Cause	4006	Altered Adjustments or Components	
Barrel	Description	22" 30-06 SPR	
	Date Code	EV	
	Bore Plugged	False	
	Bulged	False	
	Fired	False	
	Fired while Obstructed		
	Muzzle/Crown Condition	Slightly Worn; Functioning	
Bolt	Firing Pin	Slightly Worn; Functioning	
	Shroud	Slightly Worn; Functioning	
	Face	Slightly Worn; Functioning	
	Handle	Slightly Worn; Functioning	
	Stop	Slightly Worn; Functioning	
Extractor	Condition	Slightly Worn; Functioning	
	Cut Condition	Slightly Worn; Functioning	
	Ext/Eject Test	False	
Locking	Block Condition	---Select---	
	Lug Condition	Slightly Worn; Functioning	
	Notch Condition	---Select---	
Overall	Exterior Condition	Worn; Functioning	GREASE APPLIED TO THE ACTION UNDER THE STOCK
	Stock Condition	Worn; Functioning	
	Fore End Condition	---Select---	
Receiver	Condition	Slightly Worn; Functioning	
	Bulged	False	
Safety	Description		NOT OF REM MFG
	Function	---Select---	
Tests	Test Fired	False	
	Feeding Test	False	
Trigger	Condition	---Select---	NOT OF REM MFG (TIMNEY)
	Pull	---Select---	2.5#
	Altered	False	
Non-Remington Components	Description	TWO PIECE BASES AND TPA	

frmRepairMain - FGI Repairs

File Add Repair Estimate Repair Expedite Repair Inquiry Repair Tools CSR Tools Reports Table Maintenance System

frmREInquiry - Repair Inquiry

Repair Number: RE00209140 Serial: A5829565 Model: 700 Centre Fire Caliber: 30.06 SFRG Produced: 10/18/1979 SKU: 20000 Repairman: Status: Parked 11/4/2010 11:46:23 AM

Verify Repair

ADDRESS INFORMATION

Customer: Received from Return To: Received from

Name: JIMMY GUNTER JR JIMMY GUNTER JR

Address 1: 3706 BRAKEFIELD DAIRY ROAD 3706 BRAKEFIELD DAIRY ROAD

Address 2: PO Box PO Box

City: JASPER JASPER

State: AL Zip Code: 35503 Country: US AL Zip Code: 35503 Country: US

FPL:

Contact / Condition Problems Estimate History / Status Shipping / Billing

Date	Code	User ID	Desc1	Desc2	Current Status
11/3/2010 9:55	New	schultscm	Repair Added		Parked
11/3/2010 9:55	Expedite	schultscm	From: Check In	To:	11/4/2010 11:46:23 AM
11/4/2010 11:46	Maint	Treviaww	Repair Maintenance	Status: Estm	Product Services
11/4/2010 11:46	ParkedExt	Treviaww	Placed in PS Back Rack	hold for disp	Repair Location

Shipping Hold ☐ Interface Hold ☐ Estimate Sent ☐ Parts Received ☐ Passed Inspection ☐ Return as Received ☐ Has Been Approved ☐ Internal Repair ☐ Exclude TATC ☐

Current Location: ILN

Transfer Number: ILN

Repair Search Refresh Close

start | DMS-Desktop | frmRepairMain | D1102R7XPL | Wednesday, Nov 3 2010 | 1:25 PM

The trigger is this gun is not a Remington trigger assembly it is a TIMNEY, OFFER TO replace it with a Remington X-MARK PRO at a Special price.

Free 11/4/10

REDACTED

8356 exp. 6/12

Trig 47.00
Shp. 17.-
Test 11.50
75.50
+ tax

RECEIVED
NOV - 5 2010

BY:

4967


 221
 EV 10/7
 2.6

Model Number: <i>Rem 700</i>		Serial Number: <i>A6829565</i>	
Name: <i>Jimmy B. Gunter, Jr.</i>		Date of Purchase: <i>7/17/81</i> ^{<i>Picked up</i>} _{<i>(Approximately a month later)</i>} <i>LAYAWAY</i>	
Address (no PO Boxes): <i>3706 Brakefield Dairy Road</i>			
City: <i>Jasper</i>		State: <i>ALA</i>	Zip: <i>35503</i>
Phone (Daytime): <i>(205) 387 8316</i>		Fax: _____	
E-mail Address: _____			
Please describe your problem: <i>After a trip to the firing range, I was unloading my rifle, by cycling the ammo, using the bolt. I had removed a couple of rounds, when I am cycled the bolt, the rifle fired, shot a hole through a wall, two pieces of furniture and out a window! This is the only time it happened, so to be on the safe side, I stored it in my gun safe until after talking with one of your reps. named <i>Kagan</i>. I would like to <u>fake Advantage</u> of your <u>Safety Modification Program</u>!</i> 500 characters left			
NOTE: Prior to shipping your firearm contact the Repair Center for services and estimated repair time.			

Number:

A6829565

Model: 700



RE00209140

E OR SPENT SHELLS IN YOUR
 WITH THE FIREARM. THIS IS A
 YOU FEEL YOU MUST SEND SPENT
 SEPARATE PACKAGE AND INCLUDE
 (1), TELEPHONE AND MODEL AND
 OF YOUR FIREARM.

your firearm before sending it.

... Pack your firearm for safety and to prevent further damage in shipping and handling. Preferably, ship in a firearm box. (Note: Original boxes may not be returned.)

- :: Remove all accessories from your firearm to prevent loss or damage.
- :: Ship your INSURED firearm by either UPS or Parcel Post. Remington is not responsible for damage or loss during shipment, so you may elect to purchase insurance from your carrier.

Print

Reset

(TIMNEY TPA)
TRIG. ASSM. Not of Rem. Mfg.
Quote to replace TPA at 1/2
Normal charges on return
AS REC'D.

Rem. oil / Hoppe / Rig / Sweats
Brand of cleaning solution used:

Wipe down How often do you clean the bore? (Months or Number of rounds) *After each outing, complete bore cleaning and wipe down if fired*

How often do you clean the action? (Months or Number of rounds)

How often do you clean the trigger assembly? (Months or Number of rounds) *Brush with lightly oil brush*

Brand of lubricant used: *Rem. oil*

How often do you lubricate the bore? (Months or Number of rounds) *Bore Snake or Rod & Patch After each Range session*

How often do you lubricate the action? (Months or Number of rounds) *Lubed Each time the Bore is cleaned*

How often do you lubricate the trigger assembly? (Months or Number of rounds) *Before long term Storage / use in adverse conditions etc.*

Have you reviewed the cleaning and maintenance recommendations on our web site or in our owners manual? ☒ YES ☐ NO

When was the last time that your firearm was serviced by a Remington authorized repairman/gunsmith?

What were the services performed?

Ship your INSURED firearm by either UPS or Parcel Post to:

Please select a state from above to view the address of the Premier Field Service Center in your area.

Must be out in 90 days
Picked up about 8/15/81

LAYAWAY
FRED'S Ser. # A6829565
• PAY CASH • PAY LESS •

Date: *July 17, 1981* No. G 41766

M *Jimmy Ginter*

Address: *Rt 9 Box 109*

City: *SASER* Tel: *872-8316* Clerk No: *OS-2*

REQUESTS THAT WE HOLD FOR HER

QUANT.	DESCRIPTION	PRICE
1	Rem. 30-06	227.37

SPENT SHELLS IN YOUR FIREARM REARM. THIS IS A VIOLATION OF JUST SEND SPENT SHELLS PLEASE AND INCLUDE NAME, ADDRESS MODEL AND SERIAL NUMBER OF FIREARM.

our firearm before sending it. prevent further damage in shipping and preferably, (original boxes may not be returned.) firearm to prevent loss or damage.

asp

10/26/2010