

Remington Arms Co., Inc.
Product Service
Legal Case #:4998

Case Information

RE#	Date Opened	Date Opened(PS)	Date Closed	Incident Date	Pre Lit	Lit	Obsolete
209015	11/2/2010	11/8/2010	11/8/2010				

Customer Information

Type	Business	First Name	Last Name	Street	City	State	Zip	Age	Contact
Incident		Michael	Kormash	38 Hickory Way	Mt. Arlington	NJ	07856		H 973-398-1301 E mjk262@verizon.net

Incident Information

Claims	Codes	Repair Est.	Medical Treatment	Medical Status
PI				
PD	Cause:4038	Could Not Duplicate Concern		
S	Concern:1025	Unexplained Discharge - No Mention of Safety Position	Unknown	
C	Unexplained Discharge			

Customer wrote on our repair form - In regard to recent tv show, he had an accidental trigger fire and has the bolt lock mechanism. Please check to ensure this model is safe to operate. df

Firearm Information

Mfg.	Type	Model/Ga.	SKU	Serial	Bbl.	DOM
Remington	CF/BA	700/30-06 SPR	n/a	A3206493	AA	3/5/1980
Date Purchased	Where Purchased	Accessories	Original Owner			
10/16/1980	SOUTHERN GUN OPA LOCKA FL		Y			

CONCERN:CHECK SAFE OPERATION OF TPA

Ammunition Information - None Defined

Other Products Information - None Defined

Settlement

Settlement	Release of Claims	Release Date	Reimbursement	Cash Settlement	Reim. Date APV	Cash Date APV
Per Ilion - Repair under BLM program						
	Repair/Replacement Cost	Repair/Replacement Date				
	\$77.73	11/16/2010				

11/16/10: Per Fred S. - Could not duplicate concern. Check over, replace TA, clean & test fire under BLM program - quote. df

Examination[Remington/CF/BA]

Part	Sub-Part	Code	Comment
Examination	Examiner		B.TRAVIS
	Exam Date		11/8/2010
	Product Type		RF
	Action Type		A
	Assigned To		F.SUPRY
Cause	4038	Could Not Duplicate Concern	
Barrel	Description		22" 30-06 SPR
	Date Code		AA
	Bore Plugged	False	
	Bulged	False	
	Fired	False	

	Fired while Obstructed	
	Muzzle/Crown Condition	Slightly Worn; Functioning
Bolt	Firing Pin	Slightly Worn; Functioning
	Shroud	Slightly Worn; Functioning
	Face	Slightly Worn; Functioning
	Handle	Slightly Worn; Functioning
	Stop	Slightly Worn; Functioning
Extractor	Condition	Slightly Worn; Functioning
	Cut Condition	Slightly Worn; Functioning
	Ext/Eject Test	False
Locking	Block Condition	---Select---
	Lug Condition	Slightly Worn; Functioning
	Notch Condition	---Select---
Overall	Exterior Condition	Slightly Worn; Functioning
	Stock Condition	Slightly Worn; Functioning
	Fore End Condition	---Select---
Receiver	Condition	Slightly Worn; Functioning
	Bulged	False
Safety	Description	STANDARD M/700 BOLT LOCK SAFETY
	Function	Like new; Functioning
	Sub-Assembly	Non-ISS
Sear	Lift	---Select---
	Notch	Like new; Functioning
	Tests	Test Fired
Feeding Test	Tests	False
Trigger	Condition	Like new; Functioning
	Pull	---Select---
	Altered	False
	Sub-Assembly	M/700 Bolt Lock

frmRepairInquiry - Repair Inquiry																																																																	
Repair Number:	RE00209015	Serial: A3206493 Model: 700 Center Fire Caliber: 30 06 SPRG Produced: 03/05/1980 SKU: 20000	Repairman:	Charles Swanson																																																													
Verify Repair			Status:	Repairing 11/8/2010 6 05 20 AM																																																													
ADDRESS INFORMATION																																																																	
Customer ☒ Received from			Return To ☐ Received from																																																														
Name: MICHAEL KORMASH			MICHAEL KORMASH																																																														
Address 1: 38 HICKORY WAY			38 HICKORY WAY																																																														
Address 2: PO Box			PO Box																																																														
City: MOUNT ARLINGTON			MOUNT ARLINGTON																																																														
State: NJ Zip Code: 07856 Country: US			NJ Zip Code: 07856 Country: US																																																														
FFL ☐ ☐ ☐ ☐ ☐ ☐ ☐ ☐																																																																	
Contact / Condition Problems Estimate History / Status Shipping / Billing																																																																	
<table border="1" style="width: 100%; border-collapse: collapse;"> <thead> <tr> <th style="width: 10%;">Date</th> <th style="width: 10%;">Code</th> <th style="width: 10%;">User ID</th> <th style="width: 20%;">Desc1</th> <th style="width: 20%;">Desc2</th> <th style="width: 10%;"></th> </tr> </thead> <tbody> <tr> <td>11/2/2010 5:0...</td> <td>EmailSent</td> <td>AmEmail</td> <td>Repair Received</td> <td>MJK.262@VER</td> <td>☐ Shipping Hold</td> </tr> <tr> <td>11/2/2010 5:0...</td> <td>EmailVerified</td> <td>AmEmail</td> <td>Receipt</td> <td>MJK.262@VER</td> <td>☐ Interface Hold</td> </tr> <tr> <td>11/4/2010 11:...</td> <td>Expedite</td> <td>pencercl</td> <td>From: Check In</td> <td>To: Repair Bar</td> <td>☐ Estimate Sent</td> </tr> <tr> <td>11/5/2010 1:0...</td> <td>Estimate</td> <td>swansonch</td> <td>Estimate Update</td> <td>Status: Estimat</td> <td>☐ Parts Received</td> </tr> <tr> <td>11/8/2010 6:0...</td> <td>Maint</td> <td>Travisbw</td> <td>Repair Maintenance</td> <td>Status: Repairin</td> <td>☐ Passed Inspection</td> </tr> <tr> <td colspan="5"></td> <td>☐ Return as Received</td> </tr> <tr> <td colspan="5"></td> <td>☐ Has Been Approved</td> </tr> <tr> <td colspan="5"></td> <td>☐ Internal Repair</td> </tr> <tr> <td colspan="5"></td> <td>☐ Exclude TATC</td> </tr> </tbody> </table>					Date	Code	User ID	Desc1	Desc2		11/2/2010 5:0...	EmailSent	AmEmail	Repair Received	MJK.262@VER	☐ Shipping Hold	11/2/2010 5:0...	EmailVerified	AmEmail	Receipt	MJK.262@VER	☐ Interface Hold	11/4/2010 11:...	Expedite	pencercl	From: Check In	To: Repair Bar	☐ Estimate Sent	11/5/2010 1:0...	Estimate	swansonch	Estimate Update	Status: Estimat	☐ Parts Received	11/8/2010 6:0...	Maint	Travisbw	Repair Maintenance	Status: Repairin	☐ Passed Inspection						☐ Return as Received						☐ Has Been Approved						☐ Internal Repair						☐ Exclude TATC	Current Status Repairing 11/8/2010 6 05 20 AM swansonch Repair Bench Repair Location ILIN Current Location ILIN Transfer Number
Date	Code	User ID	Desc1	Desc2																																																													
11/2/2010 5:0...	EmailSent	AmEmail	Repair Received	MJK.262@VER	☐ Shipping Hold																																																												
11/2/2010 5:0...	EmailVerified	AmEmail	Receipt	MJK.262@VER	☐ Interface Hold																																																												
11/4/2010 11:...	Expedite	pencercl	From: Check In	To: Repair Bar	☐ Estimate Sent																																																												
11/5/2010 1:0...	Estimate	swansonch	Estimate Update	Status: Estimat	☐ Parts Received																																																												
11/8/2010 6:0...	Maint	Travisbw	Repair Maintenance	Status: Repairin	☐ Passed Inspection																																																												
					☐ Return as Received																																																												
					☐ Has Been Approved																																																												
					☐ Internal Repair																																																												
					☐ Exclude TATC																																																												
Repair Search Refresh Close																																																																	

~~Offering~~^{Quoting} Bolt Lock modification program

RECEIVED
NOV - 9 2010

BY: _____

4998

22"
AA 3/80
SH
007

Remington

Factory Repair Instructions

(NOTE: Please print and complete this form, and then include it with your firearm.)

Model Number: 700 BDL 3006		Serial Number: A3206493	
Are you the original owner? ☒ YES ☐ NO			
Name: MICHAEL KORMASH		Date of Purchase: 10/16/1980	
Address (no PO Boxes): 38 HICKORY WAY			
City: MT. ARLINGTON		State: NJ	Zip: 07856
Phone (Daytime): 973 3981301		Fax:	
E-mail Address: mjk262@verizon.net			
☒ I would like to receive future e-mail updates from Remington.			
Please describe your problem:			
AS PER PHONE CONVERSATION IN REGARD TO RECENT TV SHOW RE: ACCIDENTAL TRIGGER FIRE AND BOLT LOCK MECHANISM PLEASE CHECK TO ENSURE THIS MODEL IS SAFE TO OPERATE			
ALSO PLEASE GIVE ME 3 PCS PART # 17034 RECEIVER PLUG SCREW I LOST ONE & 2 WILL BE EXTRA (SEE ATTACHED PARTS LIST)			
Ammunition Information:			
Manufacturer:		Type:	
Other (i.e. bullet weight/type, shot size, powder):			
Handload Information:			
Powder Used:		Powder Weight:	
Case/Hull Used:		Primer Used:	
Bullet Type/Shot Size:		Reloader Used:	
Firearms Care (Cleaning and Lubrication):			
Brand of cleaning solution used: HOPPE'S OR REMINGTON			
How often do you clean the bore? (Months or Number of rounds) AFTER EACH USE & MONTHLY			
How often do you clean the action? (Months or Number of rounds) AFTER EACH USE & MONTHLY			
How often do you clean the trigger assembly? (Months or Number of rounds) AFTER EACH USE & MONTHLY			
Brand of lubricant used: HOPPE'S OR REMINGTON			

How often do you lubricate the bore? (Months or Number of rounds) **AFTER EACH USE & MONTHLY**

How often do you lubricate the action? (Months or Number of rounds) **AFTER EACH USE & MONTHLY**

How often do you lubricate the trigger assembly? (Months or Number of rounds) **AFTER EACH USE**

Have you reviewed the cleaning and maintenance recommendations on our web site or in our owners manual?
☒ YES ☐ NO

Comments:

When was the last time that your firearm was serviced by a Remington authorized repairman/gunsmith? **N/A**

What were the services performed? **NOISE**

Ship your **INSURED** firearm by either UPS or Parcel Post to:

REMINGTON ARMS CO., INC
ATTN: Arms Service Division
14 Hoefler Ave
Ilion, NY 13357

A3206493

Model: **700**



RE00209015

IN YOUR FIREARM OR IN THE SAME BOX WITH THE
 IF YOU FEEL YOU MUST SEND SPENT SHELLS PLEASE
 ME, ADDRESS (WITH ZIP CODE), TELEPHONE AND--

ing it.
 image in shipping and handling. Preferably,
 be returned.)
 loss or damage.
 de the box. Shipments without a proper
 ost. Remington is not responsible for
 purchase insurance from your carrier.
 delines:

Under repairs will be processed during the following times:
 :: Repairs \$75.00 and under will be completed and returned to you C.O.D. (To avoid C.O.D. Charges, please
 include your credit card number and expiration date with your gun)

VISA **REDACTED** **3612** **EXP. DATE 8/12**
 :: For Repairs over \$75.00, you detailing the nature of the repair, applicable taxes
 and shipping. You will have 30 days to approve the repair estimate. Repairs can be paid by check, money order,
 or credit card (American Express, Discover, MasterCard, or VISA). If you wish, you can expedite repairs over
 \$75.00 by setting a pre-authorized amount that can be billed to your credit card.

*could not duplicate cust concern
 check over, replace TPA, clean and test
 Fire under bolt lock program for \$20.00*

(Include the Plug Screws)

Quote

700BDC 3006

COPY OF ORIGINAL
SALES RECEIPT

SN A3206493

NOTE:

THIS IS MY
OLD ADDRESS
MY CURRENT
ADDRESS IS:

MICHAEL KORMASH
38 HICKORY WAY
MT. ARLINGTON, NJ
07856

RAY'S SPORT SHOP, INC.

SPORTING GOODS

WHOLESALE - RETAIL

201-561-4400-01-02

559 HIGHWAY 22

NORTH PLAINFIELD, N.J. 07060

ARCHERY EQUIPMENT • POLICE EQUIPMENT • AMMUNITION & RELOADING SUPPLIES

ARCHERY LANES • INDOOR RIFLE & PISTOL RANGE

FISHING TACKLE • HUNTING & FISHING ACCESSORIES • GUNS & GUN SMITHING

Type of Transaction SALE Date 10/1/83

Name MICHAEL KORMASH

Address 38 HICKORY ST

MT. ARLINGTON N.J. Zip 07856

Sold by <u>(Signature)</u>	Cash <u>X</u>	Check	AMX	Deposit on Acct.	Paid Out	Other	Cashier
Co-sign			BAC		Ring #		
			MC				
			HC				
Quantity	Description					Amount	
1	NEW REMINGTON 760					323.90	
	RIFLE						
	30-06						
Serial #	A7-26423						
N.J.F.ID. #	672430 A						
DR. LIC. #	K6615 54471 09562						
OTHER ID.							
D.O.B.	9-3-53						
PHONE #	204-9194						
REF. #							
SHOP REPAIR #	DELIVERED IN FULL						

All claims and returned goods MUST be accompanied by this bill.