

Remington Arms Co., Inc.

Product Service

Legal Case #:5014

Case Information

RE#	Date Opened	Date Opened(PS)	Date Closed	Incident Date	Pre Lit	Lit	Obsolete
213373	12/8/2010	11/8/2010	12/9/2010				

Customer Information

Type	Business	First Name	Last Name	Street	City	State	Zip	Age	Contact
Incident		Joe	Lineberger	3029 Preston Mill Rd	Huddleston	VA	24104		H 540-297-7114

Incident Information

Claims	Codes	Repair Est.	Medical Treatment	Medical Status
PI				
PD				
S	Fired when he worked the bolt to unload	Cause:4038 Concern:1020	Could Not Duplicate Concern	Unknown
C				

11/8/10 Per call from Lineberger, he has a 700 that is about 25 yrs old and a couple of years ago he was coming out of the woods and he worked the bolt to unload the round out of the chamber and it fired. Hasn't happened since. Wants a new trigger even if he has to pay for it.cm

Firearm Information

Mfg.	Type	Model/Ga.	SKU	Serial	Bbl.	DOM
Remington	CF/BA	700/30-06 SPR	n/a	B6228267	KA	5/27/1980
Date Purchased	Where Purchased	Accessories	Original Owner			
	SANDY DIST CHARLESTON WV	TWO PIECE SCOPE BASE	Y			

CONCERN:FSR

Ammunition Information - None Defined

Other Products Information - None Defined

Settlement

Remington/700/CF/BA

Settlement	Release of Claims	Release Date	Reimbursement	Cash Settlement	Reim. Date APV	Cash Date APV
Replace TPA, clean at BLSM program price						
	Repair/Replacement Cost	Repair/Replacement Date				
	40.23	12/12/2010				

11/8/10 Mailing ARS and letter.cm 12/12/10 Per Ilion, could not duplicate concern. Trig assm set screws altered. Replace TPA, clean and test fire under BLSM program price of \$20 + shipping. Emailed Linberger inspection info and quote.cm 12/13/10 Lineberger called and approved repair.cm 12/14/10 Per call from Lineberger, 8:45 am, he has read on the internet that no one likes the XMark trigger. He wants me to get them to stop the repair and send him his rifle and original trigger back. I've sent the request to the repairman and will send a waiver if they can stop repairs.cm 12/14/10 Lineberger called back, changed his mind, wants us to install the trigger. Nagle retrieved the rifle from Packing and will get back to repairman.cm

Examination[Remington/CF/BA]

Part	Sub-Part	Code	Comment
Examination	Examiner		B.TRAVIS
	Exam Date		12/9/2010
	Product Type		RF
	Action Type		A
	Assigned To		T.NAGLE
Cause	4038	Could Not Duplicate Concern	
Barrel	Description		22" 30-06 SPR
	Date Code		KA
	Bore Plugged	False	
	Bulged	False	
	Fired	False	
	Fired while Obstructed		
	Muzzle/Crown Condition	Slightly Worn; Functioning	
Bolt	Firing Pin	Slightly Worn; Functioning	
	Shroud	Slightly Worn; Functioning	
	Face	Slightly Worn; Functioning	
	Handle	Slightly Worn; Functioning	
	Stop	Slightly Worn; Functioning	
Extractor	Condition	Slightly Worn; Functioning	
	Cut Condition	Slightly Worn; Functioning	
	Ext/Eject Test	False	
Locking	Block Condition	---Select---	
	Lug Condition	Slightly Worn; Functioning	
	Notch Condition	---Select---	
Overall	Exterior Condition	Slightly Worn; Functioning	
	Stock Condition	Slightly Worn; Functioning	
	Fore End Condition	---Select---	
Receiver	Condition	Slightly Worn; Functioning	
	Bulged	False	
Safety	Description		STANDARD M/700 BOLT LOCK SAFETY
	Function	Like new; Functioning	
	Sub-Assembly	Non-ISS	
Sear	Lift	---Select---	.011
	Notch	Slightly Worn; Functioning	
	Tests	Test Fired	False
Feeding Test		False	
Trigger	Condition	Slightly Worn; Functioning	
	Pull	---Select---	2.5#
	Altered	True	SET SCREWS ALTERED
	Sub-Assembly	M/700 Bolt Lock	

•	Non-Remington Components	Description	TWO PIECE SCOPE BASE
---	-----------------------------	-------------	----------------------







