Remington Arms Co., Inc.
Product Service
Legal Case #:5413

Case Information

RE# Date Opened Date Opened(PS) Date Closed Incident Date Pre Lit Lit Obsolete 217413 1/4/2011 12/13/2010 1/6/2011

Customer Information

Type Business First Name Last Name Street City State Zip Age Contact

Reporter Larry Matchak 1500 Sandy Lane Hermitage PA 16148 H724-962-4637

E Imatchak@verizon.net

Incident Information

Claims Codes Repair Est. Medical Treatment Medical Status

PΙ

PD Cause:4038 Could Not Duplicate Concern
Unknown

S Concern:1007 Fired on Safe Release

C FSR

Customer sent in an email. He stated that his son was currently using the Model 700 that was his father's. His father bought the rifle around 1972. He stated that his father & his son have had a FSR. No damage, No injury. He would like to have trigger replaced. df

Firearm Information

Mfg. Model/Ga. SKU Bbl. **DOM Type** Serial CF/BA 700/3006 SPRG Remington 311943 n/a 10/1/1967 Where Purchased Original Owner Date Purchased Accessories TWP PIECE BASE N

CONCERN:FSR

Ammunition Information - None Defined
Other Products Information - None Defined
Settlement

Remington/700/CF/BA

Settlement Release of Claims Release Date Reimbursement Cash Settlement Release Date Reimbursement Release Date Reimbursement Release Date Reimbursement Settlement APV APV

Per Ilion - Quote to repair under BLM program

Repair/Replacement Cost Date
\$45.40 1/17/2011

12/13/10: I will email ltr & form. I will ask media coord. to email ARS. df 1/17/11: Per Ilion - Could not duplicate concern. TA very dirty & sticky, parts work sluggish. Replace TA, clean & test fire under BLM program - quote. Customer apprvd repair & paid by credit card. df

Examination[Remington/CF/BA]

Sub-Part	Code	Comment
Examiner		B.TRAVIS
Exam Date		1/6/2011
Product Type		RF
	Examiner Exam Date	Examiner Exam Date

http://cps03ap13:200/psaapp/PrintDisplay.aspx?ID=5413&Type=Case

1/17/2011

[Action Type		A			
	Assigned To		T.NAGLE			
Cause	4038	Could Not Duplicate Concern				
	Description		22" 3006 SPR			
	Date Code		EP			
	Bore Plugged	False				
Barrel	Bulged	False]			
	Fired	False				
	Fired while Obstructed					
	Muzzle/Crown Condition	Slightly Worn; Functioning				
	Firing Pin	Slightly Worn; Functioning				
	Shroud	Slightly Worn; Functioning				
Bolt	Face	Slightly Worn; Functioning				
	Handle	Slightly Worn; Functioning				
	Stop	Slightly Worn; Functioning				
	Condition	Slightly Worn; Functioning				
Extractor	Cut Condition	Slightly Worn; Functioning				
	Ext/Eject Test	False				
Locking	Block Condition	Select				
	Lug Condition	Slightly Worn; Functioning				
	Notch Condition	Select				
	Exterior Condition	Slightly Worn; Functioning				
Overall	Stock Condition	Slightly Worn; Functioning				
	Fore End Condition	Select				
Receiver	Condition	Slightly Worn; Functioning				
Receiver	Bulged	False				
	Description		M/700 BOLT LOCK SAFETY			
Safety	Function	Like new; Functioning				
	Sub-Assembly	Non-ISS				
	Lift	Select	.009			
Sear	Notch	Slightly Worn; Functioning	SLUGGISH			
	Tests	Test Fired	False			
Feeding Test	10313	False				
	Condition	Slightly Worn; Functioning	DIRTY,STICKY			
Trigger	Pull	Select	6#			
111550	Altered	False				
	Sub-Assembly	M/700 Bolt Lock				
Non-Remington Components	Description		TWP PIECE BASE			

Remington.

5413

December 13, 2010

Larry Matchak 1500 Sandy Lane Hermitage, PA 16148 Ph: 724-962-4637

Email: lmatchak@verizon.net

Ref: #5413

Dear Mr. Matchak,

You will receive a pre-paid shipping label in a separate email within 24-48 hours. Please include a copy of this letter to put inside the shipping container. The letter inside is important as sometimes the outside label gets damaged in transit and we want to be sure the firearm is logged in correctly. Mark the ends of the box with "Product Service". Product Service will be inspecting the firearm and will contact me with the results.

I hope that this action will keep you a loyal Remington customer.

Sincerely,
D. Fulcher
Consumer Affairs Administrator
Remington, H&R, Marlin
Phone: 1-800-243-9700

Fax: 336-548-7872

1 JAN 1 2011

enclosure

311943 Model: 700

RE00217413

could not dupli wate concern T.A. very durty a sticky, parts works sluggish slephace TPA, cleant test Rine under BLP for \$20.00 + ship.

Quote

Remington Arms Company, Inc. ● 870 Remington Drive ● P.O. Box 700 ● Madison, NC 27025
Phone 800-243-9700 ● www.remington.com

 3^{00}

Print	Reset 3			
Model	Serial			
Number: 700 Number: 311 943				
Are you the original owner?: 🖺 YES 📓 NO				
Name: LARRY MATCHAK	Date of Purchase:			
Address (no PO Boxes): 1500 SAMPY LANE				
City: HERMITAGE	State: PA. Zip: 14/78			
Phone (Daytime): 724-962-463つ	Fax:			
E-mail Address: (if e-mail address is provided be sent)				
E-mail A	ddress:			
Please describe your proble	em and date of occurrence:			
ACCIDENTAL FI	RING WHEN			
SAFETY IS TAK	EN OFF.			
THIS HAPPENE	DON 2 OKASSIONS			
ONEE APPROX. 20	YEARS AGO, +			
ONCE A COUPLE	WEEKS AGO			
SEE ATTICH	IKO LETTER >			
500 cha	racters left			
Ammunition I	nformation:			
Manufacturer: REMINGTON	Type: CORE - LOKT			
Other (i.e. bullet weight/type, shot size,				
powder): 15-0 4 180	O GRAIN			
Handload Information:				
Powder Used:	Powder Weight:			
Case/Hull Used:	Primer Used:			
Bullet Type/Shot Size:	Reloader Used:			
Firearms Care (Cleaning and Lubrication):				

http://www.remington.com/asp/factory_repair_form.asp

12/13/2010

LARRY MATCHAK
1500 SANDY LANE
HERMITAGE, PA. 16148
PH# 724-962-4637
REF#5413 COPY OF ORIGINAL E-MAIL SENT

MY SON IS PRESENTLY USING HIS GRANDFATHERS REMINGTON MODEL 700 30-06 BOLT ACTION RIFLE. THIS GUN WAS PURCHASE BY MY FATHER IN 1972. BETWEEN MY SON AND MY FATHER THERE HAS BEEN 2 ACCIDENTAL FIRINGS OVER THE YEARS WHEN THE SAFETY IS TAKEN OFF. I UNDERSTAND THAT THERE HAS BEEN THIS TYPE OF PROBLEM WITH THIS RIFLE DATING WAY BACK. I AM NOT INTERESTED IN ANY LAW SUITS BUT WOULD FEEL MUCH BETTER KNOWNING THE GUN IS SAFE. I UNDERSTAND THAT THERE IS A REPLACEMENT TRIGGER THAT WILL SOLVE THE PROBLEM. I BELIEVE THAT IT IS THE X-MARK PRO TRIGGER ASSEMBLY. SO FAR I HAVE BEEN TOLD BY SEVERAL GUN DEALERS THAT I HAVE TO SEND THE RIFLE TO THE FACTORY TO GET THIS DONE. IF THIS IS TRUE WHERE DO I SEND IT AND HOW MUCH WILL IT COST? I WOULD APPRECIATE ANY HELP YOU CAN GIVE ME. SERIAL NUMBER ON THIS RIFLE IS #311943. THANK YOU

Brand of cleaning solution used: OUTER'S + Hoppe's				
How often do you clean the bore? (Months or Number of rounds) AFTER USPGE WEATHER CONDITION				
How often do you clean the action? (Months or Number of rounds)				
How often do you clean the trigger assembly? (Months or Number of rounds) YEARLY Brand of lubricant used: OUTER'S & HOPPE'S				
Brand of lubricant used: OUTER'S 4 HOPPE'S				
How often do you lubricate the bore? (Months or Number of rounds)				
How often do you lubricate the action? (Months or Number of rounds)				
How often do you lubricate the trigger assembly? (Months or Number of rounds)				
Have you reviewed the cleaning and maintenance recommendations on our web site or in our owners manual? >□ YES ☒ NO				
When was the last time that your firearm was serviced by a Remington authorized repairman/gunsmith?)				
What were the services				
performed?)				
Ship your INSURED firearm by either UPS or Parcel Post to:				
Remington Arms Co., Inc. Attn: Arms Service Division 14 Hoefler Avenue Ilion, NY 13357				
☐ WARNING: DO NOT SEND LIVE OR SPENT SHELLS IN YOUR FIREARM OR IN THE SAME BOX WITH THE FIREARM. THIS IS A VIOLATION OF FEDERAL LAW. IF YOU FEEL YOU MUST SEND SPENT SHELLS PLEASE SEND THEM IN A SEPARATE PACKAGE AND INCLUDE NAME, ADDRESS (WITH ZIP CODE), TELEPHONE AND MODEL AND SERIAL NUMBER OF YOUR FIREARM.				
:: Record the serial number of your firearm before sending it. :: Pack your firearm for safety and to prevent further damage in shipping and handling. Preferably, ship in a firearm box. (Note: Original boxes may not be returned.) :: Remove all accessories from your firearm to prevent loss or damage. :: Provide a return address on both the outside and inside the box. Shipments without a proper				

http://www.remington.com/asp/factory_repair_form.asp

12/13/2010

return address will be refused.

:: Ship your INSURED firearm by either UPS or Parcel Post. Remington is not responsible for

damage or loss during shipment, so you may elect to purchase insurance from your carrier.

Charge repairs will be processed using the following guidelines:

:: Repairs \$75.00 and under will be completed and returned to you C.O.D. (To avoid C.O.D. Charges, please include your credit card number and expiration date with your gun)

:: For Repairs over \$75.00, you will receive a written estimate detailing the nature of the repair, applicable taxes and shipping. You will have 30 days to approve the repair estimate. Repairs can be paid by check, money order, or credit card (American Express, Discover, MasterCard, or VISA). If you wish, you can expedite repairs over \$75.00 by setting a pre-authorized amount that can be billed to your credit card. We process checks electronically through Check21.

Reference # 101209-000045

Status Updated

Assigned To Administrators

Dell -

Product Firearms

SLA

Not specified

Queue CSR

Date Created 12/09/2010 12:12 PM

Initial Response 12/13/2010 08:51 AM

Last Updated 12/13/2010 09:56 AM

Customer SmartSense 0 (on -3 to +3 scale)

Staff SmartSense +1 (on -3 to +3 scale)

REMINGTON MODEL 700 BDL

Discussion Thread

Customer (Larry Matchak)

HERE IS THE INFORMATION YOU REQUESTED:

RIFLE SERIAL #311943

CAL, 30-06

MAILING ADDRESS:

LARRY MATCHAK 1500 SANDY LANE

HERMITAGE, PA. 16148

PHONE # 724-962-4637

-- Original Message -

From: Remington Information

To: Imatchak@verizon.net

Sent: Monday, December 13, 2010 8:51 AM Subject: REMINGTON MODEL 700 BDL [Incident: 101209-000045]

Response (Dell -)

Dear Mr. Matchak.

12/13/2010 08:51 AM

12/13/2010 09:56 AM

We would like to have the firearm come into our Product Services Department at our factory for examination. Please reply back to me with the serial number of the firearm, caliber, your mailing address and phone number. We would like to send you a pre-paid shipping label for UPS to have the firearm come in. I will also include a form that you can fill out to let the examiner know exactly what happened, when this occurred, and what you are expecting.

Sincerely, Dell

Customer (Larry Matchak)

12/09/2010 12:12 PM

MY SON IS PRESENTLY USING HIS GRANDFATHERS REMINGTON MODEL 700 BDL 30-06 BOLT ACTION RIFLE. THIS GUN WAS PURCHASE BY MY FATHER IN 1972. BETWEEN MY SON AND MY FATHER THERE HAS BEEN 2 ACCIDENTAL FIRINGS OVER THE YEARS WHEN THE SAFETY IS TAKEN OFF, I UNDERSTAND THAT THERE HAS BEEN THIS TYPE OF PROBLEM WITH THIS RIFLE DATING WAY BACK . I AM NOT INTERESTED IN ANY LAW SUITS BUT WOULD WOULD FEEL MUCH BETTER KNOWNING THE GUN IS SAFE. I UNDER STAND THAT THERE IS A REPLACEMENT TRIGGER THAT WILL SOLVE THE PROBLEM. I BELIEVE THAT IT IS THE X-MARK PRO TRIGGER ASSEMBLY, SO FAR I HAVE BEEN TOLD BY SEVERAL GUN DEALERS THAT I HAVE TO SEND THE RIFLE TO THE FACTORY TO GET THIS DONE. IF THIS IS TURE WHERE DO I SEND IT AND HOW MUCH WILL IT COST? I WOULD APPRECIATE ANY HELP YOU CAN GIVE ME. SERIAL NUMBER ON THIS RIFLE IS #311943. THANK YOU

Primary Contact

First Name: Larry

Last Name: Matchak

Organization:

Login: Imatchak@verizon.net

Title: Contact Type:

Email: Imatchak@verizon.net

Email - Alternate #1: Email - Alternate #2:

Office Phone: Mobile Phone:

Fax:

Assistant Phone:

Home Phone:

Street

City

State/Province

Postal Code

Country

Additional Information

Model Number: 700



December 13, 2010

Larry Matchak 1500 Sandy Lane Hermitage, PA 16148 Ph: 724-962-4637

Email: lmatchak@verizon.net

Ref: #5413

Dear Mr. Matchak,

You will receive a pre-paid shipping label in a separate email within 24-48 hours. Please include a copy of this letter to put inside the shipping container. The letter inside is important as sometimes the outside label gets damaged in transit and we want to be sure the firearm is logged in correctly. Mark the ends of the box with "Product Service". Product Service will be inspecting the firearm and will contact me with the results.

I hope that this action will keep you a loyal Remington customer.

Sincerely, D. Fulcher Consumer Affairs Administrator Remington, H&R, Marlin Phone: 1-800-243-9700

Fax: 336-548-7872

enclosure

Remington Arms Company, Inc. ◆ 870 Remington Drive ◆ P.O. Box 700 ◆ Madison, NC 27025 Phone 800-243-9700 ◆ www.remington.com



December 13, 2010

Larry Matchak 1500 Sandy Lane Hermitage, PA 16148 Ph: 724-962-4637

Email: lmatchak@verizon.net

Ref: #5413

Dear Mr. Matchak,

You will receive a pre-paid shipping label in a separate email within 24-48 hours. Please include a copy of this letter to put inside the shipping container. The letter inside is important as sometimes the outside label gets damaged in transit and we want to be sure the firearm is logged in correctly. Mark the ends of the box with "Product Service". Product Service will be inspecting the firearm and will contact me with the results.

I hope that this action will keep you a loyal Remington customer.

Sincerely,
D. Fulcher
Consumer Affairs Administrator
Remington, H&R, Marlin
Phone: 1-800-243-9700
Fax: 336-548-7872

enclosure

Remington Arms Company, Inc. • 870 Remington Drive • P.O. Box 700 • Madison, NC 27025 Phone 800-243-9700 • www.remington.com

	Print	Reset					
	Model Serial						
Number: Number:							
	Are you the original ow	ner?: 🖸 YES 🖺 N	10				
Name:	ne: Date of Purchase:						
Address (no PO Boxes):							
City:		State:	Zip:				
(Daytime):	Phone	Fax:					
E-mail Address: be sent)	E-mail Address:(if e-mail address is provided, notification of receipt and shipment will be sent)						
□ Iw	E-mail A ould like to receive future		emington.				
Ple	ase describe your proble		rence:				
	programme and the second second	racters left					
	Ammunition	Information:					
Manufacturer:		Type:	:				
ро	Other (i.e. bullet we wder):	ight/type, shot size,					
			· · · · · · · · · · · · · · · · · · ·				
	Handload Ir	I					
Powder Used		Powder Weight:					
Case/Hull Use	ed:	Primer Used:					
Bullet Type/Shot	Size:	Reloader Used:					
	Firearms Care (Cleani	ng and Lubrication):					

Brand of cleaning solution used:					
How often do you clean the bore? (Months or Number of rounds)					
How often do you clean the action? (Months or Number of rounds)					
How often do you clean the trigger assembly? (Months or Number of rounds)					
Brand of lubricant used:					
How often do you lubricate the bore? (Months or Number of rounds)					
How often do you lubricate the action? (Months or Number of rounds)					
How often do you lubricate the trigger assembly? (Months or Number of rounds)					
Have you reviewed the cleaning and maintenance recommendations on our web site or in our owners manual? > YES NO					
When was the last time that your firearm was serviced by a Remington authorized repairman/gunsmith?)					
What were the services performed?)					
Ship your INSURED firearm by either UPS or Parcel Post to:					
Remington Arms Co., Inc. Attn: Arms Service Division 14 Hoefler Avenue Ilion, NY 13357					
☐ WARNING: DO NOT SEND LIVE OR SPENT SHELLS IN YOUR FIREARM OR IN THE SAME BOX WITH THE FIREARM. THIS IS A VIOLATION OF FEDERAL LAW. IF YOU FEEL YOU MUST SEND SPENT SHELLS PLEASE SEND THEM IN A SEPARATE PACKAGE AND INCLUDE NAME, ADDRESS (WITH ZIP CODE), TELEPHONE AND MODEL AND SERIAL NUMBER OF YOUR FIREARM.					
:: Record the serial number of your firearm before sending it. :: Pack your firearm for safety and to prevent further damage in shipping and handling. Preferably, ship in a firearm box. (Note: Original boxes may not be returned.) :: Remove all accessories from your firearm to prevent loss or damage. :: Provide a return address on both the outside and inside the box. Shipments without a proper					

return address will be refused.

:: Ship your INSURED firearm by either UPS or Parcel Post. Remington is not responsible for

damage or loss during shipment, so you may elect to purchase insurance from your carrier.

Charge repairs will be processed using the following guidelines:

:: Repairs \$75.00 and under will be completed and returned to you C.O.D. (To avoid C.O.D. Charges, please include your credit card number and expiration date with your gun)

:: For Repairs over \$75.00, you will receive a written estimate detailing the nature of the repair, applicable taxes and shipping. You will have 30 days to approve the repair estimate. Repairs can be paid by check, money order, or credit card (American Express, Discover, MasterCard, or VISA). If you wish, you can expedite repairs over \$75.00 by setting a pre-authorized amount that can be billed to your credit card. We process checks electronically through Check21.

Fulcher, Dell Marie

From:

To:

Sent: Subject: Verizon Online Postmaster [postmaster@verizon.net] Imatchak@verizon.net Monday, December 13, 2010 5:13 PM Delivered: Larry Matchak - Ref# 5413

Your message has been delivered to the following recipients:

Imatchak@verizon.net

Subject: Larry Matchak - Ref# 5413





Remington Arms Company, Inc. 870 Remington Drive P. O. Box 700 Madison, NC 27025-0700

ARS LABEL REQUEST FORM

DATE:	12/13/2010	LILE	UESTED BY:		Dell				1
QUANTITY:	1	WEI	GHT PER PKO	3 :		10	lbs		
RUEASECHECKONE MEDIA COORDINATOR TO MAIL	XXXXX	P-620-1		,		,			
DESCRIPTION:	Ref # 5413								•
,	rifle		4XX596 SVC GNDCOM TRACKING# 124 REF 1:LARRY M REF 2:5413/RI	XX59 ATCH	969067010	WT 10.0 3143	CURR USI LBS	1	OF 1
	LABEL IN	NF(HANDLING CHAR SINGLE-PIECE DV 0.00 DC 0.00 AH 0.00 TOT PUB CHG 7	PUB		RGS: 0.00 0.00 0.00 PUB+HAI		1.00	SD
MAIL LABEL TO:	Larry Matchak		101 Pub ChG 7	. 32		PUBTHH	MULING	7.92	
	1500 Sandy Lane								
	Hermitage, PA 16148								
:	Ph: 724-962-4637								
<u>.</u>	Email: lmatchak@verizon.ne	et			Email to	custome	r ome, 2,31		
RETURN ITEM TO	Remington Arms		-						
	Attn: Product Service								
	Ilion, NY								•
		=							

PLEASE COMPLETE ALL PARTIS OF THIS FOR

Imatchak@verizon.net







