Remington Arms Co., Inc. Product Service Legal Case #:4987

Case Information

RE# Date Opened Date Opened(PS) Date Closed Incident Date Pre Lit Lit Obsolete

212971 12/6/2010 11/5/2010 12/7/2010

Customer Information

Street Type **Business** First Name Last Name City State Zip Contact Age 4 Wayne Dr C 864-238-8325 Jeff Ouzts SC 29687 Incident **Taylors**

Incident Information

Claims Codes Repair Est. Medical Treatment Medical Status

PΙ

PD

Cause: 4038 Could Not Duplicate Concern

S Fired on bolt closing

Concern:1008 Fired on Bolt Closing

Unknown

C

11/5/10 Per call from Ouzts, he saw the CNBC program and he has had his 700 fire twice when closing the bolt. He bought it from his grandad and is not sure if he was the original owner or not.cm

Firearm Information

Mfg. Remington Type CF/BA Model/Ga. 700/243 WIN

SKU n/a **Serial Bbl. DOM** 6570709 PW 6/1/1972

Date Purchased

Where Purchased

Accessories

Original Owner

Cnased SULLIVAN HDWE

ANDERSON SC

SCOPE,SEE THRU RING MOUNTS

N

CONCERN: WILL GO OFF WITHOUT TOUCHING IT

Ammunition Information - None Defined Other Products Information - None Defined Settlement

Remington/700/CF/BA

Settlement

Release of Claims

Release Date

Reimbursement

Cash Settlement Reim. Date

APV

Cash Date APV

Per Ilion, replace trigger assm, clean at BLSM program price

Repair/Replacement

Repair/Replacement

Cost

Date

40.23

12/10/2010

11/5/10 Mailing ARS.cm 12/12/10 Per Ilion, could not duplicate concern. Trigger assm is very dirty. Replace TPA, clean and test fire under BLSM program price of \$20 + shipping.cm 12/14/10 Spoke with Ouzts, he approved replacing the trigger and the \$37 charge. He can replace the barrel himself and asked that we remove that from the estimate.cm


Examination[Remington/CF/BA]

Part	Sub-Part	Code	Comment
Examiner		B.TRAVIS	
	Exam Date		12/7/2010

http://cps03ap13:200/psaapp/PrintDisplay.aspx?ID=4987&Type=Case

12/14/2010

م, ا	Product Type	i	RF
Examination	Action Type	า	A
	Assigned To]	T.NAGLE
Cause	4038	Could Not Duplicate	POOR MAINTENENCE
		Concern	
Barrel	Description]]	22" 243 WIN
	Date Code		PW
	Bore Plugged	False]
	Bulged	False]
	Fired	False	
	Fired while Obstructed		1
	Muzzle/Crown Condition	Slightly Worn; Functioning	
	Firing Pin	Slightly Worn; Functioning	
	Shroud	Slightly Worn; Functioning	
Bolt	Face	Slightly Worn; Functioning	
	Handle	Slightly Worn; Functioning	
	Stop	Slightly Worn; Functioning	
	Condition	Slightly Worn; Functioning	
Extractor	Cut Condition	Slightly Worn; Functioning	
	Ext/Eject Test	False	
	Block Condition	Select	
Locking	Lug Condition	Slightly Worn; Functioning	
-	Notch Condition	Select	
	Exterior Condition	Slightly Worn; Functioning	
Overall	Stock Condition	Slightly Worn; Functioning	
	Fore End Condition	Select	
D .	Condition	Slightly Worn; Functioning	
Receiver	Bulged	False	
Safety	Description		STANDARD M/700 BOLT LOCK SAFETY
	Function	Like new; Functioning	
		Non-ISS	
Sear	Lift	Select	N/A, SCOPE MOUNTED
	Notch	Slightly Worn; Functioning	DIRTY
		Test Fired	False
Feeding Test	Tests	False	
	Condition	Slightly Worn; Functioning	VERY DIRTY
Trigger	Pull	Select	5.5#
	Altered	False	
	Sub-Assembly	M/700 Bolt Lock	
Non-Remington Components	Description		SCOPE,SEE THRU RING MOUNTS



REDACTED

1297 DEC - 8 2010 D

5/11



IOTE: Please complete and print this form, and the nitrock	dollyiby frilesia:	
Model Number: 700	starvunes 65	70709
Are you the original owner?: YES NO		
Name: Jeff Ouzts	Date of Purchase;	2008
Address (no PO Boxes): 4 Wayne	Drive	
city: Taylors	State: 5C	zip: 29687
Phone (Daytime): 238-8325 (86	04) Fax:	
E-mail Address:(if e-mail address is provided, notific		will be
sent) Jeffourts@att.ne		· · · · · · · · · · · · · · · · · · ·
E-mail Address:	- Comington	
I would like to receive future e-mail updates from Please describe your problem and date of occurre		
When bullet is in T		211 00
afc in the state	pipe dan	5111 90
off without touc	thing it.	Bolt is
down safety is or	J. Gan will	go off.
		J
manuscript in the second secon		
500 characters left		—
Ammunition Information:		
Manufacturer: Reminqton	Туре: 243	
Other (i.e. bullet weight/type, shot size, powder):		·
	:	
Handload Information:	7	
Powder Used:	To Conglet:	
Case/Hull Used:	Phiner Verok	
Bullet Type/Shot Size:	Fielder Teach	
	Mary Mary Control of the Control of	

72" 7w 65 5.5

4987

November 5, 2010

Jeff Ouzts 4 Wayne Dr Taylors, SC 29687

Subject: #4987, Model 700

Dear Mr. Ouzts,

Per our phone conversation, enclosed is a prepaid UPS ground shipping label for shipment of the firearm to our factory for inspection. Please include a copy of this letter with the firearm. The letter inside is important as sometimes the outside label gets damaged in transit and we want to be sure the firearm is logged in correctly. Please mark the ends of the box with "Product Service".

I apologize for the inconvenience that this incident has caused and I hope that these actions will keep you as a loyal Remington customer.

Sincerely,

Christy Mitchell Consumer Affairs Administrator Phone: 800-243-9700, ext 8684 christy.mitchell@remington.com

enclosure



could not duplicate concern. T.A. is nexy dirty. Replace TPA, clean + Trit Rine under BLP for # 10.00 + ship

Quote

Remington Arms Company, Inc. • 870 Remington Drive • P.O. Box 700 • Madison, NC 27025 Phone 800-243-9700 • www.remington.com



Remington Arms Company, Inc. 870 Remington Drive P. O. Box 700 Madison, NC 27025-0700

ARS LABEL REQUEST FORM

DATE:	11/5/2010	REQUESTED BY:	christy
QUANTITY: 1		WEIGHT PER PACKAGE:	10
REASEICHECKONEI MEDIA COORDINATOR	,	LWH AAAH	xxxxx
TO MAIL DESCRIPTION:		I WILL MAIL	
Model 700			

LABEL INFORMATION

MAIL LABEL TO:	Jeff Ouzts 4 Wayne Dr Taylors, SC 29687
RETURN ITEM TO	: Rem Product Service

ARLEASE COMPLETE ALLEPARTS OF THIS FORM: AND SEND TO THE MEDIA COORDINATION AND SEND TO THE SEND TO THE MEDIA COORDINATION AND SEND TO THE SEND TO THE MEDIA COORDINATION AND SEND TO THE SEND TH

4XX596 NOV 5, 2010 ALL CURR USD 1 OF 1 SVC CNDCOM ACT WT 10.0 LBS
TRACKINGH 1Z4XX5969066500455
REF 1.JEFF OUZTS/CD/CM
REF 2:700

HANDLING CHARGE 0.00
SINGLE-PIECE PUB RATE CHRGS: SVC 1/P USD CV 0.00 CDD 0.00 RS 0.00
DC 0.00 DGD 0.00 SD 0.00
AH 0.00 PR 0.00 SP 0.00
TOT PUB CHC 8.74 PUB+HANDLING 8.74

