Remington Arms Co., Inc.
Product Service
Legal Case #:5433

Case Information

RE# Date Opened Date Opened(PS) Date Closed Incident Date Pre Lit Lit Obsolete

217089 1/3/2011 12/15/2010 1/6/2011

Customer Information

Type Business First Name Last Name Street City State Zip Age Contact

Incident Joseph Russo 54 County Rd 22236 Anx Cleveland TX 77327 H 281-659-9228 E coyote free@yahoo.com

Incident Information

Claims Codes Repair Est. Medical Treatment Medical Status

ΡI

PD Cause:4038 Could Not Duplicate Concern

Concern: 1008 Fired on Bolt Closing

Unknown

S Concern: 1008 Fired of C FBC

Customer called in. He stated that he had a FBC years ago & wants the gun checked out. No damage, No injury. df

Firearm Information

 Mfg.
 Type
 Model/Ga.
 SKU
 Serial
 Bbl.
 DOM

 Remington
 CF/BA
 700/270 WIN
 n/a
 6634903
 KX
 5/1/1973

Date Purchased Where Purchased Accessories Original Owner

EVANS SPT SHREVEPORT LA TWO PIECE BASE N

CONCERN:FBC

Ammunition Information - None Defined Other Products Information - None Defined

Settlement

Remington/700/CF/BA

Settlement Release of Claims Release Date Reimbursement Cash Settlement Release Date Reimbursement Release Date Reimbursement Release Date APV

Per Ilion - Repair under BLM program

Repair/Replacement Repair/Replacement

Cost **Date** \$45.40 1/17/2011

12/15/10: Sending ARS, ltr, form & box. Box order# 1168703. df 1/17/11: Per Ilion - Could not duplicate concern. TA dirty & set screws altered, has min. trigger return. Replace TA, clean & test fire under BLM program - quote. I spoke with customer. He apprvd quote & paid by credit card. df

Examination[Remington/CF/BA]

Part	Sub-Part	Code	Comment
Examination	Examiner		B.TRAVIS
	Exam Date		1/6/2011
	Product Type		RF
	Action Type		A
	Assigned To		T.NAGLE

http://cps03ap13:200/psaapp/PrintDisplay.aspx?ID=5433&Type=Case

1/17/2011

Cause	4038	Could Not Duplicate Concern	
	Description		22" 270 WIN
	Date Code		KX
	Bore Plugged	False]
Barrel	Bulged	False	j
	Fired	False	
	Fired while Obstructed		1
	Muzzle/Crown Condition	Worn; Functioning]
	Firing Pin	Slightly Wom; Functioning	1
	Shroud	Slightly Worn; Functioning	
Bolt	Face	Slightly Worn; Functioning	1
	Handle	Slightly Wom; Functioning	1
	Stop	Slightly Wom; Functioning	
	Condition	Slightly Wom; Functioning	1
Extractor	Cut Condition	Slightly Wom; Functioning	ĺ
	Ext/Eject Test	False	1
	Block Condition	Select	1
Locking	Lug Condition	Slightly Worn; Functioning	1
	Notch Condition	Select	1
	Exterior Condition	Slightly Worn; Functioning	1
Overall	Stock Condition	Slightly Worn; Functioning	1
	Fore End Condition	Select	1
	Condition	Slightly Worn; Functioning	1
Receiver	Bulged	False	1
	Description		M/700 BOLT LOCK SAFETY
Safety	Function	Like new; Functioning]
•	Sub-Assembly	Non-ISS	Ī
	Lift	Select	.004
Sear	Notch	Slightly Worn; Functioning	
		Test Fired	False
Feeding Test	Tests	False	
	Condition	Slightly Worn; Functioning	DIRTY MIN TRIG RETURN
77 *	Pull	Select	2.5#
Trigger	Altered	True	SET SCREWS ALTERED
	Sub-Assembly	M/700 Bolt Lock	
Non-Remington Components	Description		TWO PIECE BASE

22"
EXS/7
2.57
2.57

S433

December 15, 2010

Joseph Russo 54 County Rd 22236 Anx Cleveland, TX 77327 Ph: 281-659-9228

Ref: #5433

Dear Mr. Russo,

Enclosed is a prepaid UPS shipping label to cover shipment of your firearm to our factory for examination.

Please include a copy of this letter to put inside the shipping container. The letter inside is important as sometimes the outside label gets damaged in transit and we want to be sure the firearm is logged in correctly. Mark the ends of the box with "Product Service". Product Service will be inspecting the firearm and will contact me with the results.

I hope that this action will keep you a loyal Remington customer.

Sincerely,
D. Fulcher
Consumer Affairs Administrator
Remington, H&R, Marlin
Phone: 1-800-243-9700

Fax: 336-548-7872

MEGEZWI M JAN 10 2011

BY:____

could not duplicate concers. T.A. dirty + set screws Altered,

MAS MIN Triq. peture. Replace TPA, clean+testfine under

enclosure

FOR FURTHER INFO PLEASE CALL ME.

6634903

PE00217000

ton Drive ● P.O. Box 700 ● Madison, NC 27025 • www.remington.com

BCP Con \$ 20.00 + Ship

270

Print	Reset				
Model Number: 700	Serial Number: // 2460 44 7				
Are you the original ow	Number: <u> </u>				
	Date of Purchase:				
Name: Joseph C. Russo	NIA				
Address (no	PO Boxes):				
54 CR 22-23 6 BNX					
City: CLEVELA NO	State: アス Zip: アスマ				
Phone (Daytime): 281-659-7228	Fax: Sanc				
E-mail Address:(if e-mail address is provid					
be sent) COYOTE - FREE @	10 Hdg. Carr				
E-mail A					
☐ I would like to receive future e					
Please describe your problem and date of occurrence: MY GRANDSON INHERITS D THIS FIREARM FROM HIS BOATERNAL GRAND FOTHER. I WAS TEST FIRING IT WHEN I CHAMBERED A ROUND AND PUT THE SAFETY ON. WHEN I RELEASED THE SAFETY THE GUN FIRED. LUCKING IT WAS PENTED DEAN RAILE. NO FURTHER ATTEMPTS WERE MODE TO BIRD IT ACAIN. 500 characters left Manufacturer: MAA Type: Other (i.e. bullet weight/type, shot size, powder):					
Handload Information: U/A					
Powder Used:	Powder Weight:				
Case/Hull Used:	Primer Used:				
Bullet Type/Shot Size:	Reloader Used:				
Firearms Care (Cleaning and Lubrication):					

Brand of cleaning solution used:					
How often do you clean the bore? (Months or Number of rounds)					
How often do you clean the action? (Months or Number of rounds)					
How often do you clean the trigger assembly? (Months or Number of rounds)					
Brand of lubricant used:					
How often do you lubricate the bore? (Months or Number of rounds)					
How often do you lubricate the action? (Months or Number of rounds)					
How often do you lubricate the trigger assembly? (Months or Number of rounds)					
Have you reviewed the cleaning and maintenance recommendations on our web site or in our owners manual? > YES NO					
When was the last time that your firearm was serviced by a Remington authorized repairman/gunsmith?)					
What were the services performed?)					
Ship your INSURED firearm by either UPS or Parcel Post to:					
Remington Arms Co., Inc. Attn: Arms Service Division 14 Hoefler Avenue Ilion, NY 13357					
☐ WARNING: DO NOT SEND LIVE OR SPENT SHELLS IN YOUR FIREARM OR IN THE SAME BOX WITH THE FIREARM. THIS IS A VIOLATION OF FEDERAL LAW. IF YOU FEEL YOU MUST SEND SPENT SHELLS PLEASE SEND THEM IN A SEPARATE PACKAGE AND INCLUDE NAME, ADDRESS (WITH ZIP CODE), TELEPHONE AND MODEL AND SERIAL NUMBER OF YOUR FIREARM.					
:: Record the serial number of your firearm before sending it. :: Pack your firearm for safety and to prevent further damage in shipping and handling. Preferably, ship in a firearm box. (Note: Original boxes may not be returned.) :: Remove all accessories from your firearm to prevent loss or damage. :: Provide a return address on both the outside and inside the box. Shipments without a proper					

return address will be refused.

:: Ship your INSURED firearm by either UPS or Parcel Post. Remington is not responsible for

damage or loss during shipment, so you may elect to purchase insurance from your carrier.

Charge repairs will be processed using the following guidelines:

- :: Repairs \$75.00 and under will be completed and returned to you C.O.D. (To avoid C.O.D. Charges, please include your credit card number and expiration date with your gun)
- :: For Repairs over \$75.00, you will receive a written estimate detailing the nature of the repair, applicable taxes and shipping. You will have 30 days to approve the repair estimate. Repairs can be paid by check, money order, or credit card (American Express, Discover, MasterCard, or VISA). If you wish, you can expedite repairs over \$75.00 by setting a pre-authorized amount that can be billed to your credit card. We process checks electronically through Check21.



Remington Arms Company, Inc. 870 Remington Drive P. O. Box 700 Madison, NC 27025-0700

ARS LABEL REQUEST FORM

DATE:		12/15/2010	REQUESTED BY:	Dell
QUANTITY:		<u> </u>	WEIGHT PER PKG:	10 lbs
PLEASEIGHECKONE MEDIA COORDINATOR TO MAIL			I WILL MAIL	XXXXXX
DESCRIPTION:	Ref # 5433 rifle			

LABEL INFORMATION

MAIL LABEL TO: Joseph Russo

54 County Rd 22236 Anx Cleveland, TX 77327 Ph: 281-659-9228

RETURN ITEM TC Remington Arms

Attn: Product Service

Ilion, NY

PLEASE COMPLETE ALL PARTS OF THIS FORM AND SEND TO THE MEDIA COOFDINATION

4XX596 DEC 15, 2010 ALL CURR USD 1 OF 1 SVC GNDCOM ACT WT 10.0 LBS
TRACKING# 1Z4XX5969067282369
REF 1:JOSEPH RUSSO/CD/DMF
REF 2:5433/RIFLE

HANDLING CHARGE 0.00
SINGLE-PIECE PUB RATE CHRGS: SVC T/P USD

HANDLING CHARGE 0.00
SINGLE-PIECE PUB RATE CHRGS: SVC T/P USD
DV 0.00 COD 0.00 RS 0.50
DC 0.00 DGD 0.00 SD 0.00
DC 0.00 PR 0.00 SP 0.00
TOT PUB CHG 9.45 PUB+HANDLING 9.45





