rage 1 01 3

Remington Arms Co., Inc.
Product Service
Legal Case #:5469

Case Information

RE# Date Opened Date Opened(PS) Date Closed Incident Date Pre Lit Lit Obsolete

220543 1/25/2011 12/20/2010 1/26/2011

Customer Information

Type Business First Name Last Name Street City State Zip Age Contact

Incident Brian Smith 3214 N Northshore Blvd Wichita KS 67205 W 620-669-6439

Incident Information

Claims Codes Repair Est. Medical Medical Treatment Status

PΙ

PD Cause:4006 Altered Adjustments or

S Fired on safety Components Unknown

orelease Concern:1007 Fired on Safe Release

C

12/20/10 Per call from Smith, he bought his 700 new about 25 yrs ago. About 3 weeks ago it fired when he released the safety. It cut his thumb when it recoiled back but he is ok. He has not been able to duplicate it but once since.cm

Firearm Information

 Mfg.
 Type
 Model/Ga.
 SKU
 Serial
 Bbl.
 DOM

 Remington
 CF/BA
 700/270 WIN
 n/a
 B6529660
 XD
 12/1/1983

Date Purchased Where Purchased Accessories Original Owner

TWO PIECE BASE Y

CONCERN:FSR

Ammunition Information - None Defined Other Products Information - None Defined Settlement

Remington/700/CF/BA

Settlement Release of Claims Release Date Reimbursement Cash Settlement Settlement APV APV

Per Ilion, replace TPA, clean, test fire at 1/2 normal cost

Repair/Replacement Repair/Replacement Cost Date

12/20/10 Mailing box and ARS.cm 1/28/11 Per Ilion, will follow down. Trigger assm dirty, rusty, set screws altered. Trigger will not return properly. Replace TPA, clean, test fire at 1/2 normal cost.cm

Examination[Remington/CF/BA]

Part	Sub-Part	Code	Comment	
Examination	Examiner		B.TRAVIS	
	Exam Date		1/26/2011	
	Product Type		RF	
	Action Type		A	

http://cps03ap13:200/psaapp/PrintDisplay.aspx?ID=5469&Type=Case

1/28/2011

r munispiay Page 2 of 3

	Assigned To		T.NAGLE
Cause	4006	Altered Adjustments or Components	
	Description		22" 270 WIN
	Date Code		XD
	Bore Plugged	False	
	Bulged	False	
Barrel	Fired	False	
	Fired while Obstructed		-
	Muzzle/Crown Condition	Slightly Worn; Functioning	
	Firing Pin	Slightly Worn; Functioning	
	Shroud	Slightly Worn; Functioning	
Bolt	Face	Slightly Worn; Functioning	
	Handle	Slightly Worn; Functioning	
	Stop	Slightly Worn; Functioning	BINDS
	Condition	Slightly Worn; Functioning	
Extractor	Cut Condition	Slightly Worn; Functioning	
	Ext/Eject Test	False	
	Block Condition	Select	
Locking	Lug Condition	Slightly Worn; Functioning	
	Notch Condition	Select	
	Exterior Condition	Slightly Worn; Not Functioning	
Overall	Stock Condition	Slightly Worn; Functioning	BEDDED
	Fore End Condition	Select	
Receiver	Condition	Slightly Worn; Functioning	
	Bulged	False	
	Description		M/700 SAFETY
Safety	Function	Like new; Functioning	
	Sub-Assembly	Non-ISS	
	Lift	Select	.010
Sear	Notch	Slightly Worn; Functioning	
	Tests	Test Fired	False
Feeding Test	1 6515	False	
	Condition	Slightly Worn; Not Functioning	DIRTY,RUSTY,TRIG NOT RETURNING WILL FOLLOW DOWN
	Pull	Select	2#

http://cps03ap13:200/psaapp/PrintDisplay.aspx?ID=5469&Type=Case

1/28/2011

Trigger	Altered	True	SET SCREWS ALTERED	
	Sub-Assembly	M/700 Non-Bolt Lock		-
Non-Remington Components	Description		TWO PIECE BASE	

72/83 7 12/83 7 14

5469

December 20, 2010

Brian Smith 3214 N Northshore Blvd Wichita, KS 67205

Subject: #5469, Model 700

Dear Mr. Smith,

Thank you for your patience. Enclosed is a UPS ground prepaid shipping label to cover shipment of the firearm for inspection at our factory. Please include a copy of this letter with the firearm. The letter inside is important as sometimes the outside label gets damaged in transit and we want to be sure the firearm is logged in correctly. Please mark the ends of the box with "Product Service".

I apologize for the inconvenience that this incident has caused and I hope that these actions will keep you a loyal Remington customer.

Sincerely,

Christy Mitchell Consumer Affairs Administrator Phone: 800-243-9700, ext 8684 christy.mitchell@remington.com

Willfollow down.

T.A. dinty, Rusty, set screws

Altered Trig will Not return

Properly. Replace TPA, clean

+ Test Rine At 1/2 NormAl

LOST.

B6529660 |Model: 700 | RE00220543

Remington Arms Company, Inc. ◆ 870 Remington Drive ◆ P.O. Box 700
Phone 800-243-9700 ◆ www.remington.com

Madison, NG 27025

Model Number: 700	Serial Number: 86529660
Are you the original owner?: YES NO	
Name: BRYAN SMITH «	Date of Purchase: 1984 ?
Address (no PO Boxes): 32/4 N Non	TH SHOPLE BOUND
city: WICHITA	State: KS Zip: 67205
Phone (Daytime): (3/2) 5%-2020	Fax:
E-mail Address:(if e-mail address is provided, notification	of receipt and shipment will be
sent) BRYANSMITHCE MORTONSA	
E-mail Address:	
Lucy Id Has be used to future a mail undates from For	sington
I would like to receive future e-mail updates from Ren	
Please describe your problem and date of occurrence:	
GUN FIRED WHEN TAKEN	OF OF SAFETY
TWO TIMES IN A ROW	. 1ST TIME W/
HANDLOAD AMMUNITION,	2ND TIME WITH
HE AMMUNITION.	
The second secon	
	: 기계 :
500	
Characters left	
Ammunition Information: HAND LOA) S	
Manufacturer:	Type:
Other (i.e. bullet weight/type, shot size, powder):	
Handload Information:	·
nandoza inomaton.	ANNA CA ATTION AND THE PROPERTY OF THE PROPERT
Powder Used:	Powder Weight:
Case/Hull Used:	Primer Used:
Bullet Type/Shot Size:	Reloader Used:

Firearms Care (Cleaning and Lubrication):
Brand of cleaning solution used:
How often do you clean the bore? (Months or Number of rounds)
How often do you clean the action? (Months or Number of rounds)
How often do you clean the trigger assembly? (Months or Number of rounds)
Brand of lubricant used:
How often do you lubricate the bore? (Months or Number of rounds)
How often do you lubricate the action? (Months or Number of rounds)
How often do you lubricate the trigger assembly? (Months or Number of rounds)
Have you reviewed the cleaning and maintenance recommendations on our web site or in our owners manual? YES NO
When was the last time that your firearm was serviced by a Remington authorized repairmen/gunsmith?) MEVER SERVICED
Tepanna vgursman)
What were the services performed?)
Remington Arms Co., Inc. Attn: Arms Service Division 14 Hoefler Avenue Ilion, NY 13357
①WARNING: DO NOT SEND LIVE OR SPENT SHELLS IN YOUR FIREARM OR IN THE SAME BOX WITH THE FIREARM. THIS IS A VIOLATION OF FEDERAL LAW. IF YOU FEEL YOU MUST SEND SPENT SHELLS PLEASE SEND THEM IN A SEPARATE PACKAGE AND INCLUDE NAME, ADDRESS (WITH ZIP CODE), TELEPHONE AND MODEL AND SERIAL NUMBER OF YOUR FIREARM.
:: Record the serial number of your firearm before sending it. :: Pack your firearm for safety and to prevent further damage in shipping and handling. Preferably, ship in a firearm box. (Note: Original boxes may not be returned.) :: Remove all accessories from your firearm to prevent loss or damage. :: Provide a return address on both the outside and inside the box. Shipments without a proper return address will be refused.



Remington Arms Company, Inc. 870 Remington Drive P. O. Box 700 Madison, NC 27025-0700

ARS LABEL REQUEST FORM

DATE: 12/20/20	010 REQUESTED BY:	christy
QUANTITY:	1 WEIGHT PER PACKAGE	E: 10
RLEASE CHECK ONE MEDIA COORDINATOR TO MAIL	· I WILL MAIL	xx
DESCRIPTION:	I WILL MAIL	
B6529660	700	·

LABEL INFORMATION

MAIL LABEL TO:	Brian Smith 3214 N Northshore Blvd Wichita, KS 67205
RETURN ITEM TO:	Rem Prod Service

REFASE COMPLETE ALL PARTIS OF THIS FORM AND SEND TO THE MEDIA COORDINATION

DEC 21, 2010 ALL CURR USD ACT WT 10.0 LBS 1 OF 1 4XX596 SVC GNDCOM TRACKING# 1Z4XX5969066199596 REF 1:BRIAN SMITH/CD/CM REF 2:700/B6529660 HANDLING CHARGE 0.00 SINGLE-PIECE PUB RATE CHRGS: SVC T/P USD RS 0.50 COD 0.00 DV 0.00 DC 0.00 AH 0.00 TOT PUB CHG 9.49 SD 0.00 DGD 0.00 SP 0.00 0.00 PR PUB+HANDLING 9.49







