

Remington Arms Co., Inc.
 Product Service
 Legal Case #:5439

Case Information

| RE# | Date Opened | Date Opened(PS) | Date Closed | Incident Date | Pre Lit | Lit | Obsolete |
|-----|-------------|-----------------|-------------|---------------|---------|-----|----------|
| | | 12/15/2010 | | | | | |

Customer Information

| Type | Business | First Name | Last Name | Street | City | State | Zip | Age | Contact |
|----------|----------|------------|-----------|--------------------|-----------|-------|-------|-----|----------------|
| Incident | | Bobby | Stahl | 2934 County Rd 463 | Stockdale | TX | 78160 | | H 830-534-5935 |

Incident Information

| Claims | Codes | Repair Est. | Medical Treatment | Medical Status |
|--------|--|-------------|-------------------|----------------|
| PI | | | | |
| PD | Cause:4079 Other - Unexamined | | Unknown | |
| S | Fired on safety release Concern:1007 Fired on Safe Release | | | |
| C | | | | |

12/15/10 Per call from Stahl, he owns a 2nd hand 700 BDL and it had fired on safe release twice. He has also had a problem with our ammo in the rifle. The primer was stuck on the bolt face and another primer stuck in the bolt lugs making it hard to open the bolt and he broke the handle off trying to open it.cm

Firearm Information

| Mfg. | Type | Model/Ga. | SKU | Serial | Bbl. | DOM |
|----------------|-----------------|-------------|----------------|--------|------|-----|
| Remington | CF/BA | 700/270 | n/a | | | |
| Date Purchased | Where Purchased | Accessories | Original Owner | | | |
| | | | N | | | |

Ammunition Information

| Mfg. | Type | Cal./Ga. | SKU | UPC | DOM | Mfg. Code |
|-----------|-------|----------|--------|-----|-----|-----------|
| Remington | BP/ | 270 WIN | | | | |
| Concern | Other | Factory | Reload | | | |
| 0: | | Y | N | | | |

Other Products Information - None Defined

Settlement

Remington/700/CF/BA

| Settlement | Release of Claims | Release Date | Reimbursement | Cash Settlement | Reim. Date APV | Cash Date APV |
|-------------------------|-------------------------|--------------|---------------|-----------------|----------------|---------------|
| Repair/Replacement Cost | Repair/Replacement Date | | | | | |

12/15/10 Mailing label for rifle and emailed Strickland to send one for 1/2 box unfired and the incident round and primers extracted.cm

Examination[Remington/CF/BA]

| Part | Sub-Part | Code | Comment |
|------|----------|------|---------|
| | | | |



www.remington.com

Remington Arms Company, Inc.
870 Remington Drive
P. O. Box 700
Madison, NC 27025-0700

ARS LABEL REQUEST FORM

| | | | |
|---------------------------|------------|---------------------|---------|
| DATE: | 12/15/2010 | REQUESTED BY: | christy |
| QUANTITY: | 1 | WEIGHT PER PACKAGE: | 10 |
| PLEASE CHECK ONE: | | | |
| MEDIA COORDINATOR TO MAIL | | xx | |
| DESCRIPTION: | | I WILL MAIL | |
| 700 | | | |

LABEL INFORMATION

| | |
|-----------------|--|
| MAIL LABEL TO: | Bobby Stahl 2934 County Rd 463 Stockdale, TX 78160 |
| RETURN ITEM TO: | Rem Prod Service |

PLEASE COMPLETE ALL PARTS OF THIS FORM AND SEND TO THE MEDIA COORDINATOR

4XX596 DEC 15, 2010 ALL CURR USD 1 OF 1
SVC GNDCOM ACT WT 10.0 LBS
TRACKING# 1Z4XX5969066646978
REF 1:BOBBY STAHL/CD/CM
REF 2:700

HANDLING CHARGE 0.00

| | | | |
|------------------------------|--------------|-------------|--|
| SINGLE-PIECE PUB RATE CHRGS: | | SVC T/P USD | |
| DV 0.00 | COD 0.00 | RS 0.50 | |
| DC 0.00 | DGD 0.00 | SD 0.00 | |
| AH 0.00 | PR 0.00 | SP 0.00 | |
| TOT PUB CHG 10.54 | PUB+HANDLING | 10.54 | |