

Remington Arms Co., Inc.

Product Service

Legal Case #:5582

Case Information

RE#	Date Opened	Date Opened(PS)	Date Closed	Incident Date	Pre Lit	Lit	Obsolete
		12/7/2010					

Customer Information

Type	Business	First Name	Last Name	Street	City	State	Zip	Age	Contact
Incident		Ronald	Vannoy	403 3rd Ave	Nutter Fort	WV	26301		H 304-623-1740 E rvannoy@ma.rr.com

Incident Information

Claims	Codes	Repair Est.	Medical Treatment	Medical Status
PI				
PD				
S	Fired when lifting the bolt	Cause:4079 Other - Unexamined Concern:1020 Fired on Bolt Opening	Unknown	
C				

12/7/10 Per email sent to Remington.com, incid # 101126-000039, "I have a model 700 BDL, (serial no. 196760) that has always been unsafe to use because it will discharge sometime when you lift the bolt handle to empty the chamber. I was told by a gunsmith to let him put a Canjar trigger trigger in it and it seemed to work fine, but has again begun to be unpredictable when letting the safety off to the fire position. Does Remington have a fix for this? The gunsmith who installed the Canjar trigger is deceased and I would like to get this issue resolved."cm

Firearm Information

Mfg.	Type	Model/Ga.	SKU	Serial	Bbl.	DOM
Remington	CF/BA	700/	n/a	196760		1/1/1966
Date Purchased	Where Purchased	Accessories	Original Owner			
			U			

Ammunition Information - None Defined

Other Products Information - None Defined

Settlement

Remington/700/CF/BA

Settlement	Release of Claims	Release Date	Reimbursement	Cash Settlement	Reim. Date APV	Cash Date APV
	Repair/Replacement Cost	Repair/Replacement Date				

1/7/11 Mailing box and ARS from Corporate due to the delay in sending to Vannoy.cm

Examination[Remington/CF/BA]

Part	Sub-Part	Code	Comment
------	----------	------	---------

Reference #
101126-000039

Status
Solved

Assigned To
Administrators
Christy -

Product
Firearms

SLA
Not specified

Queue
CSR

Date Created
11/26/2010 11:11 AM

Initial Response
12/07/2010 09:37 PM

Last Updated
12/11/2010 03:27 AM

Date Closed
12/11/2010 03:27 AM

Customer SmartSense
+1 (on -3 to +3 scale)

Staff SmartSense
0 (on -3 to +3 scale)

A form was submitted on REMINGTON - PROD.

Discussion Thread

Response (Christy -)

12/07/2010 09:37 PM

Mr. Vannoy, I apologize for the delay in responding. We can inspect the rifle at the factory. If you would like to send it, let me know what address you would like a UPS ground shipping label mailed to and we will contact you after inspection regarding the findings.

Sincerely,
Christy Mitchell

Customer (~~Dana~~ ~~Roberts~~)

11/26/2010 11:11 AM

Hello,

A form was submitted on the site. Please see submitted information below:

Form Title: Contact Us

First Name: Ronald

Last Name: Vannoy

Email: rvannoy@ma.rr.com

Address 1: 403 3Rd. Ave.

Address 2:

Telephone: 304-623-1740

City: Nutter Fort

State: WV.

Zip Code: 26301

Country: USA

Comments:

I have a model 700 BDL, (serial no. 196760) that has always been unsafe to use because it will discharge sometime when you lift the bolt handle to empty the chamber. I was told by a gunsmith to let him put a Canjar trigger trigger in it and it seemed to work fine, but has again begun to be unpredictable when letting the safety off to the fire position. Does Remington have a fix for this? The gunsmith who installed the Canjar trigger is deceased and I would like to get this issue resolved.

Primary Contact

First Name: ~~Dana~~

Last Name: ~~Roberts~~

Organization:

Login: ~~BRnWJXkzpdw48~~

Title:

Contact Type:

Email: ~~dana@42@remington.net~~

Email - Alternate #1:

Email - Alternate #2:

Office Phone:

Mobile Phone:

Fax:

Assistant Phone:

Home Phone:

Street

City

State/Province

Postal Code

Country

Additional Information



www.remington.com

Remington Arms Company, Inc.
870 Remington Drive
P. O. Box 700
Madison, NC 27025-0700

ARS LABEL REQUEST FORM

DATE:	1/7/2011	REQUESTED BY:	christy
QUANTITY:	1	WEIGHT PER PACKAGE:	10
PLEASE CHECK ONE			
MEDIA			
COORDINATOR			
TO MAIL			
DESCRIPTION:			
700 196760			

LABEL INFORMATION

MAIL LABEL TO:	Ronald Vannoy 403 3rd Ave Nutter Fort, WV 26301
RETURN ITEM TO:	Rem Product Service

PLEASE COMPLETE ALL PARTS OF THIS FORM AND SEND TO THE MEDIA COORDINATOR

4XX596 JAN 10, 2011 ALL CURR USD 1 OF 1
SVC GND COM ACT WT 10.0 LBS
TRACKING# 1Z4XX5969067504119
REF 1:RONALD VANNOY/CD/CM
REF 2:700/196760

HANDLING CHARGE 0.00
SINGLE-PIECE PUB RATE CHRGs: SVC T/P USD
DV 0.00 COD 0.00 RS 0.50
DC 0.00 DGD 0.00 SD 0.00
AH 0.00 PR 0.00 SP 0.00
TOT PUB CHG 8.24 PUB+HANDLING 8.24





