Remington Arms Co., Inc. **Product Service** Legal Case #:5119

Case Information

Date Opened(PS) **Incident Date** RE# **Date Opened Date Closed** Pre Lit Lit

12/17/2010 11/17/2010 12/28/2010 10/26/2010 215154

**Customer Information** 

Street City State Zip Age Contact Type Business First Name Last Name

H 435-574-0306 708 E. Mule Deer Rd Central UT 84722 Incident H. Ross Warner E hrwarner@gmail.com

Incident Information

Medical Medical Repair Est. Claims Codes Treatment Status

PΙ

Could Not Duplicate PD Cause:4038

Concern Unknown Fired when safety was

Concern:1007 Fired on Safe Release released

C

11/17/10 Per call from Warner, he has a Model 700 BDL .243 that he bought new in the '60's. The other day when he came back from hunting, he was in his workshop and released the safety and it fired. It had never happened before but he didn't use it much because he lived in AK and had used larger calibers.cm

Firearm Information

Model/Ga. SKU Mfg. Serial Bbl. **DOM** Type 700/243 WIN 1/1/1967 CF/BA n/a 283738 KP Remington

**Date Purchased** Where Purchased **Original Owner** Accessories Y

TWO PIECE SCOPE BASE

CONCERN:FSR

Ammunition Information - None Defined Other Products Information - None Defined

Settlement

Remington/700/CF/BA

Cash Release of Claims Release Date Date Settlement Reimbursement Date Settlement APV APV

Per Ilion, replace TPA, clean, test fire at BLSM program price

Repair/Replacement Repair/Replacement

Cost Date 1/5/2011

75.77

11/17/10 Mailing ARS and box.cm 1/5/11 Per Ilion, could not duplicate concern. Trigger set screws altered. Trigger assm dirty. Replace TPA, clean and test fire under BLSM program price. Called Warner and he approved repair.cm

Examination[Remington/CF/BA]

Part	Sub-Part	Code	Comment
	Examiner		B.TRAVIS
	Exam Date		12/28/2010

http://cps03ap13:200/psaapp/PrintDisplay.aspx?ID=5119&Type=Case

1/5/2011

Reim.

Cash

Obsolete

rimmonhia			1 agc 2 01
	Product Type		RF
Examination	Action Type		A
	Assigned To		T.NAGLE
Cause	4038	Could Not Duplicate Concern	
Barrel	Description		22" 243 WIN
	Date Code		KP
	Bore Plugged	False	
	Bulged	False	
	Fired	False	
	Fired while Obstructed		•
	Muzzle/Crown Condition	Slightly Worn; Functioning	
Bolt	Firing Pin	Slightly Worn; Functioning	
	Shroud	Slightly Worn; Functioning	
	Face	Slightly Worn; Functioning	
	Handle	Slightly Worn; Functioning	
	Stop	Slightly Worn; Functioning	
Extractor	Condition	Slightly Worn; Functioning	
	Cut Condition	Slightly Worn; Functioning	
	Ext/Eject Test	False	
Locking	Block Condition	Select	
	Lug Condition	Slightly Worn; Functioning	,
	Notch Condition	Select	
Overall	Exterior Condition	Slightly Worn; Functioning	
	Stock Condition	Slightly Worn; Functioning	
	Fore End Condition	Select	
Receiver	Condition	Slightly Worn; Functioning	
	Bulged	False	
Safety	Description		M/700 BOLT LOCK SAFETY
	Function	Like new; Functioning	
	Sub-Assembly	Non-ISS	
Sear	Lift	Select	.006
	Notch	Slightly Worn; Functioning	
		Test Fired	False
Feeding Test	Tests	False	
Trigger	Condition	Slightly Worn; Functioning	DIRTY
	Pull	Select	3#
	Altered	True	SET SCREWS ALTERED
	Sub-Assembly	M/700 Bolt Lock	
Non-Remington Components	Description		TWO PIECE SCOPE BASE

KP5/67

November 17, 2010

H. Ross Warner 708 E. Mule Deer Rd Central, UT 84722

Subject: #5119, Model 700

Dear Mr. Warner,

Enclosed is a UPS ground prepaid shipping label. Please include a copy of this letter with the firearm. The letter inside is important as sometimes the outside label gets damaged in transit and we want to be sure the firearm is logged in correctly. Please mark the ends of the box with "Product Service".

I apologize for the inconvenience that this incident has caused and I hope that these actions will keep you as a loyal Remington customer.

Sincerely,

Christy Mitchell Consumer Affairs Administrator Phone: 800-243-9700, ext 8684 christy.mitchell@remington.com

20.40 21 -35-17.5°

enclosure



iculd Mot dup I coate CONCERM

T. A. Set schens Actered. T.A. DIRLY. Ry hace TPA, clears YOST Clin under BLP Con 8 20.00 + Ship

Quote 120224VIII 1Ain 042011

Remington Arms Company, Inc. • 870 Remington Drive • P.O. Box 700 • Madison, NC 27025 Phone 800-243-9700 • www.remington.com

Model Number: 700 BDL	Serial Number: 283738
Are you the original owner?: X YES NO	
Name: H.Ross WARNER .	Date of Purchase: 1966 or so.
Address (no PO Boxes): 708 E. Mule I	Deerkd.
City: Central	State: UT Zip: 84722
Phone (Daytime): 435-574-0306	Fax:
E-mail Address:(if e-mail address is provided, notification of the sent) HRWARNER @ Gmail	
E-mail Address:	
I would like to receive future e-mail updates from F	Remington.
Please describe your problem and date of occurren	ce:
October 26, 2010 a	
	ber on my cleaning
11	ik the next morning
to unload and cle	ran the weapon . Upon
releasing the sofil	Ty the gun fired (No
finger on the trigg	es) also noone purt
characters left	
Ammunition Information:	
Manufacturer: REMINGTON	Type: 243 Win
Other (i.e. bullet weight/type, shot size, powder): 10	OGR. Core-Lokt PTd Soft PT.
Handload Information:	
Powder Used:	Powder Weight:
Case/Hull Used:	Primer Used:
Bullet Type/Shot Size:	Reloader Used:

Firearms Care (Cleaning and Lubrication):
Brand of cleaning solution used: PRO SHOT 1 Step Gun Cleaner & Lub
How often do you clean the bore? (Months or Number of rounds) After each use: OR
How often do you clean the action? (Months or Number of rounds) After each use.
How often do you clean the trigger assembly? (Months or Number of rounds) After each use.
Brand of lubricant used: BUTCH'S GUN OIL
How often do you lubricate the bore? (Months or Number of rounds) After Use ORNA
How often do you lubricate the action? (Months or Number of rounds): After US
How often do you lubricate the trigger assembly? (Months or Number of rounds) After Use.
Have you reviewed the cleaning and maintenance recommendations on our web site or in our owners manual?  YES X NO
When was the last time that your firearm was serviced by a Remington authorized
repairman/gunsmith?) Never
What were the services performed?)
Remington Arms Co., Inc.  Attn: Arms Service Division  14 Hoefler Avenue  Winn NY 13357  There is have not  Cleaned the weaper  Since last dischar
14 Hoefler Avenue Ilion, NY 13357  Since last dischar
●WARNING: DO NOT SEND LIVE OR SPENT SHELLS IN YOUR FIREARM OR IN THE SAME BOX WITH THE FIREARM. THIS IS A VIOLATION OF FEDERAL LAW. IF YOU FEEL YOU MUST SEND SPENT SHELLS PLEASE SEND THEM IN A SEPARATE PACKAGE AND INCLUDE NAME, ADDRESS (WITH ZIP CODE), TELEPHONE AND MODEL AND SERIAL NUMBER OF YOUR FIREARM.
:: Record the serial number of your firearm before sending it. :: Pack your firearm for safety and to prevent further damage in shipping and handling. Preferably, ship in a firearm box. (Note: Original boxes may not be returned.)  :: Remove all accessories from your firearm to prevent loss or damage. :: Provide a return address on both the outside and inside the box. Shipments without a proper return address will be refused.







