Remington Arms Co., Inc.
Product Service
Legal Case #:5138

| Case I |  |  |
|--------|--|--|
|        |  |  |
|        |  |  |

RE# Date Opened Date Opened(PS) Date Closed Incident Date Pre Lit Lit Obsolete
213186 12/8/2010 11/18/2010 12/9/2010

Customer Information

Last Name Street City Type **Business** First Name State Zip Age Contact H 814-673-3847 Weisenfluh 1025 W. 3rd St Oil City PA 16301 Incident Kevin E kweisnfluh@comcast.net

Incident Information

Claims Codes Repair Est. Medical Treatment Medical Status

ΡI

PD Cause:4015 Improper Maintenance
S Fired when safety was released Concern:1007 Fired on Safe Release
Unknown

S Fired when safety was released C

11/18/10 Per call from Weisenfluh, he has a 700 30-06 that was passed down to him from his uncle. Last year his father was shooting it and it fired when he released the safety. It has a bolt lock and he wants that removed.cm

Firearm Information

Model/Ga. SKU Mfg. Type Serial Bbl. DOM CF/BA 700/30-06 SPR n/a 363158 DR 1/1/1968 Remington Where Purchased Accessories **Original Owner Date Purchased** 

N

CONCERN:FSR

Ammunition Information - None Defined Other Products Information - None Defined Settlement

Remington/700/CF/BA

Settlement Release of Claims Release Date Reimbursement Cash Reim. Date APV APV

Per Ilion, replace trigger, clean at BLSM program price

Repair/Replacement
Cost
40.23

Repair/Replacement
Date
12/13/2010

11/18/10 Mailing ARS and box.cm 12/13/10 Per Ilion, Trigger assm very dirty and sticky causing parts to work sluggish. Replace TPA, clean and test fire under BLM program price for \$20 + shipping. Emailed Weisenfluh the estimate and inspect info.cm

12/14 Kevin called approved.

Examination[Remington/CF/BA]

| Part | Sub-Part | Code | Comi     | ment |
|------|----------|------|----------|------|
| E    | xaminer  |      | B.TRAVIS | ,    |
|      |          |      | 10/0/0   |      |

|             | Exam Date    | ]                    | 12/9/2010     |
|-------------|--------------|----------------------|---------------|
| Examination | Product Type |                      | RF            |
|             | Action Type  | ]                    | A             |
|             | Assigned To  | ]                    | T.NAGLE       |
| Cause       | 4015         | Improper Maintenance |               |
|             | Description  |                      | 22" 30-06 SPR |
| <b>I</b>    | Date Code    |                      | DR            |
| Barrel      | Bore Plugged | False                |               |
|             | Bulged       | False                | ·             |
| <u>[</u> ]  | Fired        | False                | ]             |

|                         | Fired while Obstructed            | _1                             |                                 |
|-------------------------|-----------------------------------|--------------------------------|---------------------------------|
| •                       | Muzzle/Crown Condition            | Slightly Worn; Functioning     |                                 |
|                         | Firing Pin                        | Slightly Worn; Functioning     | SLUGGISH                        |
|                         | Shroud Slightly Worn; Functioning |                                |                                 |
| Bolt                    | Face                              | Slightly Worn; Functioning     |                                 |
|                         | Handle                            | Slightly Worn; Functioning     |                                 |
|                         | Stop                              | Slightly Worn; Functioning     | SLUGGISH                        |
|                         | Condition                         | Slightly Worn; Functioning     |                                 |
| Extractor               | Cut Condition                     | Slightly Worn; Functioning     |                                 |
|                         | Ext/Eject Test                    | False                          |                                 |
|                         | Block Condition                   | Select                         |                                 |
| Locking                 | Lug Condition                     | Slightly Worn; Functioning     |                                 |
|                         | Notch Condition                   | Select                         |                                 |
|                         | Exterior Condition                | Slightly Worn; Not Functioning |                                 |
| Overall Stock Condition |                                   | Slightly Worn; Functioning     |                                 |
| Fore End Condition      |                                   | Select                         |                                 |
| IIReceiver              |                                   | Slightly Worn; Functioning     |                                 |
| Bulged False            |                                   | False                          |                                 |
|                         | Description                       |                                | STANDARD M/700 BOLT LOCK SAFETY |
| Safety Function         |                                   | Like new; Functioning          |                                 |
|                         | Sub-Assembly                      | Non-ISS                        |                                 |
|                         | LiftSelect                        |                                | .009                            |
| Sear                    | Notch                             | Slightly Worn; Functioning     |                                 |
|                         | Toota                             | Test Fired                     | False                           |
| Feeding Tests False     |                                   | False                          |                                 |
|                         | Condition                         | Slightly Worn; Not Functioning | DIRTY STICKY TRIG NOT RETURNING |
| Trican                  | Pull                              | Select                         | 4#                              |
| Trigger                 | Altered                           | False                          | ·                               |
|                         | Sub-Assembly                      | M/700 Bolt Lock                |                                 |

|     | 1000   | mREInquir   | المتاز والراج                 | grada (1871 g)iş    | art in Golden to the con-               | st war constitute  | ye sayan da sayan<br>Kara sayan kasa bada | leg out it and<br>Marketine I by | ر<br>معادد مناه<br><u>(م الدائما (موا</u>       | (在元章( <b>)</b> 在   | garantara                  | teriorista<br>Seriorista | en e   |                  |        |
|-----|--------|---|-------------------------------|---------------------|---|--|---|----------------------------------|---|--|----------------------------|--------------------------|--|------------------|--------|
| ,   |        | pair, Number  | RE0                           | 0213186             | Serial<br> sprg                         | 363158 Móde  | l 700: Center Fi                          | ire Caliber 3                    | 006, j  | Repairman:   |                            |                          | The second of the  |                  |        |
|     | 1      | enly Repair   | 0004                          |                     |   |  |   |                                  |   | Status   | New 12/8                   | /2010 7:43:3             | 3 AM   |                  | )<br>k |
| l.  |        | UDHESS INF  | Custo                         | 2 1 100             |   |  | <b>⊙</b> Received fro                     | om Ret                           | in To   |  |                            | <b>C</b> Re              | ceived from  | 1 3 X            |        |
| ļ   |        | Name:   | KEVIN                         | WEISENFL            | UH                                      | Table Africa and Table 1.  | A MARKET SERVICE STREET                   |                                  | IN WEISE  | NFLUH  | The district of the second | Carried Artis            | erne en e   |                  |        |
| ľ   |        | (Address 1:   | 1025\                         | w. 3RD ST.          | •                                       | rémetéraké   |   | 102                              | W. 3RD 9  | ST.  | 34 " 547.64                |                          |  |                  |        |
| E   |        | Address 2   | OIL CI                        | TO.                 | * | PO Böx   |   | OIL                              | CITU  |  | PO B                       | ox:                      |  |                  |        |
|     |        | City:   |                               | Zip Code:           | 16301                                   | Country:   | lus .                                     | PA                               | ~~  | je 16301   |                            | intry US                 |  |                  | À      |
|     |        | 1177 ans. 4 44                                      | 1000mm                        | archine             | KKASELO                                 | and the same   | rFL                                       |                                  | इ.स. क्षेत्र स्ट्रा स्ट्रिकेट हैं।<br>जनसङ्ख्या |  | 25 mg/h/87                 |                          | discould be a least  |                  |        |
|     |        |   |                               |                     |   |  |   |                                  |   |  |                            |                          | BAR POR  |                  |        |
|     | L      | nlact / Lond  | tion   P                      | roblems   E         | stimate ( Tist                          | in / status  | Shipping 7 Billing                        |                                  |   |  | ray):                      | Current S                |  |                  |        |
|     |        | Date 🦠  |                               |                     | 1                                       | ∷ '.Desc1  |   | Desc2                            |   | pping Hold   | 為建訂                        | Ne                       | W Control  |                  |        |
|     |        | 12/8/2010 7   | -                             | ew                  | lopatafi                                | Repair Add   | <del> </del>                              | To:                              | Asel-ta.  | rface Hold<br>mate Sent  |                            | 412/8/2010<br>lopa       |  |                  |        |
|     | 炒      | 12/8/2010 7   | -+                            | xpedite<br>mailSent | lopatafi<br>ArmEmail                    | From: Chec<br>Repair Rec   | <del></del>                               | kweisenflu                       | Î-Î-Par   | ts Received  |                            | Repair                   | Bench,   |                  |        |
|     |        | 12/8/2010 1   |                               | mailVerified        | ArmEmail                                | Receipt  |   | kweisenflu                       | _] ,  | ssed Inspect   |                            | Repair Lo                | N  |                  |        |
| 2.5 |        | 12/9/2010 2   |                               | laint               | Travisbw                                | Repair Mair  | ntenance                                  | Status: Ne                       |   | urn as Rece<br>s Been Appr   |                            | Current L                |  |                  |        |
| 7   |        | 1 10 10 10 10                                       | 异基合物                          | 数据的数                | <b>次载为200</b> 0分                        | <b>不可当然</b> 源 否  |   | 为海峡等沿水                           |   | rnal Repair  |                            | Transfer i               |  | 13674            |        |
| -50 |        | Wagner 24   | 3.48                          | 知為的數                | 松本計劃                                    | N. Y. Y.   |   | 1276576                          | ΓExc  | lude TATC  |                            |                          |  |                  | 7      |
| ].  |        | Repair Se   | arch                          |                     |   |  | 784                                       |                                  |   |  |                            | Refresh                  |  | lose             | ŝ      |
|     | A A    | * 500 562 E**<br>********************************** | र्थ स्टब्स्<br>इंग्रेस्ट्रिक् | 177                 |   |  |   |                                  | 机气的   | A PARTY  |                            | 公本上表现。<br>一个如此 VATA      | A STATE OF THE STA | Marian September | Å.     |
| l   | ek ye. | <b>经人通过</b>   | arges).<br>Nam                | 42 30 44            | 化加基础                                    | AVAIMES!   | ringstim                                  |                                  | A Carlo   | E. W. K. C.  |                            | ing Application within   | artiko (a. jarajor).<br>Mangara  | 7.74.1.22        | 0      |
|     |        |   | raid.                         |                     |   |  |   |                                  |   |  |                            |                          |  |                  |        |
|     |        |   |                               |                     | <b>以后来</b>                              |  |   | WHITE SERVE                      |   |  |                            |                          |  |                  |        |
|     |        |   |                               |                     |   | The state of the s |   |                                  | ***************************************         | the state of the s | •                          |                          |  |                  |        |
|     |        |   |                               |                     |   |  |   |                                  |   |  |                            |                          |  |                  |        |

DEC 1 0 2010

5138

72" Di29/68

November 18, 2010

Kevin Weisenfluh 1025 W. 3<sup>rd</sup> St. Oil City, PA 16301

Subject: #5138, Model 700

Dear Mr. Weisenfluh,

Enclosed is a UPS ground prepaid shipping label. Please include a copy of this letter with the firearm. The letter inside is important as sometimes the outside label gets damaged in transit and we want to be sure the firearm is logged in correctly. Please mark the ends of the box with "Product Service".

I apologize for the inconvenience that this incident has caused and I hope that these actions will keep you as a loyal Remington customer.

Sincerely,

Christy Mitchell Consumer Affairs Administrator Phone: 800-243-9700, ext 8684 christy.mitchell@remington.com

enclosure

363158 Model: 700 RE00213186 T.A. VERY DIRTY + STICKY CAUSING PARTS to WORLK
SCUGGESH. PUPLACETPA
cleAN + Test CIPL
UNDER BLP Con \$ 20.00 +
Ship
Quale

Remington Arms Company, Inc. • 870 Remington Drive • P.O. Box 700 • Madison, NC 27025 Phone 800-243-9700 • www.remington.com

| Model Number: Model 700  | Serial Number: 363158                      |
|--|--|
| Are you the original owner?: YES NO  |  |
| Name: Keuin Weisenfluh .   | Date of Purchase: 1986                     |
| Address (no PO Boxes): 1025 W 3rd  | street                                     |
| City: Oil City   | State: PA Zip: 1-6301                      |
| Phone (Daytime): 814-673-3847  | Fax:                                       |
| E-mail Address:(if e-mail address is provided, notification  | n of receipt and shipment will be          |
| sent) Kweisenflut@comcas   | tinet                                      |
| E-mail Address:  |  |
| I would like to receive future e-mail updates from Re  |  |
| Please describe your problem and date of occurrence  |  |
| Miss fired on taking<br>ehamber new round  | s safety off and and and and and mussfired |
|  |  |
|  |  |
|  |  |
|  |  |
|  | $\mathcal{L}^{(2)}$                        |
|  | · ,  |
|  | and the same and the same and the 🚨 🖰      |
| 500 characters left  |  |
| Ammunition Information:  |  |
|  |  |
| Manufacturer: Remins ton   | Type: Silver tip                           |
| low  |  |
| Other (i.e. bullet weight/type, shot size, powder): 140  | 2 grains                                   |
|  |  |
| Handload Information:  |  |
| Powder Used:   | Powder Weight:                             |
| Case/Hull Used:  | Primer Used:                               |
| The state of the s |  |

Firearms Care (Cleaning and Lubrication): Brand of cleaning solution used: How often do you clean the bore? (Months or Number of rounds) o (ounds How often do you clean the action? (Months or Number of rounds) How often do you clean the trigger assembly? (Months or Number of rounds) Brand of lubricant used: How often do you lubricate the bore? (Months or Number of rounds) 6 rounds How often do you lubricate the action? (Months or Number of rounds) How often do you lubricate the trigger assembly? (Months or Number of rounds) Have you reviewed the cleaning and maintenance recommendations on our web site or in our owners manual? YES X NO When was the last time that your firearm was serviced by a Remington authorized repairman/gunsmith?) What were the services performed?) Remington Arms Co., Inc. Attn: Arms Service Division 14 Hoefler Avenue Ilion, NY 13357 **WARNING:** DO NOT SEND LIVE OR SPENT SHELLS IN YOUR FIREARM OR IN THE SAME BOX WITH THE FIREARM. THIS IS A VIOLATION OF FEDERAL LAW. IF YOU FEEL YOU MUST SEND SPENT SHELLS PLEASE SEND THEM IN A SEPARATE PACKAGE AND INCLUDE NAME, ADDRESS (WITH ZIP CODE), TELEPHONE AND MODEL AND SERIAL NUMBER OF YOUR FIREARM. :: Record the serial number of your firearm before sending it. :: Pack your firearm for safety and to prevent further damage in shipping and handling. Preferably, ship in a firearm box. (Note: Original boxes may not be returned.) :: Remove all accessories from your firearm to prevent loss or damage. :: Provide a return address on both the outside and inside the box. Shipments without a proper return address will be refused.







