Remington Arms Co., Inc. **Product Service** Legal Case #:4928

Case Information

Date Opened(PS) **Date Closed Incident Date** Pre Lit Obsolete RE# **Date Opened** Lit 11/16/2010 11/2/2010 11/17/2010 210468 Customer Information Contact **Business** First Name Last Name Street City State Zip Type Age 101 Nathan Hale Dr Incident Albert Wolfe Starkville MS 39759 C 662-312-7684 Incident Information **Medical Treatment Medical Status** Codes Repair Est. Claims ΡI

PD Cause:4038 Could Not Duplicate Concern Concern: 1008 Fired on Bolt Closing

Unknown

C FBC

S

11/2/10: Customer called in. He saw TV show and stated that he had FBC about a year ago while hunting. No damage. No injury. df

Firearm Information

Model/Ga. SKU Serial Bbl. **DOM** Mfg. Type 700/270 WIN 27476 CF/BA E6494352 ES 10/1/1998 Remington **Date Purchased** Where Purchased Accessories **Original Owner** 12/24/1999 SPORTS SOUTH INC SCOPE BASE, AND RINGS Y

CONCRN:FBC

Ammunition Information - None Defined Other Products Information - None Defined Settlement

Remington/700/CF/BA

Cash Cash Reim. Release of Claims Release Date Reimbursement Settlement Date Settlement Date APV APV

Per Ilion - Quote to repair @ 1/2 normal charges

Repair/Replacement Cost Repair/Replacement Date

11/2/10: Sending ARS, ltr, form & box. Box order# 1154611. df 11/22/10: Per Ilion - Could not duplicate concern. TA very dirty. Offering to replace TA, clean & test fire @ 1/2 normal charges to restore confidence in rifle. df 11/22/10: I called cust. & went over report. He asked me to mail him the quote & he would get back w/me. df 11/23/10: Customer called. He will send money order with quote, df

Examination[Remington/CF/BA]

Part	Sub-Part	Code	Comment
	Examiner		F.SUPRY
	Exam Date		11/17/2010
Examination	Product Type		RF
	Action Type		A
	Assigned To		F.SUPRY
Cause	4038	Could Not Duplicate Concern	
	Description		22" 270 WIN
	Date Code		ES
	Bore Plugged	False	
Barrel	Bulged	False	
	Fired	False	
	Fired while Obstructed		

	Muzzle/Crown Condition	Slightly Worn; Functioning	
	Firing Pin	Slightly Worn; Functioning	
Bolt	Shroud	Slightly Worn; Functioning	
	Face	Slightly Worn; Functioning	SOME BRASS WASH
	Handle	Slightly Worn; Functioning	
	Stop	Slightly Worn; Functioning	
	Condition	Slightly Worn; Functioning	
Extractor	Cut Condition	Slightly Worn; Functioning	
	Ext/Eject Test	False	
	Block Condition	Select	
Locking	Lug Condition	Slightly Worn; Functioning	
	Notch Condition	Select	
	Exterior Condition	Slightly Worn; Functioning	
Overall	Stock Condition	Slightly Worn; Functioning	
	Fore End Condition	Select	
n :	Condition	Slightly Worn; Functioning	
Receiver	Bulged	False	
	Description		STANDARD M/700 SAFETY
Safety	Function	Like new; Functioning	
	Sub-Assembly	Non-ISS	
<u> </u>	Lift	Select	012
Sear	Notch	Slightly Worn; Functioning	
		Test Fired	False
Feeding Test	Tests	False	
	Condition	Slightly Worn; Functioning	DIRTY
m ·	Pull	Select	5#
Trigger	Altered	False	
	Sub-Assembly	M/700 Non-Bolt Lock	
Non-Remington Components	Description		SCOPE BASE, AND RINGS

QUOTATION

Remington Arms Company, Inc.

870 Remington Dr. P.O. Box 700 Madison, NC 27025-0700 ESTIMATING REPORT

Parts/Repairs Fax 800-243-9700 336-548-7801

www.remington.com info@remington.com


ALE PRICES QUOTED ARE IN EXCHANGE FOR REPLACED PARTS.


THIS IS NOT AN INVOICE. THIS IS AN ESTIMATE TO REPAIR, RECONDITION, OR REPLACE THE ITEM(S) DESCRIBED BELOW. IF THIS IS SATISFACTORY, PLEASE APPROVE BY SIGNING BELOW AND RETURNING TO THE ABOVE ADDRESS. REPAIR TO TAKE APPROXIMATELY (4) WEEKS AFTER RECEIPT OF APPROVAL. IF WE DO NOT RECEIVE YOUR APPROVAL IN 15 DAYS, WE SHALL RETURN THE ITEM(S) AS RECEIVED POSTAGE DUE.

Repair Order Number	Description/Serial Number	Date Received - 11/16/2010				
RE00210468	E6494352	Estimate Date - 11/17/2010				
RE00210406 Account # - R-	E0494332	Current Date - 11/22/2010				
1.000		* * * * * * * * * * * * * * * * * * *				
Customer		Return To				
ALBERT WOLFE		ALBERT WOLFE				
101 NATHAN HALE DR.		101 NATHAN HALE DR.				
		OF A DAVING A D. A. C. A				
STARKVILLE. MS 39759 US		STARKVILLE. MS 39759 US				
Phone (H) (662)-312-7684	Fax					
Phone (W)	Email					
Please Circle One						
VISA MC AMEX DISCOVER Card No)	Exp. Date				
PO Number						
Daytime Phone ()	Time To Call	Open Acct. R				
Approval: Customer Signature Date						
If You Desire Any Change Please Use	If You Desire Any Change Please Use The Reverse Side For Your Comments And Mark This Box Notice: We process checks electronically through Check 21 Problems Reported Found					
No.	tice: We process checks electronically through	ugh Check 21				
	Problems					
Reported	Found					
gant and the second of the second and the second a						
1	or series in the series was regardled events. Series and account of a series of the se	 Selection of the selection of the selection. 				
M100 SEE CUSTOMERS LET	}					
· ·	TER M123					
M100 SEE CUSTOMERS LET	TER M123					
M100 SEE CUSTOMERS LET M123 FORWARD TO PRODU	TER M123					
M100 SEE CUSTOMERS LET M123 FORWARD TO PRODU FOR INSPECTIO	TER M123 JCT SERVICE	FORWARD TO PRODUCT SERVICE F				
M100 SEE CUSTOMERS LET M123 FORWARD TO PRODU FOR INSPECTIO	TER M123 JCT SERVICE					
M100 SEE CUSTOMERS LET M123 FORWARD TO PRODU FOR INSPECTIO	TER M123 JCT SERVICE Technician's Comments	FORWARD TO PRODUCT SERVICE F				
M100 SEE CUSTOMERS LET M123 FORWARD TO PRODU FOR INSPECTIO ProblemNotes could not duplicate con	TER M123 JCT SERVICE Technician's Comments cern.trigger assm very dirty.can of	FORWARD TO PRODUCT SERVICE F				
M100 SEE CUSTOMERS LET M123 FORWARD TO PRODU FOR INSPECTIO ProblemNotes could not duplicate con	TER M123 JCT SERVICE Technician's Comments	FORWARD TO PRODUCT SERVICE F				
M100 SEE CUSTOMERS LET M123 FORWARD TO PRODU FOR INSPECTIO ProblemNotes could not duplicate con	TER M123 JCT SERVICE Technician's Comments cern.trigger assm very dirty.can of	FORWARD TO PRODUCT SERVICE F				

Estimate **COD. Shinning and Handling Charges are NOT Included in this Quote

Material #	Material Description	<u>Otv</u>	Warranty Y/N	<u>Price/</u> Unit	<u>Discount</u> Percent	Extended Amt
Part						
F305570B	X-MARK PRO 700 TRIG ASSB RH BLACK (O	1	N	\$94.00	50%	\$47.00
Service						
4000114	GR-SHIPPING & HANDLING (GUN REPAIR)	1	N	\$17.00	0%	\$17.00
4000119	GR-TEST	1	N	\$23.00	50%	\$11.50
				Sub Total	•	\$75.50
				Est. Sales 7	Гах:	\$5.29
				Grand To	tal:	\$80.79





4928

COPY/

November 2, 2010

Albert Wolfe 101 Nathan Hale Dr. Starkville, MS 39759 Ph: 662-312-7684

Ref: #4928

Dear Mr. Wolfe,

Please include a copy of this letter & our form to put inside the shipping container. The letter inside is important as sometimes the outside label gets damaged in transit and we want to be sure the firearm is logged in correctly. Mark the ends of the boxes with the name "Supry". Mr. Supry will be inspecting the firearm and will contact me with the results.

I hope that this action will keep you a loyal Remington customer.

Sincerely,
D. Fulcher
Consumer Affairs Administrator
Remington, H&R, Marlin
Phone: 1-800-243-9700

Fax: 336-548-7872

df enclosure

E6494352 Model: 700 RE00210468 could not duplicate LONCERN.

TRIO. ASSMUZRY DINLY, CAN

often to replace TPA, elean

trest fine at 1/2 Normal

changes to restone confidence

in Rife.

ande

Model Number: (4/2 270	Serial	Number:			
REMINGTON Mode 1700	F 6 49 4352				
Name:	Date of Purchase:				
AIBERT WOIFE	12-24-99				
Address (no PO Boxes):					
101 Nathan Halk Dr					
City: STARKVILLE	State: Zip: 39759				
Phone	Phone				
(Daytime): 462 3127684	(Daytime): 4623127684				
E-mail Address:					
Please describe your problem:					
Shot the Gun, Eje	Shot the Gun, Ejected the Shell.				
Injected another	Shell w	iththe			
bolt, The gun misfired, without					
pulling the trig	qer.				
500 chara	cters left				
NOTE: Prior to shipping your firearm, contact the Repair Center for services provided and estimated repair time.					
WARNING: DO NOT SEND LIVE OR SPENT SHELLS IN YOUR FIREARM OR IN THE SAME BOX WITH THE FIREARM. THIS IS A VIOLATION OF FEDERAL LAW. IF YOU FEEL YOU MUST SEND SPENT SHELLS PLEASE SEND THEM IN A SEPARATE PACKAGE AND INCLUDE NAME, ADDRESS (WITH ZIP CODE), TELEPHONE AND MODEL AND SERIAL NUMBER OF YOUR FIREARM. :: Record the serial number of your firearm before sending it. :: Pack your firearm for safety and to prevent further damage in shipping and handling. Preferably, ship in a firearm box. (Note: Original boxes may not be returned.) :: Remove all accessories from your firearm to prevent loss or damage. :: Ship your INSURED firearm by either UPS or Parcel Post. Remington is not responsible for damage or loss during shipment, so you may elect to purchase insurance from your carrier.					
Print	Reset				



Remington Arms Company, Inc. 870 Remington Drive P. O. Box 700 Madison, NC 27025-0700

ARS LABEL REQUEST FORM

DATE:		11/2/2010	REQUESTED BY:	Dell
QUANTITY:		1	WEIGHT PER PACK	A 10 lbs
PLEASEICHECKONE MEDIA COORDINATOR TO MAIL			I WILL MAIL	XXXXXX
DESCRIPTION:	Ref# 4928 Rifle			

LABEL INFORMATION

MAIL LABEL TO: Albert Wolfe

101 Nathan Hale Dr.
Starkville, MS 39759
Ph: 662-312-7684

RETURN ITEM TC Remington Arms
Attn: Product Service
Ilion, NY

RUEASERCOMPLETE AND PARTIS FORM AND SEND TO THE MEDIA COORDINATOR

2010 ALL CURR USD ACT UT 10 0 LES NOV 2, 2010 1 0F 1 SVC GNOCOM TRACKINGH 1242X5969065745834 REF 1:ALBERT WOLFE/CD/DMF REF 2:4928/RIFLE HANDLING CHARGE 0.00 SINGLE-PIECE PUB RRIE CHRGS: SVC T/P USD DV 0.00 COD Ø ØØ DGD Ø ØØ RS 0.50 DC 0.00 SD 0.00 AH 0.00 PR 0 00 SP 0.00 TOT PUB CHG 8.78 PUB+HANDLING 8.78

