

Remington Arms Co., Inc.
Product Service
Legal Case #:4771

Case Information

RE#	Date Opened	Date Opened(PS)	Date Closed	Incident Date	Pre Lit	Lit	Obsolete
205339	10/7/2010	10/8/2010	10/8/2010				

Customer Information

Type	Business	First Name	Last Name	Street	City	State	Zip	Age	Contact
Incident		Lyndon	Zuiderveen	8300 South Forward Rd	McBain	MI	49657		H 231-590-4533 E zuiderveenl@michigan.gov

Incident Information

Claims	Codes	Repair Est.	Medical Treatment	Medical Status
PI				
PD	Cause:4038	Could Not Duplicate Concern		
S	fires on safe release	Concern:1007 Fired on Safe Release	Unknown	
C				

10/14/10 Per letter with rifle, this gun will fire when you take the safety off. It has done it 2 times this last hunting season. He saw on our site there there is a safety update that can be done on the rifle.cm

Firearm Information

Mfg.	Type	Model/Ga.	SKU	Serial	Bbl.	DOM
Remington	CF/BA	700/3006 SPR	n/a	A6885630	AA	2/9/1980
Date Purchased	Where Purchased	Accessories	Original Owner			
	WILLIAMS SPTG CADILLAC MI		U			

CONCERN:FSR

Ammunition Information - None Defined

Other Products Information - None Defined

Settlement

Remington/700/CF/BA

Settlement	Release of Claims	Release Date	Reimbursement	Cash Settlement	Reim. Date APV	Cash Date APV
Per Ilion, replace TPA, clean, test under BLSM program price						
	Repair/Replacement Cost	Repair/Replacement Date				
	30.23	10/14/2010				

10/14/10 Per Ilion, could not duplicate concern. Check over, replace TPA, clean and test fire under bolt lock program price of \$20 + S&H.cm

Examination[Remington/CF/BA]

Part	Sub-Part	Code	Comment
Examination	Examiner		B.TRAVIS
	Exam Date		10/8/2010
	Product Type		RF
	Action Type		A
	Assigned To		F.SUPRY
Cause	4038	Could Not Duplicate Concern	
Barrel	Description		22" 3006 SPR
	Date Code		AA
	Bore Plugged	False	
	Bulged	False	
	Fired	False	
	Fired while Obstructed		
	Muzzle/Crown Condition	Slightly Worn; Functioning	

Bolt	Firing Pin	Slightly Worn; Functioning	
	Shroud	Slightly Worn; Functioning	
	Face	Slightly Worn; Functioning	
	Handle	Slightly Worn; Functioning	
	Stop	Slightly Worn; Functioning	
Extractor	Condition	Slightly Worn; Functioning	
	Cut Condition	Slightly Worn; Functioning	
	Ext/Eject Test	False	
Locking	Block Condition	---Select---	
	Lug Condition	Slightly Worn; Functioning	
	Notch Condition	---Select---	
Overall	Exterior Condition	Slightly Worn; Functioning	
	Stock Condition	Slightly Worn; Functioning	
	Fore End Condition	---Select---	
Receiver	Condition	Slightly Worn; Functioning	
	Bulged	False	
Safety	Description		STANDARD M/700 BOLT LOCK SAFETY
	Function	Like new; Functioning	
	Sub-Assembly	Non-ISS	
Sear	Lift	---Select---	.011
	Notch	Slightly Worn; Functioning	
	Tests	Test Fired	False
Feeding Test	Tests	False	
Trigger	Condition	Slightly Worn; Functioning	
	Pull	---Select---	3.5#
	Altered	True	SET SCREWS ALTERED
	Sub-Assembly	M/700 Bolt Lock	

frmRepairMain - FGI Repairs

File
Add Repair
Estimate Repair
Expedite Repair
Inquiry
Repair Tools
CSR Tools
Reports
Table Maintenance
System

frmREInquiry - Repair Inquiry

Repair Number: RE00205339
Serial: A6885630, Model 700, Center Fire, Caliber: 30, 06 SPRG Produced: 02/09/1980 SKU: 20000

Repairman: Bruce Travis
Status: Repairing 10/8/2010 5:00:06 PM

Verify Repair

ADDRESS INFORMATION

Customer

Received from

Return To

Received from

Name: LYNDON ZUIDERVEEN
Address 1: 8300 S FORWARD RD
Address 2:
City: MCBAIN
State: MI Zip Code: 49657 Country: US

Name: LYNDON ZUIDERVEEN
Address 1: 8300 S FORWARD RD
Address 2:
City: MCBAIN
State: MI Zip Code: 49657 Country: US

Contact / Condition

Problems

Estimate

History / Status

Shipping / Billing

Date	Code	User ID	Desc1	Desc2
10/8/2010 4:5...	Approved	harperam	Phone call	
10/8/2010 5:0...	Repairing	System	Immediate SAP Allocation	
10/11/2010 5...	Expedite	pencerl	From ApproveRack	To: Rep
10/11/2010 9...	Expedite	pencerl	From: Repair Bench	To: Gale
10/11/2010 11...	Expedite	perrettavc	From: Gallery	To: Final

☐ Shipping Hold
☐ Interface Hold
☒ Estimate Sent
☒ Parts Received
☐ Passed Inspection
☐ Return as Received
☒ Has Been Approved
☐ Internal Repair
☐ Exclude TATC

Current Status

Repairing

10/8/2010 5:00:06 PM

System

Final Inspect

Repair Location

ILN

Current Location

ILN

Transfer Number

Repair Search

Refresh

Close

supryll - ILN/Prod

frmRepairMain

D1102R7XPIL

Tuesday, Oct 12 2010

8:48 AM

start
Inbox - Microsoft
DMS - Desktop
frmRepairMain - FGI
DMS - Global Ser
AFMSEPV 2010
9:44 AM

27
20.23
20.—
67.23
37.—
30.23

RECEIVED
OCT 13 2010
BY:

PS 14827

4771
Lyndon Zuiderveen
8300 South Forward Rd.
McBain, MI 49657
231-590-4533
zuiderveenl@michigan.gov

Remington 30-06 Model 700 Serial No. A6885630

Bolt 5630

This gun will fire when you take the safety off. It has done it 2 times this last hunting season. I seen on your web site that there was a safety update that could be done on the rifle.

Please inspect and repair. Please call if you need anymore info.

Thank you.

A6885630

Model: 700



RE00205339

could not duplicate concern.
check over, replace TPA, clean +
test fire under bolt lock
program for \$20.00

Quote

22"
AA 3/8"
3.5"
011