Remington Arms Co., Inc. Product Service Legal Case #:5298

Case Information

RE# **Date Opened** Date Opened(PS) **Date Closed Incident Date** Pre Lit Lit Obsolete X 12/6/2010 12/6/2010 212382 12/3/2010

Customer Information

Type **Business** First Name Last Name Street City State Zip Age Contact 7686 Rte 53 14856 H 607-329-1430 **Perkins** Kanona NY. Incident Adrian

Incident Information

Claims Codes Repair Est. Medical Treatment Medical Status

PΙ

PD Cause:4006 Altered Adjustments or Components

Unknown

S Fired on safety release Concern: 1007 Fired on Safe Release

12/16/10 Per note with rifle, if you set the bolt pull the trigger with the safety on, remove your finger from the trigger and take safety off it will fire more times than not.cm

Firearm Information

Mfg. Remington

Type CF/BA

Model/Ga. 710/270 WIN

SKU 27408

Bbl. Serial

DOM

Date Purchased

Where Purchased

Accessories

71312792 PA

6/27/2006 4:30:41 AM

WAL-MART SUPERCENTER 3221

Original Owner

U

CONCERN:FSR

Ammunition Information - None Defined Other Products Information - None Defined Settlement

Remington/710/CF/BA

Release Date

Reimbursement

Cash Settlement

Reim. Date Cash Date APV APV

Per Ilion, replace trigger assm, clean at 1/2 normal cost

Settlement

Repair/Replacement

Release of Claims

Repair/Replacement Date

12/16/10 Per Ilion, Trigger assm set screws altered. Replace TPA, check over, clean and test fire at 1/2 normal cost.cm

Examination[Remington/CF/BA]

Part	Sub-Part	Code	Comment
Examination	Examiner		B.TRAVIS
	Exam Date		12/6/2010
	Product Type		RF
	Action Type		A
	Assigned To	<u> </u>	T.NAGLE
Cause	4006	Altered Adjustments or Components	
Barrel	Description		22" 270 WIN
	Date Code	•	PA
	Bore Plugged	False	
	Bulged	False	
	Fired	False	
	Fired while Obstructed		
	Muzzle/Crown Condition	Slightly Worn; Functioning	
	Firing Pin	Slightly Worn; Functioning	

		=14	
Bolt	Shroud	Slightly Worn; Functioning	
	Face	Slightly Worn; Functioning	
	Handle	Slightly Worn; Functioning	
	Stop	Slightly Worn; Functioning	
Extractor	Condition	Slightly Worn; Functioning	
	Cut Condition	Slightly Worn; Functioning	
	Ext/Eject Test	False	
Locking	Block Condition	Select	
	Lug Condition	Slightly Worn; Functioning	
	Notch Condition	Select	
	Condition	Select	
Magazine	Box Condition	Slightly Worn; Functioning	
	Exterior Condition	Slightly Worn; Functioning	
Overall	Stock Condition	Slightly Worn; Functioning	
	Fore End Condition	Select	
Receiver	Condition	Slightly Worn; Functioning	
	Bulged	False	
Safety	Description		STANDARD M/710 SAFETY
	Function	Like new; Functioning	
	Sub-Assembly	Non-ISS	
Sear	Lift	Select	
	Notch	Like new; Functioning	
		Condition	Slightly Worn; Functioning
Pull		Select	2.2#
Altered	Trigger	True	SET SCREWS ALTERED
Sub-Assembly		Other Remington	

10m NAGLE

4-5 710 6 AS BAD A Sout 5 rounds Fired throught it

- you set the B.Lf to egg. golf SAFEON, Penoue y F. Wyer From Trigger AND to KE SAFETY OFF IT WITH more tomes than not

ESTIONS CALL.

607-329-1430

閏71312792



T.A. set sciews Altered. Rephase TPA, check over, cleant Test fine AT 1/2 Nonwal cost.

Quote





