

Remington Arms Co., Inc.
Product Service
Legal Case #:5420

Case Information

RE#	Date Opened	Date Opened(PS)	Date Closed	Incident Date	Pre Lit	Lit	Obsolete
214103	12/10/2010	12/14/2010	12/14/2010				

Customer Information

Type	Business	First Name	Last Name	Street	City	State	Zip	Age	Contact
Reporter	Appleton Scheels	---	Appleton Scheel	4301 W. Wisconsin Ave	Appleton	WI	54913		W 920-830-2977
Incident		Josh	Arndt	838 Emily St.	Menasha	WI	54952		H 920-725-4540

Incident Information

Claims	Codes	Repair Est.	Medical Treatment	Medical Status
PI				
PD	Cause:4038 Could Not Duplicate Concern		Unknown	
S	Concern:1007 Fired on Safe Release			
C FSR				

Dealer sent gun in for consumer. Consumer stated gun will fire when put in fire position. df

Firearm Information

Mfg.	Type	Model/Ga.	SKU	Serial	Bbl.	DOM
Remington	CF/BA	700/7MM08 REM	84151	G6941066	LE	2/3/2010 8:23:19 AM
Date Purchased	Where Purchased	Accessories	Original Owner			
	ACUSPORT (OH) CORPORATION	SCOPE,RINGS,TWO PIECE BASE	U			

CONCERN:FIRES WHEN PUT IN FIRE POSITION

Ammunition Information - None Defined

Other Products Information - None Defined

Settlement

Settlement	Release of Claims	Release Date	Reimbursement	Cash Settlement	Reim. Date APV	Cash Date APV
Per Ilion - check over & test fire @ n/c						
	Repair/Replacement Cost	Repair/Replacement Date				
	\$42	1/5/2011				

Per Ilion - Red powder residue on action. Check over at bench, TA is functioning as designed. Will clean, safety inspect & test fire @ n/c - warranty. df

Examination[Remington/CF/BA]

Part	Sub-Part	Code	Comment
Examination	Examiner		B.TRAVIS
	Exam Date		12/14/2010
	Product Type		RF
	Action Type		A
	Assigned To		T.NAGLE
Cause	4038	Could Not Duplicate Concern	
Barrel	Description		20" 7MM08 REM
	Date Code		LE
	Bore Plugged	False	
	Bulged	False	

	Fired	False	
	Fired while Obstructed		
	Muzzle/Crown Condition	Slightly Worn; Functioning	
Bolt	Firing Pin	Like new; Functioning	
	Shroud	Like new; Functioning	
	Face	Like new; Functioning	
	Handle	Like new; Functioning	
	Stop	Like new; Functioning	
Extractor	Condition	Slightly Worn; Functioning	
	Cut Condition	Slightly Worn; Functioning	
	Ext/Eject Test	False	
Locking	Block Condition	---Select---	
	Lug Condition	Slightly Worn; Functioning	
	Notch Condition	---Select---	
Overall	Exterior Condition	Like new; Functioning	RED POWDER RESIDUE ON/IN ACTION
	Stock Condition	Like new; Functioning	
	Fore End Condition	---Select---	
Receiver	Condition	Like new; Functioning	
	Bulged	False	
Safety	Description		STANDARD XMP SAFETY
	Function	Like new; Functioning	
	Sub-Assembly	Non-ISS	
Sear	Lift	---Select---	N/A
	Notch	Like new; Functioning	
	Tests	Test Fired	False
Feeding Test		False	
Trigger	Condition	Like new; Functioning	
	Pull	---Select---	3#
	Altered	False	
	Sub-Assembly	X-Mark Pro	
Non-Remington Components	Description		SCOPE,RINGS,TWO PIECE BASE

frmRepairMain - FGI Repairs

frmREInquiry - Repair Inquiry

ADDRESS INFORMATION

FFL:

- ☐ Shipping Hold
- ☐ Interface Hold
- ☐ Estimate Sent
- ☐ Parts Received
- ☐ Passed Inspection
- ☐ Return as Received
- ☐ Has Been Approved
- ☐ Internal Repair
- ☐ Exclude TATC

Current Status

New
12/12/2010 6:18:27AM
lopatafl
Repair Bench
Repair Location
ILN
Current Location
ILN
Transfer Number

Close

10:33 AM

RECEIVED
DEC 17 2010

BY:

F

**REPAIR
TAG**

014649

APPLETON SCHEELS

Fox River Mall
4301 West Wisconsin Ave
Appleton, WI 54913
920.830.2977

5420

2011
LEZ/10
34

CUSTOMER <u>JOSH ARUNT</u>		INVOICE NO. F <u>014649</u>	
ADDRESS <u>838 Emily St. Menasha WI 54952</u>		DATE RECEIVED <u>12-3-10</u>	
MODEL OR SERIAL NO. <u>G6941066</u>	PHONE <u>(920) 725-4540</u>	DATE RECEIVED	
TROUBLE REPORTED <u>Fires when put in fire position</u>		PROMISED	DELIVERED
<u>Rem. 700LT 7mm-08</u>			
DESCRIPTION OF MATERIAL USED		AMOUNT	
<u>Customer Requests description of repairs done</u>			
<u>Insurance Co. : \$750.00</u>		#109	
<u>W/Scope</u>	TOTAL MATERIALS		
RECEIVED BY <u>K. Gibson</u>	LABOR		
	TAX		
Thank You! CASH	ON COMPLETION OF WORK →	TOTAL	

Serial Number:

G6941066

Model: **700**



RE00214103

Red powder residue on action.

check over at bench, T.A.
is functioning as designed.
will clean, safety inspect + test
fire at 1X/c

Warranty







