Remington Arms Co., Inc. Product Service Legal Case #:5337

Case Information

RE# **Date Opened** Date Opened(PS) **Date Closed Incident Date** Pre Lit Lit Obsolete 12/8/2010 12/7/2010 12/8/2010 212984

Customer Information

Type **Business** First Name Last Name Street City State Zip Age Contact 605 S Wichita St Reporter Gander Mt. Gander Mt. Wichita KS 67202 W 316-303-9333

Incident Information

Claims Codes Repair Est. **Medical Treatment Medical Status**

ΡI

PD Cause:4038 Could Not Duplicate Concern

Unknown

S Fired on safe release Concern:1007 Fired on Safe Release

12/19/10 Per letter with rifle, customer stated that he fired the rifle four times and on the fifth shot it fired when he let the safety off.cm

Firearm Information

Model/Ga. SKU Mfg. Type Serial Bbl. **DOM** 6/29/2010 5:35:33 G6981781 PE CF/BA 700/243 WIN 27093 Remington

Date Where Purchased Accessories Purchased

Original

AM

GANDER WAREHOUSE

SCOPE, RINGS, TWO PIECE

Owner

#1/Leban

BASE

U

CONCERN:FSR

Ammunition Information - None Defined Other Products Information - None Defined

Settlement

Remington/700/CF/BA

Cash Reim. Date Cash Date Release Date Settlement Release of Claims Reimbursement Settlement APV APV

Per Ilion, check over, clean and test fire at no charge

> Repair/Replacement Repair/Replacement Cost Date 42.00 12/19/2010

12/19/10 Per Ilion, could not duplicate concern. Trigger assm functioning as designed. Check over, clean and test fire at no charge.cm

Examination[Remington/CF/BA]

Part	Sub-Part	Code	Comment	
Examination	Examiner		B.TRAVIS	$\overline{}$
	Exam Date		12/8/2010	
	Product Type		RF	\neg
	Action Type		A	
	Assigned To		T.NAGLE	
Cause	4038	Could Not Duplicate Concern		
Barrel	Description		24" 243 WIN	
	Date Code		PE	\equiv
	Bore Plugged	False		
	Bulged	False		
	Fired	False		

ų mujusp	iay		1 450 2 01
	Fired while Obstructed		_
	Muzzle/Crown Condition	Slightly Worn; Functioning	
Bolt	Firing Pin	Slightly Worn; Functioning	
	Shroud	Slightly Worn; Functioning	
	Face	Slightly Worn; Functioning	
	Handle	Slightly Worn; Functioning	
	Stop	Slightly Worn; Functioning	
Extractor	Condition	Slightly Worn; Functioning	
	Cut Condition	Slightly Worn; Functioning	
	Ext/Eject Test	False	
Locking	Block Condition	Select	
	Lug Condition	Slightly Worn; Functioning	
	Notch Condition	Select	<u></u>
Overall	Exterior Condition	Slightly Worn; Functioning	
	Stock Condition	Slightly Worn; Functioning	
	Fore End Condition	Select	
Receiver	Condition	Slightly Worn; Functioning	
	Bulged	False	
	Description		STANDARD XMP SAFETY
Safety	Function	Like new; Functioning	
	Sub-Assembly	Non-ISS	
Sear	Lift	Select	N/A
	Notch	Like new; Functioning	
		Test Fired	False
Feeding Test	Tests	False	
	Condition	Slightly Worn; Functioning	
	Pull	Select	3#
Trigger	Altered	True	SEALANT REMOVED AND SET SCREW TURNED OUT BEYOND MAX SETTING ALLOWED
	Sub-Assembly	X-Mark Pro	
			-



Service Request Service Order # 3654

SHIPPED TO VENDOR/STORE:

Remington Repair FFL# 6-16-00726 14 Hoefler Ave

Ilion, NY 13357 Attn: Repairs

Date Shipped: 11/29/2010

Phone: (800) 243-9700

RETURN SHIP TO:

Gander Mountain, FFL# 4-58-173-01-8b-01121

Attn: Gun Parts Dept. 605 South Wichita Street Wichita, KS 67202

FIREARM INFORMATION:

Manufacturer: Remington Arms Co Inc.

Type: Rifle Serial Number: G6981781

Model:

700

Cal/Ga.: .243cal

Cased?:

DESCRIPTION OF ITEM RETURNED:

700 serial no. G6981781 .243

Original fox

REASON FOR RETURN:

customer stated that he fired the rifle four times and on the fifth shot it fired when he let the safety off. Please repair and return.

ATTENTION VENDOR

Please contact me with any questions or concerns.

Steve Weems (316) 303-9333

BILLING INFORMATION:

Please include the service order number on all invoices and correspondence:

SHIP TO ABOVE ADDRESS

Forward all invoices to:

Gander Mountain

Attn: Cindy Kilbride 180 East Fifith Street St. Paul, Mn. 55101

G6981781



could not duplicate concenti T.A. functioning As Dosigned. check over, clean + Test Rive AT N/4 warmy

Ē			pair Exp	edite Rep	air Inquiry	Repair Tools	CSR Tools	Reports	Table Maintena	ince System	Location	
- 2	frmRE	Inquiry :	Repair Inc	quiry		in the state of th	and the second	en salas en				
ुर: र:	Repair N			Sei	al (G6981781*)	Model 700 Center	ire Calher	Repairman	TO THE TO SERVE THE THE SERVE THE THE SERVE TH	CAPTURE TO THE SECOND SECONDARY OF THE S	en same	
		Design Spirit	E0021298			06/29/2010 SKU: 2			The second second			
	Verily F	SS INFOR	44100					Status	Hepairing 12/8/2	2010 11 18 19 AM /		
	****	es early takes	istomer			• Received from	Return To			Received from		
13	Name		NDER MOUI	NTAIN	ec-mentality commission	A SECTION AND CONTRACTOR	AND THE STATE OF THE PERSON OF	MOUNTAIN	ESCHOLOGICA DE LA COMPANION DE	A. A. S. Land Brand Bran		
が	bbAi.	ess 1 A1	TN CINDY K	ILBRIDE	The State of the S		605 SOUT	H WICHITA ST	m 2			
A A	Add	5-1-25-31-	OE 5TH ST S	UITE 1300	PO Box			<u> </u>	PO Box			
		137.35	INT PAUL	(EE101	Country	Tur S	WICHITA KS Zi	Code 6720	2 Country	luc (Silver)		
	6 9.3	State (MI	V ZID COO	e 55101	Lountry:	ajus	// ZI	Loge: 16/20	Country &	Jus ,	<u> </u>	
						over FE		estato de la como	reference of the first			
	Contact	/ Condition	Problems	Estimate:	History / Status	Shipping / Billing						
	Date	3557470	Code	UserID	Desc1		Desc2	Shipping Holo		irrent Status		
	200	/2010 5:2:		lopatafi	Repair Ad		1880	Interface Holo	12/8/	2010 11:18:19 AM		
	12/7	/2010 5:2	Expedite	iopatafi	From: Che	eck In	12,556	Estimate Sent Parts Receive	Control of the Contro	V lopatafl Répair Bench		
	極"	/2010 5.2		lopatafi			STARIS NEW 1/888	Passed Inspe	Re	pair Location		
	12/8	/2010 11:	Maint	Travisby	v Repair M	aintenance	Ct-to- Day 1 days	Return as Re	经总统中兰手等设备	ILN (///)		
	er in	were appearance	11 (500) (50) (10) (50			es de consessant de	200 10	Has Been Ap	A PROPERTY ASSESSMENT OF THE PARTY OF THE PA	ILN		
		38 (1994)	er som særer Ny varantis			The same of the sa		Internal Repa Exclude TATI	14 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	The state of the s		
3	en on ar	Total T	TO AUG	TANK	**************************************				an decima		nia ir i	,
	Rep	air Sean	ch in the	4.50					A Carlo	resh 🔌 🛴 🤇	lose	
-3,2	id Moral Page	i contractions are	4								(Zali Bezazion)	
					777	E-size		100				
				A Section			* * ***			•		
						A CANAL SERVICE SERVICE		W 1				
letj - ILN/Pro												









